

ATTN Luke sweet ICN: ET1246

Estimate

SO-1828

9/6/2023

Service Order		Purchase Order	Authorizer		
SO-1828			Tim Armstrong		
Item	Description		Quantity	Rate	Amount
Complaint: OVERHUAL ENGINE					
Cause: Customer request					
Labor	Correction: Chassis / Chassis / OVERHUAL ENGINE		45.00000	\$100.00	\$4,500.00
Parts	PLATE SPACER - 6I4421:CT - A		1		\$674.27
Parts	SLEEVE-BUSHING - 1304698 - A		1		\$55.87
Parts	KIT ENG OVER - 10R9923:CT - A		1		\$7,052.40
Parts	HARNESS AS - 2639001:CT - A		1		\$964.59
Parts	HARNESS INJ - 3214324 - A		1		\$219.46
Parts	HARNESS INJ - 3214323 - A		1		\$276.88
Parts	REGULATOR - 2485513 - A		2		\$175.66
Parts	PAINT-YELLOW - 5900196 - A		3		\$57.71
Parts	PRIMER YELLOW - 4589582 - A		3		\$53.51
Parts	ENG PAING BLACK - DE1613 - A		1		\$17.49
Parts	HOSE-PRECOOLER - 2470266 - A		1		\$75.88
Parts	TUBE AS-OIL - 2764637:CT - A		6		\$975.00
Parts	DOWEL - 4N1650 - A		1		\$11.18
Parts	DOWEL - 6I1055 - A		1		\$12.23
Parts	SEAL AS - 3805855:CT - A		2		\$233.79
Parts	PLUG - 1656170 - A		3		\$48.98
Parts	COOLANT HOSE - 2470055 - A		1		\$84.36
Parts	INSERT .0632 - 2W3815 - A		6		\$715.26
Parts	PULLEY - 1979641 - A		1		\$105.56
Parts	PULLEY 8 GRV - 1979642 - A		1		\$263.90
Parts	JOIN-EXPANSION - 2276721 - A		1		\$446.46
Parts	LOCK NUT - 2N2766 - A		20		\$300.72
Parts	BOLT 12PT - 1241855:CT - A		16		\$430.30
Parts	BOLT 12 PT - 1241854:CT - A		10		\$295.96
Parts	CAMSHAFT-REMAN - 10R3323 - A		1		\$1,507.00
Parts	GASKET MAKER - 51813 - A		1		\$19.59
Parts	2 3/4-3 5/8 Clamp - 50904 - A		2		\$64.57
Parts	SPIN ON FUEL/WATER SEPERATOR - P551000 - A		1		\$36.17

Item	Description	Quantity	Rate	Amount
Parts	P66 MEGAFLOW HYDRAULIC OIL - PHAW32_55 - A	1		\$20.61
Parts	P66 GUARDOL ECT 15W40 BULK OIL - PHG1540_B - A	10		\$153.30
Parts	AF 50/50 ELC RED ANTIFREEZE - AF5050EXT_55 - A	11		\$146.30
Parts	TUBE AS - 1723450 - A	1		\$109.07
Parts	BOLT - 9L8925 - A	1		\$0.69
Parts	BOLT - 1221472 - A	1		\$0.72
Parts	HOSE 3" - C40-300X36 - A	2		\$59.22
Parts	FRAME CROSSTIE - 01-46365 - A	1		\$770.50
Parts	HEATER HOSE - 5526-062X400 - A	15		\$149.70
Parts	HEATER HOSE 1" - 80-100 - A	5		\$61.86
Parts	1/4" SILICONE HEATER HOSE - HH-025X25 - A	2		\$7.60
Parts	PROTECT O GLADHAND SEAL - 113 10024P - A	2		\$3.18
Subtotal				\$21,157.50

Complaint: REPLACE RH HORN COVER

Cause: Customer request

Labor	Correction: Chassis / Chassis / REPLACE RH HORN COVER, CUSTOMER PROVIDED PARTS	0.30000		\$30.00
Subtotal				\$30.00

Complaint: REPLACE TRANSMISSION OIL COOLER

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Chassis / REPLACE TRANSMISSION OIL COOLER	1.50000		\$150.00
Parts	COOLER-TRANS OIL - 019772X - A	1		\$661.25
Parts	BLOCK - MOUNTING - 002094 - A	2		\$31.47
Parts	37" JIC F SWIVEL - KTFJX-08-10 - A	4		\$50.56
Parts	#8 HOSE R2S 4000 PSI-SAE - KTR2S-08 - A	19		\$112.38
Subtotal				\$1,005.66

Complaint: REPLACE HOOD PIVOT BUSHINGS AND LOWER BRACKETS

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Chassis / REPLACE HOOD PIVOT BUSHINGS AND LOWER BRACKETS	2.00000		\$200.00
Parts	PB LOWER HOOD PIVOT LH - 1304708LRT - A	1		\$206.25
Parts	PB LOWER HOOD PIVOT RH - 1304708RRT - A	1		\$243.75
Parts	HOOD MOUNT KIT - HM75-66165 - A	2		\$127.14
Parts	KIT - HOOD PIVOT - M134709K - A	1		\$143.00
Subtotal				\$920.14

Complaint: ANNUAL DOT INSPECTION

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Chassis / ANNUAL DOT INSPECTION	0.85000		\$85.00
Subtotal				\$85.00

Complaint: REPLACE LH & RH SPOT MIRRORS

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Chassis / REPLACE LH & RH SPOT MIRRORS	0.30000		\$30.00
-------	--	---------	--	---------

Item	Description	Quantity	Rate	Amount
Parts	8 1/2 SS CONVEX - 6400301001 - A	2		\$55.27
			Subtotal	\$85.27

Complaint: REPLACE A/C LINE COMP TO EVAP

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Chassis / REPLACE A/C LINE COMP TO EVAP	1.00000		\$100.00
Parts	A/C LINE COMP TO EVAP 64" - D9026-5860 - A	1		\$588.00
Parts	FREON 134A - R134A30LB - A	5		\$87.50
				\$775.50
	HBC - HOSE BUILD CHARGE	1.00		\$85.00
	Shop Supplies			\$150.00

Unit: 2883 VIN: 1XP5DB9X67D662883
 2007 Peterbilt 379
 Chassis: 101,752 Miles

Labor	
Parts	
HBC - HOSE BUILD CHARGE	
Subtotal	
Local (8.25% of \$19,199.07)	
Total	\$25,877.99

Customer Signature: _____

Printed Name: _____ Date: _____

Service Order		Purchase Order	Authorizer		
SO-1967			Tim Armstrong		
Item	Description		Quantity	Rate	Amount
Complaint: REPLACE CARRIER AXLE 3					
Cause: Customer request					
Labor	Correction: Chassis / Chassis / REPLACE CARRIER AXLE 3		3.00000		\$300.00
Parts	RIGHT STUFF GASKET MAKER - 85224 - A		1		\$44.99
Parts	AXLE FLANGE GASKET - 499 AG0106 - A		2		\$8.23
Parts	HD SYN GEAR OIL 75W90 5GAL - 888176 - A		4		\$205.00
Parts	CARRIER-REMAN RSP40 336 - RSP40336WEL - A		1		\$1,922.40
					\$2,480.62
Complaint: REMOVE OLD STICKERS AND BADGING					
Cause: Customer request (Inspection)					
Labor	Correction: Chassis / Chassis / REMOVE OLD STICKERS AND BADGING, CLEANED UP AND MADE READY FOR NEW STICKERS AND BADGING.		1.20000		\$120.00
					\$120.00
Complaint: REPLACE FIRE EXTINGUISHER					
Cause: Customer request (Inspection)					
Labor	Correction: Chassis / Chassis / REPLACE FIRE EXTINGUISHER		0.00000		\$0.00
Parts	EXTINGUISHER 5LB - KFE 21026915 - A		1		\$54.21
					\$54.21
Complaint: REPLACE TURN SIGNAL LIGHTS					
Cause: Customer request (Inspection)					
Labor	Correction: Chassis / Chassis / REPLACE TURN SIGNAL LIGHTS		0.50000		\$50.00
Parts	PETE TURN SIG LED 379 - 222014Y - A		2		\$110.00
					\$160.00
Complaint: REPLACE BATTERIES					
Cause: Customer request (Inspection)					
Labor	Correction: Chassis / Chassis / REPLACE BATTERIES		0.80000		\$80.00
Parts	BATTERY-HD GRP 31 TERM EXC STUD 950CCA - BT31S91EXCH:TRB - A		4		\$690.00

Item	Description	Quantity	Rate	Amount
			Subtotal	\$770.00
Complaint: REPLACED ECM AND PROGRAMED, CUSTOMER SUPPLIED PARTS				
Cause: Customer request (inspection)				
Labor	Correction: Chassis / Chassis / REPLACED ECM AND PROGRAMED, CUSTOMER SUPPLIED PARTS	0.80000		\$80.00
				\$80.00
	REMOVER - ISOP/ALC	1.00		\$6.00
	Shop Supplies			\$146.83

Unit: 2883 VIN: 1XP5DB9X67D662883
 2007 Peterbilt 379
 Chassis: 113,269 Miles

Labor
 Parts
 REMOVER - ISOP/ALC
 Subtotal
 Local (8.25% of \$3,187.66)
 Total \$4,080.64

Customer Signature: _____

Printed Name: _____ Date: _____

Service Order		Purchase Order		Authorizer	
SO-3528					
Item	Description	Quantity	Rate	Amount	
Complaint: CHECK FOR BUILDING PRESSURE IN COOLANT.					
Cause: Customer request					
Labor	Correction: Engine / Valves / TROUBLESHOT SYSTEM AND FOUND BAD HEAD GASKET WITH ISSUES OF OVERHEATING SENT HEAD OFF TO GET MAGNAFLUXED TO MAKE SURE NO ISSUES WERE FOUND AND ALSO FOUND HEAD SURFACE WASNT STRAIGHT. CLEANED ALL AREAS AND CHECKED AREAS FOR ANY OTHER ISSUES ALL IS WITHIN SPECS AND NO OTHER ISSUES FOUND. REINSTALLED NEW GASKETS PLATE SEALS ETC AND REINSTALLED HEAD AND TORQUED TO SPECS AND ACCESSORIES. AFTER INSTALL CHANGED OIL AND FILTER AND FILLED WITH NEW COOLANT. RAN OVERHEAD TO SPEC AND FINISHED INSTALL. RAN TRUCK TO CHECK OVER AND TEST DROVE TWICE AFTER CHECKING FOR LEAKS TO CHECK OPERATION. RAN GOOD AND FOUND NO OTHER ISSUES WITH UNIT AT TIME.	30.00000		\$3,450.00	
Parts	GASKET KIT - 5927313 - A	1		\$1,307.67	
Parts	SREW-HEAD - 2971813 - A	12		\$68.25	
Parts	BOLT 12 PT - 1241854:CT - A	16		\$473.54	
Parts	BOLT 12PT - 1241855:CT - A	10		\$272.30	
Parts	GASKET KIT - 2481394 - A	6		\$216.75	
Parts	STUD - 8T7062 - A	1		\$19.96	
Parts	AF 50/50 ELC RED ANTIFREEZE - AF5050EXT_55 - A	12		\$204.50	
Parts	P66 GUARDOL ECT 15W40 BULK OIL - PHG1540_B - A	10		\$159.80	
Parts	Oil Filter - LFP4005 - A	1		\$34.30	
Parts	CAP-INJECTOR - 7E6508 - A	6		\$80.64	
Parts	GASKET MAKER - 51813 - A	1		\$33.40	
				\$6,321.11	
Complaint: REPLACE SPLIT A/C LINE					
Cause: SPLITTING AT CRIMP ON HOSE. (Inspection)					
Labor	Correction: A/C Cooling System / Hoses / REPLACED HOSE AND VACUUMED SYSTEM. HELD VACUUM FOR 15 MINUTES AND CHARGED SYSTEM BACK UP AND TESTED.	1.50000		\$172.50	
Parts	HOSE ASSY - 775-1404 - A	1		\$300.00	
Parts	FREON 134A - R134A30LB - A	3.5		\$52.50	
				Subtotal \$525.00	
Complaint: Bolt extraction					
Cause: BOLTS BROKE IN AREAS HAD TO GET EXTRACTED AND CLEANED TO USE. (Inspection)					

Item	Description	Quantity	Rate	Amount
Labor	Correction: Engine / Overhaul / HAD TO REMOVE BROKEN BOLTS FROM VARIOUS AREAS TO RECOVER THREADS AND REPAIR. DRILLED AND REMOVED SOME AND RECUT THREADS TO REUSE.	3.50000	\$115.00	\$402.50
			Subtotal	\$402.50

Complaint: INSPECT HEAD.

Cause: Customer request (Inspection)

Labor	Correction: Engine / Valves /	0.00000		\$0.00
Labor	SURFACE AND TEST HEAD	1	\$410.2125	\$410.21
			Subtotal	\$410.21

Complaint: Decommission truck

Cause: Customer request (Inspection)

Labor	Correction: Chassis / Cab / DECOMMISSION TRUCK PULLED DECALS, PULLED CAMERA AND ELD, TOOK LIC PLATE OFF AND CLEANED INTERIOR.	1.50000	\$115.00	\$172.50
			Subtotal	\$172.50

Shop Supplies

\$150.00

Unit: 2883 VIN: 1XP5DB9X67D662883
2007 Peterbilt 379
Chassis: 223,017 Miles

Labor	\$4,607.71
Parts	\$3,223.61
Subtotal	\$7,981.32
Local (8.25% of \$3,373.61)	\$278.32
Total	\$8,259.64

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ Date: _____