

# Invoice

**Invoice Number:** 037243  
**Invoice Date:** 04-Jun-2025  
**Due Date:** 04-Jul-2025  
**SalesPerson:** KW  
**Customer Number:** C00288  
**Equipment VIN:** 2NP3HJ8XXHM444605  
**Equipment S/N:** 01177737

6411

| Customer P.O. NO. | Terms       | Contact |
|-------------------|-------------|---------|
| 2NP3HJ8XXHM444605 | Net 30 Days |         |

| SO Type | SO Number | Shipment Number | Appointment NO. | Ship Via |
|---------|-----------|-----------------|-----------------|----------|
| IN      | 037242    | <NEW>           | FS000016940-1   |          |

| Item Number    | Unit | Ordered | Warehouse | Unit Price | Amount   |
|----------------|------|---------|-----------|------------|----------|
| BAY SHOP LABOR | HR   | 22.50   | 003       |            | 4,297.50 |

3-STAGE FAN REPLACEMENT

**NOTE:** Complaint: 3-stage fan damaged .

Cause: Normal wear and tare on fan .

Correction: Staged truck inside shop . Remove complete fan with silencer . Prep and install new 3-staged fan with new silencer . Start and test fan for proper operation . At this time 3-staged fan replacement job is all completed .

|                               |    |      |     |  |        |
|-------------------------------|----|------|-----|--|--------|
| BAY SHOP LABOR                | HR | 4.00 | 003 |  | 764.00 |
| VACCON INSPECTION AND SERVICE |    |      |     |  |        |

**NOTE:** Complaint: Customer requested a complete vaccon inspection .

Cause: Inspection due at this time .

Received By \_\_\_\_\_ Date \_\_\_\_\_

Material returns require a Return Authorization Number, a copy of this invoice and parts must be returned within 30 days of R.M.A. Issuance to receive credit. A re-stocking fee may apply.

R.M.A.# \_\_\_\_\_  
 Date \_\_\_\_\_

**Tax Total:** 5,598.97

**Invoice Total (USD):** 73,607.55

Continued...

Page: 1 of 4

| Customer P.O. NO. |           | Terms           | Contact         |            |        |
|-------------------|-----------|-----------------|-----------------|------------|--------|
| 2NP3HJ8XXHM444605 |           | Net 30 Days     |                 |            |        |
| SO Type           | SO Number | Shipment Number | Appointment NO. | Ship Via   |        |
| IN                | 037242    | <NEW>           | FS000016940-1   |            |        |
| Item Number       | Unit      | Ordered         | Warehouse       | Unit Price | Amount |

Correction: Staged truck outside . Performed complete water , vacuum and complete visual inspection . All repairs needed have been documented at this time .

|                                               |    |       |     |  |          |
|-----------------------------------------------|----|-------|-----|--|----------|
| V-624-0258                                    | EA | 1.00  | 003 |  | 55.02    |
| FLANGE MOUNT PRESSURE GAUGE 0-3000, REAR      |    |       |     |  |          |
| PORT NPT                                      |    |       |     |  |          |
| V-624-0259                                    | EA | 1.00  | 003 |  | 47.08    |
| FLANGE MOUNT PRESSURE GAUGE 0-10000, REAR     |    |       |     |  |          |
| PORT NPT                                      |    |       |     |  |          |
| V-622-0715                                    | EA | 1.00  | 003 |  | 281.35   |
| SHAFT SEAL FOR V-622-0639                     |    |       |     |  |          |
| V-624-0468                                    | EA | 1.00  | 003 |  | 439.34   |
| FILTER FOR LINDE 165CC PUMP 622-0639          |    |       |     |  |          |
| V-622-0581                                    | EA | 1.00  | 003 |  | 281.57   |
| FILTER, HYDRO, EATON PUMP 104508-007 SF-7420- |    |       |     |  |          |
| MG SF-7421-MG                                 |    |       |     |  |          |
| V-624-0272                                    | EA | 1.00  | 003 |  | 223.13   |
| FILTER ELEMENT 5 MICRON 01268256 0075 D 005   |    |       |     |  |          |
| BN4HC 2203722 0075 D 010 MM                   |    |       |     |  |          |
| V-624-0261                                    | EA | 1.00  | 003 |  | 116.64   |
| FILTER ELEMENT - 10 MICRON*, REPLACES V-624-  |    |       |     |  |          |
| 0247                                          |    |       |     |  |          |
| V-633-0965                                    | EA | 1.00  | 003 |  | 210.86   |
| TACHOMETER                                    |    |       |     |  |          |
| V-624-0276                                    | EA | 1.00  | 003 |  | 45.69    |
| WATER PRESS GAUGE BACK FEED, 0-4000 PSI       |    |       |     |  |          |
| V-680-0001                                    | EA | 12.00 | 003 |  | 871.80   |
| 8" KANAFLEX 180AR                             |    |       |     |  |          |
| V-680-0016                                    | EA | 4.00  | 003 |  | 110.52   |
| 8" KANAFLEX POWERLOCK CLAMP                   |    |       |     |  |          |
| V-711-3526                                    | EA | 1.00  | 003 |  | 1,025.84 |
| HYDROPUMP SHEAVE PKG                          |    |       |     |  |          |
| V-711-55606                                   | EA | 1.00  | 003 |  | 70.38    |
| DRIVELINE INSTALLATION RETROFIT               |    |       |     |  |          |
| V-800-9534                                    | EA | 1.00  | 003 |  | 1,535.19 |
| INLET TUBE WELDMENT                           |    |       |     |  |          |
| V-810-25351                                   | EA | 1.00  | 003 |  | 55.49    |
| SEAL, 10"                                     |    |       |     |  |          |
| V-810-25350                                   | EA | 1.00  | 003 |  | 32.75    |
| O-RING, 10"                                   |    |       |     |  |          |

Received By \_\_\_\_\_ Date \_\_\_\_\_

Material returns require a Return Authorization Number, a copy of this invoice and parts must be returned within 30 days of R.M.A. issuance to receive credit. A re-stocking fee may apply.

R.M.A.# \_\_\_\_\_

Date \_\_\_\_\_

**Tax Total:** 5,598.97

**Invoice Total (USD):** 73,607.55

Continued...

Page: 2 of 4

|                   |           |                 |                 |          |
|-------------------|-----------|-----------------|-----------------|----------|
| Customer P.O. NO. |           | Terms           | Contact         |          |
| 2NP3HJ8XXHM444605 |           | Net 30 Days     |                 |          |
| SO Type           | SO Number | Shipment Number | Appointment NO. | Ship Via |
| IN                | 037242    | <NEW>           | FS000016940-1   |          |

| Item Number    | Unit | Ordered | Warehouse | Unit Price | Amount   |
|----------------|------|---------|-----------|------------|----------|
| BAY SHOP LABOR | HR   | 6.00    | 003       |            | 1,146.00 |

Drive line service for front pump

**NOTE:** Complaint: Customer requested service on front drive line .

Cause: One year interval due at this time .

Correction: Staged truck inside shop . Install new service drive line with new bushing and pulley retrofit kit . Start and test drive line for leaks and vibrations . Drive line service job is all completed at this time .

|                |    |      |     |  |        |
|----------------|----|------|-----|--|--------|
| BAY SHOP LABOR | HR | 2.00 | 003 |  | 382.00 |
|----------------|----|------|-----|--|--------|

All vacuum gauges inop

**NOTE:** Complaint: Found damaged and worn out vacuum gauges .

Cause: Normal wear .

Correction: Staged truck inside shop . Remove pressure and RPM gauge . Install all new vacuum gauges . Start and test for leaks and for proper gauge operation . At this time vacuum worn out gauge job is all completed .

|                |    |      |     |  |        |
|----------------|----|------|-----|--|--------|
| BAY SHOP LABOR | HR | 3.00 | 003 |  | 573.00 |
|----------------|----|------|-----|--|--------|

Hydraulic service

|             |    |      |     |  |          |
|-------------|----|------|-----|--|----------|
| V-711-25604 | EA | 1.00 | 003 |  | 7,954.57 |
|-------------|----|------|-----|--|----------|

OUTLET SILENCER ASSY, SS

|             |    |      |     |  |           |
|-------------|----|------|-----|--|-----------|
| V-711-14522 | EA | 1.00 | 003 |  | 42,744.52 |
|-------------|----|------|-----|--|-----------|

3 STAGE FAN ASSEMBLY, HYD

|                |    |      |     |  |        |
|----------------|----|------|-----|--|--------|
| BAY SHOP LABOR | HR | 3.00 | 003 |  | 573.00 |
|----------------|----|------|-----|--|--------|

Leaking boom seals

**NOTE:** Complaint: Boom seals leaking .

Cause: Worn out seals .

Correction: Staged truck inside shop . Remove leaking boom seals . Install and lube new boom seals . At this time leaking boom job is all completed .

Received By \_\_\_\_\_ Date \_\_\_\_\_

**Tax Total:** 5,598.97

Material returns require a Return Authorization Number, a copy of this invoice and parts must be returned within 30 days of R.M.A. issuance to receive credit. A re-stocking fee may apply.

R.M.A.# \_\_\_\_\_

Date \_\_\_\_\_

**Invoice Total (USD):** 73,607.55

Continued...

Page: 3 of 4

| Customer P.O. NO. |           | Terms           | Contact         |          |
|-------------------|-----------|-----------------|-----------------|----------|
| 2NP3HJ8XXHM444605 |           | Net 30 Days     |                 |          |
| SO Type           | SO Number | Shipment Number | Appointment NO. | Ship Via |
| IN                | 037242    | <NEW>           | FS000016940-1   |          |

| Item Number                               | Unit | Ordered | Warehouse | Unit Price | Amount   |
|-------------------------------------------|------|---------|-----------|------------|----------|
| MSC-PART-NSTK<br>DRIVELINE SERVICE CC     | EA   | 1.00    | 003       |            | 273.17   |
| FREIGHT<br>4096030690 EFW                 | EA   | 1.00    | 001       |            | 574.40   |
| BAY SHOP LABOR<br>Tank Inlet-tube damaged | HR   | 6.00    | 003       |            | 1,146.00 |

**NOTE:** Complaint: Inlet tube inside tank is damaged .

Cause: Normal wear .

Correction: Staged truck inside shop . Remove damaged inlet tube . Install new inlet tube with all new hardware . Damaged inlet tube job is all completed at this time .

|                                                                       |    |      |     |  |        |
|-----------------------------------------------------------------------|----|------|-----|--|--------|
| MSC-PART-NSTK<br>FITTINGS SI5478HY                                    | EA | 1.00 | 003 |  | 8.59   |
| BAY SHOP LABOR<br>Swing plate inside tank has worn out mounting bolts | HR | 3.00 | 003 |  | 573.00 |

**NOTE:** Complaint: Swing plate inside tank has damaged mounting bolts .

Cause: Normal wear .

Correction: Open rear tank door and cut damaged swing door mounting bolts . Install new swing door mounting bolts . Swing plate damaged mounting bolt job is all completed .

|                                                                |    |      |     |  |        |
|----------------------------------------------------------------|----|------|-----|--|--------|
| FREIGHT<br>1Z5446640164431993                                  | EA | 1.00 | 001 |  | 720.16 |
| SHOP SUPPLY FEE<br>SHOP SUPPLIES & CONSUMABLES                 | EA | 1.00 |     |  | 315.00 |
| HAZARDOUS WASTE FEE<br>HAZARDOUS WASTE HANDLING & DISPOSAL FEE | EA | 1.00 |     |  | 561.02 |

Received By \_\_\_\_\_ Date \_\_\_\_\_

Material returns require a Return Authorization Number, a copy of this invoice and parts must be returned within 30 days of R.M.A. issuance to receive credit. A re-stocking fee may apply.

R.M.A.# \_\_\_\_\_

Date \_\_\_\_\_

Freight: 0.00

Tax Total: 5,598.97

Invoice Total (USD): 73,607.55