WO # [redacted]

QTY.	PART No. — DESCRIPTION	PRICE
2	DEGREASER	[redacted]
1	CLUTCH ASSY #2050 FT LB	
1	CLUTCH BRAKE SPIGOT	
2	COPPER WASHERS	
1	BRAKE KLEEN	
	SHOP SUPPLIES	

CARRIER [redacted]

OWNER [redacted]

[redacted]

SIGN HERE

I. C. C. No.

P. O. #

Make	Model	Year	Date	Mechanic

SPO	HUB	TRK	TRL	PH

(1) REPLACE CLUTCH AFTER INSPECTING OF PROBLEM. INTERNAL PRESS. PLATE FAILED. INSTALL A 15 1/4" HD. CLUTCH ASSY. R&R EXHAUST SYSTEM

(2) CLUTCH PEDAL - TOP PIVIOT SPLIT - REMOVE FROM SHAFT. EXTRACT ONE BOLT. WELD & RESHAPE PIVIOT. ADJUST CLUTCH SO PEDAL SWITCH WILL WORK.

(3) OIL LEAK - CLEAN OFF ENG. FOUND OIL PAN BOLT VERY LOOSE TIGHTEN PASS. SIDE PAN BOLTS NO LEAK.

TOTAL LABOR		
TOTAL PARTS		
MOTOR OIL		
A. T. F.		
GEAR OIL		
GREASE		
SUBLET WORK		
SERVICE CALL		
TAX		
TOTAL	2906	03