INVOICE

Part Description	Qty	Sale	Ext
5W-20 MOTORCRAFT	2.00		
5W-20 MOTORCRAFT	5.00		
Engine Oil Filter -	1.00		
REMAN ENGINE WITH 3 YEAR OR 100,000 MILE WARRANTY	1.00		
Spark Plug - - Plug Material: Finewire Platinum, Gap: .045, Replaces SP-515, Type - Standard Service Plg, w/ Black Coil Boots	8.00		
Exhaust Manifold Left	1.00		
Exhaust Manifold Right	1.00		
Engine Water Pump -	1.00		
EXHAUST MANIFOLD NUTS	16.00		
HEAD TEMP SENSOR	1.00		
Shop Supplies			

Labor Description	Ext
HAS A TIC IN THE ENGINE ON THE RIGHT SIDE, MAYBE EXHAUST? MAYBE ENGINE?	n/c
COMPUTER DIAGNOSTIC LEVEL 3 Test drive to verify complaint. Connect scan tool to read data gather codes. Check for any tsb's related to this issue. Diagnose for up to 1.5 hours.	
VALVE COVER - Remove & Replace - F250 Super Duty,F350 Super Duty,V8,Gas Right Side. VALVE SPRINGS ARE OFF, THE CAMSHAFT IS RUINED. NEEDS AN ENGINE.	
ENGINE ASSEMBLY (COMPLETE) - Remove & Replace - F250 Super Duty,F350 Super Duty,4WD,V8,Gas,Automatic Trans w/Air Conditioning - [Includes: R&I Engine Assembly. Transfer Fuel and Electrical Assemblies and Engine Mounts. Adjust (where applicable): Fuel mixt	
OIL CHANGE & LUBE WITH VEHICLE MAINTENANCE INSPECTION LUBE, OIL, FILTER	
FLUSH COOLING SYSTEM (LONG LIFE) Back flush the cooling system. Fill with proper amount of antifreeze to get to -35 degree.	
Hazardous Materials	

Labor:	
Parts:	
HazMat:	
SubTotal:	
Tax:	
Total:	6,566.05
Bal Due:	