

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	30+ /	783691 / 783691	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15NOV12		94.00	CHG	02NOV12
R.O. OPENED	READY	OPTIONS: ENG: C-12					

13:47 30OCT12 17:15 02NOV12

LINE OPCODE TECH TYPE HOURS

	LIST	NET	TOTAL
--	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 1814 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
 783691 COURTESY ENTRANCE INSPECTION

B DRIVE LINE CAME APART. SERVICE CALL

41 DRIVELINE

7172 CPT

7138 CPT

1 ETN/127591 OIL SEAL		1081.94	1081.94
1 ETN/127592 OIL SEAL	49.16	27.93	27.93
1 ETN/127589 LOCKNUT HEX FLANGED	39.70	22.56	22.56
1 ETN/127588 LOCKNUT HEX FLANGED	16.85	9.58	9.58
1 PH/VS48F8-6 COUPLING	17.72	10.07	10.07
10 3M/59349 15" BLACK CABLE TIE	3.33	2.29	2.29
2 801665BWK PETE MOD. VALVE	0.22	0.19	1.90
1 SP/6-4-9001-1X OUT PUT YOKE	181.64	181.64	363.28
1 SP/6-4-8991-1X YOKE	197.97	115.93	115.93
1 FRT FREIGHT	180.53	105.72	105.72
-1 FRT FREIGHT	49.68	49.68	49.68
1 FI/W01-358-9069 PETE AIR LEAF	49.68	49.68	-49.68
1 PH/VS48F8-6 COUPLING	194.69	154.24	154.24
2 NEIA/92084 5/16-18X3BOLT	3.33	2.29	2.29
4 NEIA/95111 5/16 SAE F/W	0.77	0.62	1.24
2 NEIA/94574 GD 8 LOCK NUT	0.11	0.09	0.36
1 SP/5-676X U - JOINT KIT	0.96	0.74	1.48
1 TDA/KT17SB STRAP & BOLT KIT FOR EASY SERVICE YOKE	149.30	81.63	81.63
SUBL DRIVELINE REPAIR BY AA WHEEL - PO 1074718	22.56	9.40	9.40
PO#831855			

PARTS: 909.90 CPT LABOR: 1081.94 OTHER: 451.53 TOTAL LINE B: 451.53 451.53
 2443.37

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
UNIT# 30
PIERSON HAULING
QUINTIN PIERSON
66056 US HWY 275
MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	783691 / 783691		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15NOV12			94.00	CHG	02NOV12
R.O. OPENED		READY		OPTIONS: ENG:C-12				

13:47 30OCT12 17:15 02NOV12

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

783691 1814 DRIVE TO HWY 75 AND Q TO INSPECT TRUCK. INTER AXLE DRIVE LINE CAME APART AND DAMAGED THE ABS VALVE, LF DRIVE AIR BAG, AND AIR LINE TO RIGHT REAR BRAKE CAN. CAME BACK TO SHOP AND GOT TOOLS. BLOCKED OFF AIR LINE TO AIR BAG AND FOLLOWED TRUCK BACK TO SHOP. 7172 CHECK TO SEE WHAT PARTS ARE NEEDED. TORCH OFF REST OF BROKE DRIVE LINE GIVE TO PARTS TO SEE IF CAN BE REPAIRED. 7172-MOVE TRUCKS/BRING IN SHOP. JACK UP FRAME AND REPLACE AIR BAG. START TO REMOVE BROKEN ABS VALVE. PARTS ON BENCH--7138 INSTALL NEW ABS MODULE VALVES FOR BOTH SIDES AND RECONNECTED ALL LINES. REMOVED AND REPLACE THROUGH SHAFT YOKE AND SEAL. REMOVE AND REPLACE REAR AXLE YOKE AND SEAL. INSTALLED NEW YOKES AND DRIVE LINE. DURING INSPECTION FOUND ANOTHER BAD U-JOINT ON DRIVE LINE FROM FRONT REAR AXLE TO CARRIER BEARING. REPLACE U-JOINT. AIRED UP TRUCK AND CHECK FOR LEAKS, AND PROPER BRAKE OPERATION. ALL WORKING PROPERLY AT THIS TIME. TEST DROVE AND RECHECKED ALL.

C** CHECK TRANSMISSION RANGE SHIFTING-TAKES 3-4 SECONDS TO RANGE SHIFT FROM LOW TO HIGH RANGE

600 TRANSMISSION
7101 CPT
7113 CPT
7172 CPT

1 FUL/85001 ELBOW 0.00 8.37 0.00 0.00
PARTS: 5.85 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 5.85 5.85

783691 7172-JACK UP TRUCK AND PUT ON BLOCK. PART ON STEP. 7101 BLOCK UP TRUCK. REMOVED SHIFT BOOT PANELS FOR ACCESS. REMOVED AIR LINE CLAMPS. REMOVED AIR LINES AT REAR OF TRANS. REMOVED SLAVE VALVE ASSEMBLY FROM TRANS. 7113-SET UP NEW VALVE AND INSTALLED ON TRUCK. CHECKED OPERATION, ALL WORKING PROPERLY AT THIS TIME.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV		1XP5DB9X64D819968	30+ /	783691 / 783691		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 15NOV12		94.00	CHG	02NOV12	
R.O. OPENED		READY		OPTIONS: ENG:C-12				
13:47 30OCT12		17:15 02NOV12						
LINE OPCODE TECH TYPE HOURS				LIST NET				

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	1081.94
PARTS AMOUNT	915.75
EPA FEE	0.00
SUBLET AMOUNT	451.53
SHOP FEES	151.47
TOTAL CHARGES	2600.69
LESS INSURANCE	0.00
SALES TAX	182.04
PLEASE PAY THIS AMOUNT	2782.73

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	780389 / 780389	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15NOV12		94.00	CHG	31OCT12
R.O. OPENED		READY	OPTIONS: ENG:C-12				

19:52 12OCT12 15:59 31OCT12

LINE OPCODE TECH TYPE HOURS

	LIST	NET	TOTAL
--	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

1814 CP

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
--------	------	--------	------	--------	------	---------------	------

B SHIFTS SLOW FROM LOW TO HIGH RANGE-DO NOT REMOVE BACK BOX.

600 TRANSMISSION

7104 CPT

7105 CPT

7138 CPT

1 A5000 SLAVE VALVE

1 FUL/19481 GASKET

235.00

235.00

98.90

98.90

98.90

4.51

3.15

3.15

PARTS:	102.05	LABOR:	235.00	OTHER:	0.00	TOTAL LINE B:	337.05
--------	--------	--------	--------	--------	------	---------------	--------

780389

7104!!!!!!CHECK TRUCK SEAMS THE AIR SPLIT SHIFTS GOOD ON THE FLOOR,ROADTEST,

IT SEAMED TO SHIFT TO SHIFT FOR ME,TOLD OFFICE WAS TOLD TO PARK OUT SIDE,LET COOL DOWN 7105-DRIVE & CHECK OUT ABOUT 6 TO 8 SECONDS TO SHIFT

FROM LOW TO HIGH.START TO REMOVE FLOOR AXCESS PANEL.PARTS IN TRUCK.

C ENGINE RUNS ROUGH AFTER UNIT GETS TO OPERATING TEMP

100 ENGINE

1488 CPT

PARTS:	0.00	LABOR:	643.90	OTHER:	0.00	TOTAL LINE C:	643.90
--------	------	--------	--------	--------	------	---------------	--------

780389

1488- TOOK FOR ROAD TEST TO GET ENGINE WARMED UP, JAKES WERE WEAK, BROUGHT

BACK TO SHOP AND RAN OVERHEAD, TOOK FOR DRIVE AND CAME BACK, ENGINE STILL

RUNS ROUGH BUT JAKES WORK GOOD, SET TIMING AND RE-FLASHED TOOK 3

TRIES STILL IDLES BAD, CHECKED POWERS AND GROUNDS TO ECM-OK, HOOKED UP CAT AND FOUND VOLTAGE 12.4 VOLTS, BATTERY VOLTAGE WAS 14.0 FOUND BAD

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN/OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+/-	780389/780389	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15NOV12		94.00	CHG	31OCT12
R.O. OPENED		READY		OPTIONS: ENG:C-12			
19:52 12OCT12		15:59 31OCT12					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

CONNECTION AT BATTERY'S, CLEANED UP AND
 TIGHTENED, ENGINE STOPPED RUNNING ROUGH AT IDLE.

D CHECK JAKE OPERATION - JUST HAD CUPS INJECTOR CUPS INSTALLED
 100 ENGINE

1488 CPT

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00
 780389 1488- RAN OVERHEAD AND TOOK CARE OF JAKES BEING WEAK.

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	878.90
PARTS AMOUNT	102.05
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	123.05
TOTAL CHARGES	1104.00
LESS INSURANCE	0.00
SALES TAX	77.27
PLEASE PAY THIS AMOUNT	1181.27

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV		1XP5DB9X64D819968	30+ /	738263 / 738263	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 30OCT12		94.00	CHG	10OCT12
R.O. OPENED		READY	OPTIONS:	ENG. C-12			

11:50 05OCT12 11:43 10OCT12

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7137 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

B CHECK FOR FUEL IN COOLING SYSTEM - POSSIBLE INJECTOR CUPS LEAKING

100 ENGINE

7137 CPT

7155 CPT

6 9X7317 SEAL O RING		1113.90	1113.90
6 2303728 SEAL	6.22	4.35	26.10
6 2303775 SEAL	11.45	7.34	44.04
6 2634920 SLEEVE-INJEC	7.72	7.16	42.96
12 1662904 SEAL-O-RING-	18.73	17.37	104.22
6 9X7430 SEAL O RING	10.94	10.15	121.80
6 8S9191 BOLT	7.50	5.24	31.44
1 NEIA/94112 5/8-11 NUT	2.63	1.94	11.64
2 LPWEX FLUSH @PINT	1.08	0.83	0.83
10 2388648 COOLANT-ELC	7.72	7.01	14.02
1 05-17223-000 CAP-PRESSURE. 10 PSI	12.94	12.00	120.00
PARTS: 524.96 LABOR: 1113.90 OTHER: 0.00	12.08	7.91	7.91
738263			TOTAL LINE B: 1638.86

7137 VERIFIED FUEL IN THE COOLANT. REMOVED COMPONENTS FOR ACCESS, REMOVED VALVE COVER, REMOVED ROCKERS, INJECTORS AND CUPS. CLEANED HOLES. INSTALLED THE O'RINGS ON THE CUPS. 7155 CLEAN CUP MATING SURFACES, LUBED O'RINGS, AND INSTALLED NEW CUPS. CLEAN AND INSTALL NEW O'RINGS ON INJECTORS. INSTALLED INJECTORS AND TIGHTENED HOLD DOWN BOLT TO PROPER TORQUE. REINSTALLED ROCKERS AND SET CLEARANCES TO SPECS. INSTALL VALVE COVERS, AND COMPONENTS REMOVED FOR ACCESS. DRAINED COOLING SYSTEM, ADD WEX AND REFILL WITH WATER TO FLUSH SYSTEM. RAN ENGINE TO OPERATING TEMP, AND FLUSHED OUT COOLING SYSTEM. REFILLED WITH NEW COOLANT. TEST DRIVE AND RECHECKED FOR LEAKS. ALL OKAY. PARK TRUCK OUT ON STREET FOR CUSTOMER

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	738263 / 738263	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 30OCT12		94.00	CHG	10OCT12
R.O. OPENED		READY		OPTIONS: ENG:C-12			
11:50 05OCT12		11:43 10OCT12					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

C** CHECK TRANS RANGE SHIFTING-SLOW TO SHIFT LOW TO HIGH *DO NOT REMOVE
 BACK BOX ON TRANS*

600 TRANSMISSION
 7155 CPT

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
 738263 7155 CUSTOMER NEEDED TRUCK ASAP. DID NOT HAVE TIME TO CHK.

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	1113.90
PARTS AMOUNT	524.96
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	155.95
TOTAL CHARGES	1794.81
LESS INSURANCE	0.00
SALES TAX	125.64
PLEASE PAY THIS AMOUNT	1920.45

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	30+ /	765654 / 765654	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 30AUG12		94.00	CHG	09AUG12
R.O. OPENED		READY	OPTIONS: ENG:C-12				

08:50 07AUG12 11:03 09AUG12

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 7137 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
 765654 COURTESY ENTRANCE INSPECTION

 B REPLACE THE GUSSETT BRACKETS ON RH & LH SIDES OF THE FRONT MOTOR
 MOUNT SUPPORT. FAN BLADE IS RUBBING ON THE SHROUD
 31 FRAME & FRAME COMPONENTS
 7137 CPT
 1 A11-6032 PETE BRKT. 233.12 233.12
 1 A11-6032R PETE BRKT. 81.38 81.38
 1 FRT FREIGHT 81.38 81.38
 -1 FRT FREIGHT 55.00 55.00
 2 NEIA/92072 5/16-18X11/2BOLT 55.00 55.00
 2 NEIA/92076 5/16-18X2BOLT 0.45 0.37
 4 NEIA/95111 5/16 SAE F/W 0.54 0.43
 2 NEIA/94574 GD 8 LOCK NUT 0.11 0.09
 PARTS: 166.20 LABOR: 233.12 OTHER: 0.00 TOTAL LINE B: 399.32
 765654 7137 REPLACED BROKEN MOTOR MOUNT GUSSETS. INSTALLED BOLTS IN
 HOOD THAT WERE MISSING.

 Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customerurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	233.12
PARTS AMOUNT	166.20
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	32.64
TOTAL CHARGES	431.96
LESS INSURANCE	0.00
SALES TAX	30.23
PLEASE PAY THIS AMOUNT	462.19

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	755822 / 755822	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 30JUN12		94.00	CHG	19JUN12
R.O. OPENED		READY	OPTIONS: ENG:C-12				
14:36 16JUN12		09:57 19JUN12					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 7109 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
 755822 INSPECTION 0.00

 B CHECK THE A/C SYSTEM & REPAIR
 700 A/C & HEATING
 7109 CPT
 1 ABP/N83-304163Q AC COMPRESSOR. QP7H15-4424. 172.02 172.02
 PACCAR
 1 113P/4060594RPBLT BELT 6 RIB X 1510 215.27 203.90 203.90
 32.44 28.63 28.63
 PARTS: 232.53 LABOR: 172.02 OTHER: 0.00 TOTAL LINE B: 404.55
 755822 7109- RECOVER FREON, GAINED ACCESS & REMOVED A/C COMPRESSOR.
 INSTALLED NEW ONE INSTALLED BELT, ADJUSTED & CHARGED THE SYSTEM. RUN &
 CHECK COOLING SYSTEM. ALL IS WORKING GOOD AT THIS TIME.

 C CHECK THE STEERING BOX U-JOINT. IF THE SAME AS FREIGHTLINER & WE HAVE
 THE PARTS. REPLACE IF NEEDED
 500 SUSPENSION/STEERING
 7155 CPT
 1 SP/5-103X STEERING SHAFT U-JOINT 95.88 95.88
 21.91 10.63 10.63
 PARTS: 10.63 LABOR: 95.88 OTHER: 0.00 TOTAL LINE C: 106.51
 755822 7155- FIND OUT IF WE HAVE CORRECT PART BEFORE REMOVING.
 REMOVED & INSTALLED NEW. GREASE & TEST.

 Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	267.90
PARTS AMOUNT	243.16
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	37.51
TOTAL CHARGES	548.57
LESS INSURANCE	0.00
SALES TAX	38.40
PLEASE PAY THIS AMOUNT	586.97

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	750632 / 750632		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 30MAY12		94.00	CHG	18MAY12	
R.O. OPENED		READY		OPTIONS: ENG:C-12				
14:37 17MAY12		11:47 18MAY12						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7109 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

750632 COURTESY ENTRANCE INSPECTION

B CHECK & ADVISE ON COOLANT LEAK

200 ENGINE COOLING/RADIATOR

7109 CPT

3 GT/4230T3/4 HTR HOSE4230 - 0002 2.24 1.65 305.50 4.95

6 PHM/5-032 LOOM WIRE 1 SPLIT B 0.66 0.39 2.34

10 3M/59349 15" BLACK CABLE TIE 0.22 0.19 1.90

6 GT/4230T3/4 HTR HOSE4230 - 0002 2.24 1.65 9.90

1 PH/68HB6-6 TUBE FITTING 3.09 2.12 2.12

1 PH/222P6-4 FITTING 3.45 2.37 2.37

6 OWI/AAA003 STD ANTIFREEZE 17.58 12.57 75.42

PARTS: 99.00 LABOR: 305.50 OTHER: 0.00 TOTAL LINE B: 404.50

750632 7109 CHECKED, FOUND HEATER HOSE BLOWN OUT. REMOVE AND
 REPLACE ONE RUNNING WATER PUMP TO ENGINE BLOCK BAD. REPLACE IT TO FILL
 COOLANT. RAN, CHECKED, NO LEAKS AT THIS TIME.

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	305.50
PARTS AMOUNT	99.00
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	42.77
TOTAL CHARGES	447.27
LESS INSURANCE	0.00
SALES TAX	31.31
PLEASE PAY THIS AMOUNT	478.58

CUSTOMER #: F11148
UNIT# 30
PIERSON HAULING
QUINTIN PIERSON
66056 US HWY 275
MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	30+ /	735077 / 735077	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 31MAR12		91.00	CHG	05MAR12
R.O. OPENED		READY	OPTIONS: ENG:C-12				
07:54 01MAR12		14:37 05MAR12					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7109 CPT

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

735077 COURTESY ENTRANCE INSPECTION

B CHECK POWER DIV. FOR COMING APART

35 REAR AXLE

7109 CPT

7127 CPT

1 FTR/DS404325 CARRIER		1092.00	1092.00
CORE CHARGE C	5441.14	1665.10	1665.10
SN M328315		747.50	747.50
1 ETN/512087 KIT AXLE HOUSING	114.13	72.90	72.90
2 CHR/47697 OIL SEAL	66.19	38.02	76.04
2 TDA/2208X440 GASKET	4.11	2.82	5.64
2 TDA/XK2124709E2 RELINED BRAKE SHOES	126.87	47.30	94.60
CORE CHARGE C		55.20	55.20
-2 TDA/XK2124709E2 CORE RETURN	27.60	27.60	-55.20
1 PEX/82194 NO.599 ULTRA GREY RTV	11.24	7.21	7.21
2 PHM/5-032 LOOM WIRE 1 SPLIT B	0.66	0.39	0.78
10 3M/41977 TIE WRAP 15" BLACK	0.22	0.19	1.90
38 MBL/98HL97 75/90W SYN GEAR LUBE	4.64	4.18	158.84
-1 FTR/DS404325 CORE RETURN	747.50	747.50	-747.50
PARTS: 2083.01 LABOR: 1092.00 OTHER: 0.00			
735077 7109 BRING TRUCK INTO SHOP, AND CHECK OUT REAR END. NOTED			3175.01

735077 7109 BRING TRUCK INTO SHOP, AND CHECK OUT REAR END. NOTED
THAT IT HAS TWO DINGS IN BANGO HOUSING, AND LEAKING OIL OUT OF HOUSING.
POSSIBLE IT IS CRACKED. DRAIN OIL, REMOVE POWER DIVIDER AND GEAR
CARRIER ASSEMBLY, AND INSPECTED. FOUND IT IS BAD. GETTING PRICE ON NEW
ONE. 7127- CLEANED HOUSING, AND WELDED HOLES IN HOUSING. PULLED HUBS
AND CLEANED WHEEL BEARINGS. REMOVED AND REPLACED BRAKES. 7109 OIL UP
BEARINGS, AND ASSEMBLED HUBS. PUT HUBS ON, AND FILL WITH OIL. PUT DRUMS
AND TIRES ON. INSTALLED NEW DIFFERENTIAL ASSEMBLY, AND REINSTALLED

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	735077 / 735077		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 31MAR12		91.00	CHG	05MAR12	
R.O. OPENED		READY		OPTIONS: ENG:C-12				
07:54 01MAR12		14:37 05MAR12						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
DRIVE LINE. FILL REAR END WITH NEW SYNTHETIC OIL. TAKE OUT, PUT ON BANK TO LET OIL RUN SIDE TO SIDE. ROAD TEST AND CHECKED COMPONENTS FOR LEAKS. ALL OK.							

 C CHECK FOR FUEL LEAK LEFT SIDE OF ENG.
 300 FUEL/EXHAUST
 7109 CPT
 1 4P0902 HOSE A
 4 PHM/5-030 LOOM WIRE 3/4 SPLIT
 PARTS: 39.74 LABOR: 169.26 OTHER: 0.00 TOTAL LINE C: 209.00
 735077 7109 CHECK LINE FILTER TO BACK HEAD LEAKING. REMOVE OLD
 INSTALL NEW. RUN. CHECK LEAKS. OK.

 D ABS LIGHT IS ON
 400 BRAKES
 7109 CPT
 1 801538BXW ABS SENSOR
 PARTS: 59.81 LABOR: 90.09 OTHER: 0.00 TOTAL LINE D: 149.90
 735077 7109 CHECK ABS RIGHT FRONT SENSOR CODE ORDER FROM PETE. 7109
 REMOVE ONE ABS SENSOR. INSTALL NEW ONE. TIE UP. TOOK OUT ROAD TEST.
 LIGHT WENT OUT. ALL OKAY AT THIS TIME.

 Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	1351.35
PARTS AMOUNT	2182.56
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	189.19
TOTAL CHARGES	3723.10
LESS INSURANCE	0.00
SALES TAX	260.61
PLEASE PAY THIS AMOUNT	3983.71

CUSTOMER #: F11148
 UNIT# 30PH
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN			LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968			819968	903006/903006	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 30JUN14		102.00	CHG	25JUN14	
R.O. OPENED		READY	OPTIONS: ENG:C-12					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7104 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

903006 COURTESY ENTRANCE INSPECTION

B CHECK THE A/C SYSTEM. POSSIBLE FAILED A/C COMPRESSOR

700 A/C & HEATING

1488 CPT

7101 CPT

7198 CPT

513.06 513.06

1 ABP/N83-304163Q AC COMPRESSOR. QP7H15-4424.

PACCAR

233.93 195.27 195.27

1 ABP/N83-312125 O - RING KIT

5.94 4.15 4.15

1 EC010061 ORFC TUBE

28.12 19.31 19.31

1 F31-6063 PETE ACCUMULATOR

122.46 90.09 90.09

4 COS/R134WA WARRANTY ONLY - R134A

13.38 11.06 44.24

1 23-15619 PETE HVAC FILTER

28.55 17.96 17.96

1 3X011171 EVAP CORE

567.99 500.22 500.22

1 FRT FREIGHT

13.00 13.00 13.00

-1 FRT FREIGHT

13.00 13.00 -13.00

PARTS: 871.24 LABOR: 513.06 OTHER: 0.00 TOTAL LINE B: 1384.30

903006 1488- CHECKED A/C CLUTCH-LOCKED UP, RECOVERED 1.34LBS FREON, REMOVED LINES OFF A/C COMPRESSOR AND CHECKED FOR METAL- HAS NORMAL METAL CONTENT. TURNED IN PARTS REQUEST. 1488- REPLACED A/C COMPRESSOR, INSTALLED LINES WITH NEW O-RINGS, INSTALLED BELT, REMOVED LINE FOR ORFICE TUBE, TRIED TO GET OUT BUT IT IS STUCK BAD, WENT TO MENARDS AND GOT SMALL LONG SCREWS TO TRY TO GET OUT- NO LUCK- NEEDS EVAPORATOR REPLACED. TURNED IN PREQ FOR QUOTE ON EVAPORATOR. 1488- REMOVED UPPER HOSE AT EVAPORATOR, DASH PANELS, STEPPER MOTOR, EVAPORATOR. 7101 CHECK ON PARTS ORDERED FOR TRUCK. REMOVED ACCUMULATOR, REPLACED O-RINGS, INSTALLED NEW ACCUMULATOR. 7104 CLEAN OUT HVAC HOUSING. INSTALLED EVAPORATOR INTO THE TRUCK. 7198 PUT LOW SIDE LINE ON. PUT DASH BACK

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #: F11148
 UNIT# 30PH
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	819968	903006/903006	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 30JUN14		102.00	CHG	25JUN14
R.O. OPENED		READY		OPTIONS: ENG:C-12			

07:41 21JUN14 11:08 25JUN14

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

TOGETHER. VACUMED AND CHARGED 4LB. RAN TRUCK. GETTING COLD NOW

C CHECK THE CLUTCH FOR ADJUSTMENT / CLUTCH BRAKE ADJUSTMENT
 25 CLUTCH

1488 CPT
 7104 CPT

1 06-01150 CLUTCH ROD		336.60	336.60
1 J21270-14 ROD END	48.32	33.18	33.18
1 06-01105 JAM NUT	65.68	56.37	56.37
1 06-00984 ROD END	9.99	6.21	6.21
1 HWC02552 JAM NUT	58.34	50.08	50.08
1 NEIA/92270 1/2-12X21/2BOLT	2.55	1.39	1.39
2 NEIA/94580 GD 8 LOCK NUT	1.44	1.11	1.11
2 NEIA/95117 1/2HW	1.48	1.14	2.28
1 NEIA/92266 1/2-13X2BOLT	0.45	0.37	0.74
	1.24	0.96	0.96

PARTS: 152.32 LABOR: 336.60 OTHER: 0.00 TOTAL LINE C: 488.92

903006 1488- REMOVED CLUTCH INSPECTION PLATE, ROTATED ENGINE AND ADJUSTED CLUTCH, HAS TOO MUCH FREE TRAVEL NOW AND NOT HITTING CLUTCH BRAKE, TRIED TO ADJUST ROD-SEIZED, GOT QUOTE FOR CLUTCH ROD ASSEMBLY. 1488- GOT NEW CLUTCH ROD, REMOVED FRONT BOLT AND NUT, REAR NUT WAS SEIZED-USED TORCH AND HEATED, NUT ALMOST CAME OFF THEN STOPPED, GOT CUT OFF WHEEL IN AND CUT BOLT OFF, USED TORCH AND HEATED HEIM JOINT, PRYED BOLT OUT, **INSTALLED NEW CLUTCH ROD ASSY**, ADJUSTED FREE TRAVEL, STARTED ENGINE AND GOT TO GO INTO GEAR MANY TIMES, LOCKED DOWN JAMB NUTS.

D** REPAIR THE REMOTE THROW OUT BEARING GREASE HOSE THAT IS NOT

CONNECTED

25 CLUTCH

7101 CPT		103.02	103.02
2 NEIA/92060 5/16-18X1/2BOLT	0.28	0.24	0.48
2 NEIA/95351 5/16 L/W	0.11	0.09	0.18

PARTS: 0.66 LABOR: 103.02 OTHER: 0.00 TOTAL LINE D: 103.68

903006 7101 CHECK AND INSTALLED CLUTCH RELEASE BEARING HOSE.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30PH
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV		1XP5DB9X64D819968	819968	903006/903006		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 30JUN14		102.00	CHG	25JUN14	
R.O. OPENED		READY		OPTIONS: ENG:C-12				
07:41 21JUN14		11:08 25JUN14						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL	
INSTALLED INSPECTION COVER.								

 REMIT TO TRUCK CENTER COMPANIES
 PO BOX 27379
 OMAHA, NE 68127

Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	952.68
PARTS AMOUNT	1024.22
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	133.38
TOTAL CHARGES	2110.28
LESS INSURANCE	0.00
SALES TAX	147.73
PLEASE PAY THIS AMOUNT	2258.01

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	876930 / 876930	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15JAN14		98.00	CHG	13JAN14
R.O. OPENED		READY	OPTIONS: ENG C 12				

08:36 07JAN14 09:10 13JAN14

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
-----------------------------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7155 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

B COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

7155 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C CHECK FOR A NO START CONDITION - TRUCK WILL NOT START WHILE CRANKING
 WITH STARTER - BUT WILL START RIGHT UP WHEN PULL STARTED -
 POSSIBLE ECM OR IGNITION POWER ISSUE

100 ENGINE

7155 CPT

1 PHM/8-662 TERM BATT GRP 31 3/8	3.87	1.82	254.80	254.80
1 PEX/80370 BATTERY PROTECTOR	5.91	4.13		1.82
1 PHM/1-1962 TERM WIRE SEALED CRI	0.85	0.40		4.13
2 PHM/1-52256 TERM WIRE INSULAT RI	0.37	0.16		0.40
1 NEIA/30416 1/2 STUD 8GA EYELET	2.49	1.71		0.32
1 PHM/6-107 TUBING HEAT SHRINK C	2.38	1.12		1.71
1 PHM/8-662 TERM BATT GRP 31 3/8	3.87	1.82		1.12
1 JEI/BC207M2BWS BATTERY CABLE NEG	57.58	37.98		1.82
PARTS: 49.30 LABOR: 254.80 OTHER: 0.00			TOTAL LINE C:	304.10

876930 7155. TRUCK STARTED FINE OUT ON LOT. BRING IN, CHECK FUEL
 LINES AND CHECK AND CLEAN BATTERY AND ECM CABLES. FOUND 1 BAD CABLE AND
 IT WAS TIED INTO ECM WIRE. REPLACED CABLE AND REDO ECM WIRE. CHECKED
 STARTING. TRUCK STARTS GOOD. WILL NEED TO RECHECK AT A LATER TIME.
 RECHECKED STARTING SEVERAL TIME. STARTED OKAY EACH TIME.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV		1XP5DB9X64D819968	30+ /	876930 / 876930		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN04 DD			17:00 15JAN14		98.00	CHG	13JAN14	
R.O. OPENED		READY		OPTIONS:		ENG:C-12		
08:36 07JAN14		09:10 13JAN14						
LINE OPCODE TECH TYPE HOURS				LIST				

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	254.80
PARTS AMOUNT	49.30
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	35.67
TOTAL CHARGES	339.77
LESS INSURANCE	0.00
SALES TAX	23.79
PLEASE PAY THIS AMOUNT	363.56

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	30+ /	861610 / 861610	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			WAIT 30OCT13		98.00	CHG	16OCT13
R.O. OPENED		READY		OPTIONS: ENG:C-12			

07:38 14OCT13 15:51 16OCT13

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION

CI COURTESY ENTRANCE INSPECTION

1488 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

861610 COURTESY ENTRANCE INSPECTION

B CHECK FOR LOOSING THROTTLE AT TIMES WHEN DRIVING - ENGINE SHUTTERS

WHEN LOOSES THROTTLE - NO CEL

100 ENGINE

1488 CPT

2 PHM/1-1961 TERM WIRE SEALED CRI 0.85 298.90 298.90

2 PHM/8-43147 CBL TIE 14.5 NYL BL 0.16 0.40 0.80

1 AMA/Y101506 SOCKETBULB 4.73 0.07 0.14

PARTS: 4.25 LABOR: 298.90 OTHER: 0.00 TOTAL LINE B: 303.15

861610 1488- CHECKED FOR FAULT CODES AND HAD ACTIVE FAULT FOR
 PRIMARY SPEED TIMING LOSS OF SIGNAL, REMOVED CONNECTOR AND INSPECTED
 WIRE AS ENGINE DIAPER HAD WORE INTO WIRES, REPAIRED WIRES, CLEARED
 FAULT, ALSO HAD 255 COUNTS OF COOLANT LEVEL INVALID, REMOVED SURGE TANK
 BOLTS AND UNPLUGGED SENSOR AND FOUND ONE TERMINAL SPREAD, REMOVED WIRE
 AND REPAIRED WITH PICK- PIN TENSION IS GOOD ON ALL 4 NOW, CLEARED
 FAULT, REPLACED TACH BULB, TEST DROVE AND NO PROBLEMS FOUND.

Express Assessment gets you back on the road
 fast. We diagnose repairs within two hours
 of arrival. All repairs are inspected by our
 certified foremen. If you are not completely
 satisfied with our service please call or see
www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	298.90
PARTS AMOUNT	4.25
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	41.85
TOTAL CHARGES	345.00
LESS INSURANCE	0.00
SALES TAX	24.15
PLEASE PAY THIS AMOUNT	369.15

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	1 / 1	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 17SEP13		98.00	CHG	18SEP13
R.O. OPENED		READY		OPTIONS: ENG:C-12			
12:04 17SEP13		09:59 18SEP13					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 7105 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
 1 COURTESY ENTRANCE INSPECTION

 B CHECK THE ALTERNATOR & ELECTRICAL. VOLTS KEEP DROPPING ON THE GAUGE
 54 ELECTRICAL, INSTRUMENTS, CONTROLS
 7105 CPT
 1 AWDI/5080990 SERP. BELT
 PARTS: 46.47 LABOR: 98.00 OTHER: 0.00 TOTAL LINE B: 144.47
 1 7105 CHECK OUT PROBLEM - FOUND BELT GONE - CHECKED ALL
 PULLEYS-ALL OK. INSTALL NEW BELT & RUN-DO. ALL WORKING PROPERLY AT THIS
 TIME.

Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	98.00
PARTS AMOUNT	46.47
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	13.72
TOTAL CHARGES	158.19
LESS INSURANCE	0.00
SALES TAX	11.07
PLEASE PAY THIS AMOUNT	169.26

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	844612 / 844612	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 31AUG13		98.00	CHG	15AUG13
R.O. OPENED		READY		OPTIONS: ENG:C-12			
10:20 05AUG13		10:49 15AUG13					

LINE OPCODE	TECH TYPE	HOURS	LIST	NET	TOTAL
-------------	-----------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 7155 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
 844612 COURTESY ENTRANCE INSPECTION

B A/C LINE BLEW - REPAIR A/C AS NEEDED
 700 A/C & HEATING
 7111 CPT
 7155 CPT

6 PHM/8-43147 CBL TIE 14.5 NYL BL	0.16	379.26	379.26
2 TYC/DCT110HIR TIESTRAP	2.66	0.07	0.42
1 18-04015 PETE CONDENSOR	428.31	1.96	3.92
4 COS/R134WA WARRANTY ONLY - R134A	13.38	410.26	410.26
1 1-2929 PETE A/C HOSE	182.76	11.06	44.24
3 TYC/DCT110HIR TIESTRAP	2.66	182.76	182.76
6 PHM/8-43147 CBL TIE 14.5 NYL BL	2.66	1.96	5.88
PARTS: 647.90 LABOR: 379.26 OTHER: 0.00	0.16	0.07	0.42
		TOTAL LINE B:	1027.16

844612 REMOVE BOLT OUT OF COMPRESSOR. TAPE UP COMPRESSOR. CUT ZIP
 TIES. REMOVE BOLT & SCREW & PRESSURE SWITCH. CONDENSER FITTING FROZEN.
 HEAT UP TOOK THREAD OFF CONDENSER & NUT THREADS JUNK NEED LINE &
 CONDENSER GIVE LINE TO PARTS7155/ HELP ADJUST HYDRAULIC CLUTCH REMOVE
 CONDENSOR INSTALL NEW. INSTALL LINE VAC CHARGE. SECURE LINES AND RUN VENT
 TEMP 60 AMBIENT TEMP 93

Express Assessment gets you back on the road
 fast. We diagnose repairs within two hours
 of arrival. All repairs are inspected by our
 certified foremen. If you are not completely
 satisfied with our service please call or see
www.e-freightliner.com/customer survey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	379.26
PARTS AMOUNT	647.90
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	53.10
TOTAL CHARGES	1080.26
LESS INSURANCE	0.00
SALES TAX	75.62
PLEASE PAY THIS AMOUNT	1155.88

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT	TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	822069/822069	T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			07:00 15MAY13		98.00	CHG	30APR13
R.O. OPENED		READY		OPTIONS: ENG:C-12			
14:09 29APR13		15:36 30APR13					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A COURTESY ENTRANCE INSPECTION
 CI COURTESY ENTRANCE INSPECTION
 7110 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

B OIL LEAK ON RH SIDE-TRANS OIL COOLER LINES LEAKING-REPLACE BOTH
 00 MAINTENANCE
 7110 CPT
 22 PH/213-10-300 HOSE 291.06 291.06
 4 PH/20821-10-10 FITTING 8.98 5.76 126.72
 5 UMP/S465G12-3 CLAMP 34.59 25.80 103.20
 2 TYC/DCT110HIR TIESTRAP 3.90 2.68 13.40
 5 SLO/550026909 50W SYN TRANS OIL 2.66 1.96 3.92
 PARTS: 271.89 LABOR: 291.06 OTHER: 0.00 TOTAL LINE B: 562.95

822069 FIND TRUCK BRING IN. REMOVE LOOM CLAMPS & FITTINGS, MAKE NEW
 HOSES, INSTALL & TIGHTEN FITTINGS. HAD TO REPLACE LOOM CLAMS. DIFFERENT
 SIZE HOSE. INSTALL CLAMPS & FILL TRANSMISSION

 Express Assessment gets you back on the road fast. We diagnose repairs within two hours of arrival. All repairs are inspected by our certified foremen. If you are not completely satisfied with our service please call or see www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	291.06
PARTS AMOUNT	271.89
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	40.75
TOTAL CHARGES	603.70
LESS INSURANCE	0.00
SALES TAX	42.25
PLEASE PAY THIS AMOUNT	645.95

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968	30+ /	802322 / 802322	T30	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15MAR13		94.00	CHG	25FEB13
R.O. OPENED	READY	OPTIONS	ENG. C-12				

10:53 23FEB13	10:05 25FEB13						
LINE OPCODE	TECH	TYPE	HOURS				
A	COURTESY	ENTRANCE	INSPECTION	LIST	NET	TOTAL	

CI COURTESY ENTRANCE INSPECTION
 7110 CP
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

B CHECK & ADVISE ON THE ENGINE WARNING. THE CEL IS ON. RUNS GOOD
 100 ENGINE

7172 CPT
 7110 CPT

1 2842728 SENSOR GP-PR	390.10	390.10
1 2495293 HARNESS AS	147.71	136.94
1 5P7814 SEAL	30.57	28.35
8 SLO/500004741 15W40 OIL, QT BULK OIL	6.16	4.31
1 2338005 JOINT-EXPANS	3.82	3.45
PARTS: 430.61 LABOR: 390.10 OTHER: 0.00 TOTAL LINE B:	251.76	233.41
		820.71

802322 7172-CEL IS ON. HOOKUP AND CHECK. CODE ACTIVE FOR VVA OIL
 PSI SENSOR. GET OK TO REPLACE. REMOVE SENSOR, FOUND LOCK ON HARNESS
 MISSING AND A LOT OF RUBBED SPOTS. INSTALL NEW SENSOR AND HARNESS. TOP
 OFF ENG OIL AND RUN TRUCK, NO CEL. CLEAR CODES AND TEST DRIVE. OK NO
 CEL. HAS BOOST LEAK RIGHT SIDE 7110 REMOVE TUBES REMOVE BLOWN BELLOWS.
 INSTALL NEW BELLOWS & TUBES & CLAMPS. INSTALL SCREW IN LH PLATE
 FLOPPING BY HEADLIGHTS TO SECURE. TEST DRIVE OK.

C** INSTALL THE ORDERED IN SPRING BUSHINGS
 00 MAINTENANCE

7110 CPT	376.00	376.00
2 AUT/M1641 PETE EYE CASTING	95.91	65.86
2 AUT/TRK5904 PETE BUSHING	49.50	42.49
1 AUT/AUBK8253-051 U-BOLT KIT	27.98	24.02
2 23-09444-450 5/8-11C X 4.5 IN. L	10.79	7.07
2 23-13861-110 NUT-HEX.FLNG.LKG.5/8-11.ZINC AL	2.97	2.08
2 NEIA/95117 1/2HW	0.45	0.37
2 3568887 BOLT	4.99	4.99

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: F11148
 UNIT# 30
 PIERSON HAULING
 QUINTIN PIERSON
 66056 US HWY 275
 MALVERN, IA 51551

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
BLACK	04	PETERBILT 379 CONV	1XP5DB9X64D819968		30+ /	802322 / 802322		T30
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
01JAN04 DD			17:00 15MAR13			94.00	CHG	25FEB13
R.O. OPENED		READY		OPTIONS: ENG:C-12				
10:53 23FEB13		10:05 25FEB13						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
		2	NEIA/94580 GD 8	LOCK NUT	1.48	1.14	2.28
		10	NEIA/95117 1/2	HW	0.45	0.37	3.70
		4	23-00461-006 3/4-16	HI HEX G8 L	7.64	5.46	21.84
		4	23-09114-004 3/4 IN.	WASHER L	3.42	2.40	9.60
		1	C105MA LUBRIPLATE	105	7.65	5.87	5.87
		4	NEIA/92484 3/4-10 X 2	GRADE	2.10	1.55	6.20
		1	NEIA/83252 14X1	SDRL SCREW	0.45	0.37	0.37
PARTS: 319.60 LABOR: 376.00 OTHER: 0.00 TOTAL LINE C:							695.60

802322 LH REAR BOLTS & BLOCK BOLTS FROZEN. HAD TO CUT & BEAT OUT.
 INSTALL NEW BLOCK & BUSHINGS & BOLTS. ASSEMBLE & BOLT UP. START TO CUT
 OUT OTHER SIDE. FINISH CUTTING OUT SPRING BRACKET. INSTALL NEW BRACKET
 & BOLTS & SHIMS. INSTALL BUSHINGS & PLATES. TIGHTEN ALL BOLTS. LOCK IN
 ALL BOLTS. ALL OKAY AT THIS TIME.

Express Assessment gets you back on the road
 fast. We diagnose repairs within two hours
 of arrival. All repairs are inspected by our
 certified foremen. If you are not completely
 satisfied with our service please call or see
www.e-freightliner.com/customersurvey
 Dealer Code : WRFD

DESCRIPTION	TOTALS
LABOR AMOUNT	766.10
PARTS AMOUNT	750.21
EPA FEE	0.00
SUBLET AMOUNT	0.00
SHOP FEES	107.25
TOTAL CHARGES	1623.56
LESS INSURANCE	0.00
SALES TAX	113.65
PLEASE PAY THIS AMOUNT	1737.21