Date and Time In: 9/7/2016 - 9:52 AM
Date and Time Out: 9/16/2016 - 12:23 PM
Promised Date - Time: 9/7/2016 - 9:52 AM
Cashed Out Date: 9/16/2016 - 2:32 PM
Date Appointment Initiated: 9/7/2016

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	5.05	ET411627	056	Retail			
	Slide out on driver side not working. It has a bad grinding noise. Customer had other road service help move slideout back in and had to remove inside trim (trim on top of slide) and removed parts off of motor. . CAUSE: Found the gear box was burnt up and needs to be replaced CORRECTION: Moved slide out manually and took the cables off of the gear box installed the new gear box and re-attached the cables and checked operation and worked fine						
2	0.25	ET411627	056	Retail			
	Check tire pressure and also tire wear. CAUSE: Found tire wear looked normal and the tires needed air CORRECTION: Added air as needed set the pressure at 47lbs						
3	0.50	ET411627	056	Retail			
	reinstall slide out trim which is on top of slide CAUSE: Found facia trim was coming loose CORRECTION: Re-attached facia trim as needed						
4	0.50	ET411627	056	Retail			
	Trim on other slide is off and is sitting on top of that slide. CORRECTION: Re-attached trim on the passenger side slide that was sitting on the table						
5	0.40	ET411627	056	Retail			
	Passenger slide storage door storage latch needs replaced CAUSE: Found door latch broken and needs to be replaced CORRECTION: R&R door latch and checked operation						
6	0.75	ET411627	056	Retail			
	Passenger side on tire hub cap/ cover needed installed. CAUSE: Found center cap needed to be replaced CORRECTION: Removed wheel and replaced the center cap						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
1	FR	FREIGHT						
1	392596K	Actuator - Gearbox - 13 Tooth Sprocket						
5	20-0652	COMPARTMENT DOOR CATCH						
6	336005R	CHROME CENTER CAP - 3.19" - W/ PLU						
6	FR	FREIGHT						

Pay Type	CC #	Amount

Total: $1,048.83

Printed On : 9/24/2019 9:48:57 AM
Reprint

No. 2245 P. 3

Date and Time In: 6/23/2016 - 1:29 PM
Date and Time Out: 6/23/2016 - 1:29 PM
Promised Date - Time: 6/22/2016 - 1:00 PM
Cashed Out Date: 6/23/2016 - 2:24 PM
Date Appointment Initiated: 6/22/2016

Veh Info: 14 Keystone Passport TT
Serial Numbers: Need
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	1.15	Need	025				
	Refer has check light on it CAUSE: Found the unit had run out of propane that is why the check light came on. CORRECTION: Filled propane and checked operation it worked fine.						
2	0.50	Need	025				
	Check water heater operation CAUSE: Checked water heater on gas and electric it worked fine						
3	0.00	Need					
	Fill propane CORRECTION: Filled propane						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
3	Lpgal	LP GAS by the gallon						

Pay Type	CC #	Amount

Total: $206.71

Date and Time In: 5/30/2017 - 12:35 PM
Date and Time Out: 5/30/2017 - 4:25 PM
Promised Date - Time: 5/30/2017 - 12:35 PM
Cashed Out Date: 5/30/2017 - 4:25 PM

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: Miles/Hrs In: Out: Plate #:

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	1.40	ET411627	019	Policy Charg	INC	INC	INC
	Put satellite connection in the bedroom right below the window						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
1	24-1040	CABLE TV KIT w/WP COVER	1.00					INC
1	9646	cable ends "F"	2.00					INC

Pay Type	CC #	Amount

Total: $0.00

Printed On : 9/24/2019 9:50:03 AM
Reprint

No. 2265 P. 9

Date and Time In: 5/22/2018 - 3:19 PM
Date and Time Out: 5/25/2018 - 10:30 AM
Promised Date - Time: 5/24/2018 - 3:19 PM
Cashed Out Date: 5/25/2018 - 10:31 AM
Date Appointment Initiated: 5/22/2018

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

Repair	Hrs Requested	VIN	Mech #	Type	Labor	Discount	Total
1	2.90	ET411627	064	Retail			

Repair Description
Customer request Summer Special. Includes check and service AC unit, wash and treat roof, seal any voids in roof, and wash camper.
CORRECTION: Serviced AC, cleaned the coils & filter, washed & treated the roof, no voids but did noticed the seals above the guttering on both sides need to attention, cocking is splitting. Roof does need a new reefer vent, tech also washed the exterior of the camper with soap and brushed.

2	1.00	ET411627	064	Retail			

De-winterize camper, flush water system.
CORRECTION: Tech flushed out water system with water, un by passed the hot water heater & dumped tanaks.

3	0.50	ET411627	064	Retail			

Check tires and adjust pressure as needed, check batteries, check appliances and LP.
CORRECTION: Topped off tires to 50psi, tested battery and tested good, checked all appliances, tech checked the hot water heater, the furnace, AC, stove, oven, microwave, & the refrigerator, all work good. One propane bottle is empty & the other is 3/4 full.

4	0.10	ET411627	064	Retail			

Check both slides and seals to make sure both are operating properly.
CORRECTION: Tech ran both slides in and out and both worked fine, no problems found.

5	0.10	ET411627	064	Retail			

Check all detectors and make sure they are operating correctly.
CORRECTION: Tech checked all three detectors & all tested good and the two CO2 detectors have good batteries.

6	0.00	ET411627	064	Retail			

26 point inspection.

7	0.20	ET411627	064	Retail			

Replace Reefer vent on top of camper.
CORRECTION: Tech removed old cover vent for reefer unit and installed a new one.

8	0.70	ET411627	064	Retail			

Reseal cracks above guttering on both sides.
CORRECTION: Tech removed old cocking from above guttering on roof top and resealed with new sealant.

9	0.60	ET411627	064	Retail			

The kitchen vent handle is broken. Can the handle be replaced or does it need a new assembly.
CORRECTION: Tech installed the new vent gear mechanism on the old vent.

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
1	6560	COIL CLEANER						

Date and Time In: 5/22/2018 - 3:19 PM
Date and Time Out: 5/25/2018 - 10:30 AM
Promised Date - Time: 5/24/2018 - 3:19 PM
Cashed Out Date: 5/25/2018 - 10:31 AM
Date Appointment Initiated: 5/22/2018

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

1	32512FS	RUBBER ROOF CLEANER, 32OZ
1	F022030FS	WYE ROTATING BAY FITTING
7	42160C	REFER VENT COVER - WHITE
8	410191	DICOR LAP SEALANT WHITE 11-OZ TU
9	47-0347	VENTADOME OPERATOR

Pay Type	CC #	Amount

Total: $807.94

Printed On : 9/24/2019 9:50:17 AM
Reprint

No. 2245 P. 11

Date and Time In: 4/11/2017 - 10:21 AM
Date and Time Out: 4/11/2017 - 10:21 AM
Promised Date - Time: 3/24/2017 - 4:07 PM
Cashed Out Date: 4/11/2017 - 2:55 PM
Date Appointment Initiated: 3/24/2017

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	1.25	ET411627	019				
	Dewinterize camper and make sure there are no leaks CORRECTION: Dewinterized camper didn't find any leaks.						
2	0.25	ET411627	019				
	check tire preasure CORRECTION: checked tire pressure set all tires at 47 psi.						
3	0.25	ET411627	019				
	Fill lp bottles CORRECTION: filled with 3 gal of propane						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
Pay Type	CC #	Amount						

Total: $202.23

Printed On : 9/24/2019 9:49:37 AM
Reprint

No. 2245 P. 7

Date and Time In: 5/24/2017 - 10:41 AM
Date and Time Out: 5/26/2017 - 3:05 PM
Promised Date - Time: 5/22/2017 - 9:06 AM
Cashed Out Date: 5/30/2017 - 10:55 AM
Date Appointment Initiated: 5/22/2017

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	1.70	ET411627	019	Retail			
	leaking in between the wall from bathroom to bedroom maybe around the skylight CAUSE: found a line to the outside shower which had been leaking for a while reset the line replaced end and washer no leaks now						
2	0.50	ET411627	019	Retail			
	need to put in a direct port in the for sattilite dish from the outside CAUSE: installed sat. hook up by living room tv						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
1	602317	SANTOPRENE SWIVEL 1/2" SEAL RUBI	1.00	$0.69	$0.00	$0.69	$0.00	$0.69
2	24-1040	CABLE TV KIT w/WP COVER	1.00	$13.29	$0.00	$13.29	$0.00	$13.29

Pay Type	CC #	Amount

Total: $269.33

No. 2245 P. 8

Date and Time In: 10/31/2016 - 2:41 PM
Date and Time Out: 11/3/2016 - 9:57 AM
Promised Date - Time: 10/4/2016 - 10:47 AM
Cashed Out Date: 11/8/2016 - 9:57 AM
Date Appointment Initiated: 10/4/2016

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**

Repair	Hrs	VIN	Mech #	Type	Labor	Discount	Total
	Requested Repair Description						
1	0.00	ET411627		Retail			
	Repair 1 has been moved to Invoice 131567B—Recall #16261 A/C wiring CAUSE: Repair 1 has been moved to Invoice 131567B CORRECTION: Repair 1 has been moved to Invoice 131567B						
2	1.60	ET411627	019	Retail			
	Winterize camper and dump tanks CAUSE: winterized and dumped coach tanks needed repeated flushing						
3	0.50	ET411627	019	Retail			
	front stab jack door side is bent CAUSE: checked both front stab jacks only replaced door side						
4	0.90	ET411627	019	Retail			
	need to replace tag holder on tail light CAUSE: replaced tag light and put on new bracket						
5	0.30	ET411627	019	Comeback			
	S/O is still making a noise when coming in need to verify operation is ok CAUSE: ran S/O run normally ops ok noise is not anything mechanical						
6	1.00	ET411627	019	Retail			
	service AC CAUSE: cleaned front coil cleaned filter and taped up intake where loose A/C operation OK						

Repair	Part #	Description	Qty	Retail Price	Savings	Selling Price	Extended Discount	Extended Price
2	661783	Commando Black Tank Cleaner						
2	2612785	SPLASH RV ANTIFREEZE - 50 GAL. DR						
3	48810C	EAZ-LIFT 24" SCISSOR JACK - 5000 LB						
4	18-0157	TAIL LIGHT w/ TAG BRACKET - RED						
4	1402p3	3" Hardcast Aluminized Tape						

Pay Type	CC #	Amount


Total: $541.19

Printed On : 9/24/2019 9:49:23 AM
Reprint

No. 2245 P. 5

Date and Time In: 9/7/2016 - 9:52 AM
Date and Time Out: 9/16/2016 - 12:23 PM
Promised Date - Time: 9/7/2016 - 9:52 AM
Cashed Out Date: 9/16/2016 - 2:32 PM
Date Appointment Initiated: 9/7/2016

Veh Info: 14 Keystone Passport TT
Serial Numbers: 4YDT31820ET411627
In-Srv: **Miles/Hrs In:** **Out:** **Plate #:**



Amount Due: $1,048.83

No. 2245 P. 4