002803

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1	K294-194	Door Handle	
1	HDC 010626	KWRW Ray,	
6	Coolant		
3	Gear lube		
2	PL1070ATR	mounts	
4	K264-84	grommet	
4	M200-70EP	bushings	
		SPECIAL REPAIRS	

NAME

DATE 7-19-17

ADDRESS

CITY

PHONE WHEN READY ?

TIME RECEIVED A.M. P.M.

TIME PROMISED A.M. P.M.

TERMS

CUSTOMER'S ORDER NO.

YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
94	HW 7800				

OPER. NO. | **REPAIR ORDER — LABOR INSTRUCTIONS** | ORDER WRITTEN BY

LUBRICATE ☐ CHANGE OIL ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐ $

Replace Radiator & coolant in truck.
Check out GENERAL CONDITION of truck.

RETAIN PARTS ☐ DESTROY PARTS ☐

TOTAL PARTS

ESTIMATE AMOUNT

PARTS LABOR

	TIME	BY	
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			

ESTIMATE TOTAL

GAL. GASOLINE @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS - OIL - GREASE	

TOTAL LABOR	
TOTAL PARTS	
GAS, OIL, GREASE	
SPECIAL REPAIRS	
ENVIRONMENTAL CHARGES	
STATE TAX	
TOTAL AMOUNT	$271.58

AROCC-664-3 PRINTED IN U.S.A.

94 KW
RAM

RTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1	B99	Filter	
1	BF7587	"	
1	BR2044	solidifier	
10	15W40	Rotella	
1	tube	ultra grey	
	Misc grade 8 bolts		
4	4709	Step Bosses	
2	370003A	Seals	
3	7/16x8	hole gaskets	
4	DB1657B	[illegible]	
2	10R8501	injectors	
2	ASTR9422	bags brkt	
2	KW101	shoes	
1	HE4B	torque head	
1	HE4C	torque arm	
4	ASTR9422	bags	
1	HE4C	torque arm	
4	HE91	torque bushing	
2	Drive axle	bushings	
3	KW101	brkt.	
4	KW9C	bushings	
A/C	pressure	switch	
	NEW Coolant		
3	tubes grease		
	Misc electrical		
	Freon		

SPECIAL REPAIRS

TOTAL PARTS

ESTIMATE AMOUNT		PARTS LABOR	
ADD'L AUTH. AMT	TIME	BY	
ADD'L AUTH. AMT.			
ADD'L AUTH AMT.			
ESTIMATE TOTAL			

DATE 7-28-17

ADDRESS

CITY

PHONE WHEN READY ?

TIME RECEIVED AM PM

TIME PROMISED AM PM

TERMS

CUSTOMER'S ORDER NO.

YEAR	R NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
94	KW T800	5EK07018	RS634236	

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS	ORDER WRITTEN BY

LUBRICATE ☐ CHANGE OIL ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐

Service tractor - Replace #2 + #3 injectors
Replace 6 air bags, Change all fluids, seal
back rear end housing, replace two wheel seals.
on L,F + RR drive, Replace drive axle brakes
drums, replace torque arms on rear diff.
Replace elephant ears + radius arm bushings.
Lube truck
Repair A/c.

Paid CK # 178
7-28-17
Thanks

RETAIN PARTS ☐ DESTROY PARTS ☐

RECEIVED BY

GAL. GASOLINE	@	
QTS. OIL	@	
LBS. GREASE	@	
TOTAL GAS - OIL - GREASE		

TOTAL	
Press bushings	
TOTAL PARTS	
GAS OIL GREASE	
SPECIAL REPAIRS	
ENVIRONMENTAL CHARGE	
(Prior Credit)	
STATE TAX	
TOTAL AMOUNT	606991

AROCC-664-3 PRINTED IN U.S.A.

TS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1		A/C shift boot	
1		1/4" union + ferrel	
		Misc fittings [redacted]	
2		1/2 x #10 JIC	
10	PH/21310-300	hose	
2	PH/20821-10-10	fittings	
2	PH/V500P8-04	valves	
4	EP503005	exhaust flex	
5	EC50PLS	clamps	
2	EC50FBZ	"	
1	EP50Y tube	Y pipe	
1	EP50EL45208C	pipe	
1	EP50EL45209C	pipe	
		Misc tubing + welding supplies	
		misc bulbs + connectors	
		misc bolts + well nuts	

TOTAL PARTS 65492

ESTIMATE AMOUNT		PARTS LABOR
ADD'L AUTH. AMT.	TIME	BY
ADD'L AUTH. AMT.		
ADD'L AUTH. AMT.		
ESTIMATE TOTAL		

DATE 10-17-17

ADDRESS

CITY

PHONE WHEN READY ?

TIME RECEIVED A.M. P.M.

TIME PROMISED A.M. P.M.

TERMS

CUSTOMER'S ORDER NO.

YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
94	KW TP-800				

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS	ORDER WRITTEN BY

LUBRICATE ☐ CHANGE OIL ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐ $

Drain hydraulic & remove PTO & pump system
Plug off tank & install crossover for fuel
use. Replace Exhaust from muffler bottoms
forward past y. Had to reconfigure Y pipe to weld.
Install shift boot.
Check A/C, found loose wire at trinary
switch, works now.
Repair cab lights, plug in rear clearance lights
establish ground on markers, redo right hand
side panel with new bolts & well nuts (not seen)

RETAIN PARTS ☐ DEST

TOTAL LABOR	
TOTAL PARTS	
GAS, OIL, GREASE	
SPECIAL REPAIRS	
ENVIRONMENTAL CHARGES	
STATE TAX	
TOTAL AMOUNT	1634 92

GAL. GASOLINE @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS - OIL - GREASE	

AROCC-664-3
PRINTED IN U.S.A.

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
2	JBW 8217	tank weld	
1	M-[redacted]3659	stud	
3	K-161-793-22	strap lining	
3	K-161-93471	strap lining	
	Misc shop	Exp	
1	metric wheel	nut	

SPECIAL REPAIRS

TOTAL PARTS

ESTIMATE AMOUNT			PARTS LABOR
ADD'L AUTH. AMT.	TIME	BY	
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			
ESTIMATE TOTAL			

NAME

ADDRESS

CITY

DATE 11-9-17

TIME RECEIVED	TERMS
A.M. P.M.	
TIME PROMISED	CUSTOMER'S ORDER NO.
A.M. P.M.	

YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
94	KW T800		RS634236		

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTIONS	ORDER WRITTEN BY

LUBRICATE ☐ CHANGE OIL ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH ☐ $

Fuel tank leaking, pump fuel out in transfer tanks. Pull tank out, clean straps & brackets, pressure wash tank. Clean & use JB weld tank repair & JB Quik on tank. Really needs good tank. Install tank strap linings (NEW) & bracket linings (NEW). Reinstall tank. Refill from transfer tanks. Hook up lines & check. Seems ok right now.

Replace broken wheel stud, nut & cap on L.F. Steer axle. Adjust steer brakes.

RETAIN PARTS ☐ DESTROY PARTS ☐

TOTAL LABOR	
TOTAL PARTS	
GAS, OIL, GREASE	
SPECIAL REPAIRS	
ENVIRONMENTAL CHARGES	
STATE TAX	
TOTAL AMOUNT	760.08

GAL. GASOLINE @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS - OIL - GREASE	

AROCC-864-3 PRINTED IN U.S.A.

QTY.	PART NO.	DESCRIPTION	PRICE
1	5-677X	u-joint	
1	63-4-5221-1X	yoke	
1	128049	Nut	
1	1275[illegible]	seal	
	Hnu4 2044	nuts	
1	PA01250	condenser	
1	K275-6579	bracket	
1	K275-6516-2	bracket	
1	K275-[illegible]L2R	"	
3	K207-989	seal	
1	K275-6579R	bracket	
1	K275-6552	bracket	
3	K066-422	bushings	
1	K275-6552	bracket	
1	825 x 24.5	used wheel	
1	370003A	seal	
1	B99	A Hw	
1	BF7587	"	
10	15W40	oil	
1	A/C	Hose	
	misc nuts	misc Bolts	
	134A	Freon	

PARTS TOTAL

P.O. NO.	SUBLET REPAIRS	

TOTAL SUBLET REPAIRS

P.O. NO.	DATE
3698	

TIME RECEIVED ☐ AM ☐ PM

TIME PROMISED ☐ AM ☐ PM

YR.	MAKE	MODEL	COLOR	LICENSE NO.	MILEAGE	DEL. DATE
94	KW	T-800	Black			

BODY NO. | PAINT & TRIM NO. | V.I.N.

NAME | WRITTEN BY

ADDRESS

CITY | STATE | ZIP

EMAIL

PHONE WHEN READY ☐ YES ☐ NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION	
ESA	☐
Insurance	☐
Warranty	☐
Chargeback	☐
Sales	☐
Service	☐

LABOR CHARGE

MECH. NO	INSTRUCTIONS
	Replace front diff input yoke, seal, nut & u-joint
	Service tractor. Get passenger window working.
	A/C condenser bad (grill denser) Replace with T600 setup (vin #199626)
	Replace R.F steer wheel seal. Replace loose bolts in elephant ears.
	Clean ponodraft filter, loose & replace oring & make sure its tight.

☐ SAVE PARTS

☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS		
PARTS	LABOR	TOTAL

REVISED ESTIMATED/ADDITIONAL WORK		
PARTS	LABOR	TOTAL
AUTHORIZED BY		☐ IN PERSON ☐ BY PHONE
DATE	TIME	CALLED BY	PHONE NO.

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
SUBLET REPAIRS	
TAX	
TOTAL	2767.88

Thank You

002911

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
1	1022240	Sensor	
1	1125282	oriz	
3	CAC Clamp Kit		
2	CAC Hoses	1HE 8714	
1	BF7587	filter	
1	3P2044	positive	
2	9590HD	belts	
		block heater	
	Misc	shop	
1	used	pulley	
1	gallon	coolant	
2	tubes	grease	
		SPECIAL REPAIRS	
	TOTAL PARTS		
	ESTIMATE AMOUNT		

	TIME	BY	
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			
ADD'L AUTH. AMT.			
ESTIMATE TOTAL			

NAME

ADDRESS

CITY

DATE 1-11-18

TIME RECEIVED	TERMS
A.M. P.M.	
TIME PROMISED	CUSTOMER'S ORDER NO.
A.M. P.M.	

YEAR	TYPE OR MODEL	MOTOR NO.	SERIAL NUMBER	LICENSE NUMBER	ODOMETER
94	KW T800		RS634236		

REPAIR ORDER — LABOR INSTRUCTIONS

OPER. NO. | ORDER WRITTEN BY

LUBRICATE ☑ CHANGE OIL ☑ FLUSH TRANS. ☐ FLUSH DIFF ☐ WASH ☐ POLISH ☐ $

Service tractor
Install new ECM temp sensor.
Install new block heater. top off coolant
Replace 2 CAC hose + clamps + comp intake gasket.
Replace alt belts + pulley.

GAL. GASOLINE	@	
QTS. OIL	@	
LBS. GREASE	@	
TOTAL GAS - OIL - GREASE		

TOTAL LABOR	
TOTAL PARTS	
GAS, OIL, GREASE	
SPECIAL REPAIRS	
ENVIRONMENTAL CHARGES	
STATE TAX	
TOTAL AMOUNT	928.27

Flat bed
94 and

QTY.	PART NO.	DESCRIPTION	PRICE
1	3472185080	valve	
1	fitting	3/8	
4	8709	Airbags	
1	26-124	relay	
1	B99	filter	
1	BF7587	"	
10	15W40	oil	
4	4707	step boxes	
4	16570B	drums	
1	434100301	valve	
1	PA2705	filter	
2	tubes	grease	
	misc. shop supplies		

P.O. NO. 3558

DATE 3-14-18

TIME RECEIVED ☐ AM ☐ PM

TIME PROMISED ☐ AM ☐ PM

YR.	MAKE	MODEL	COLOR	LICENSE NO.	MILEAGE	DEL. DATE
95	KW T-800	tractor				

BODY NO | PAINT & TRIM NO. | V.I.N.

NAME | WRITTEN BY

ADDR

CITY | STATE | ZIP

EMAIL

PHONE WHEN READY ☐ YES ☐ NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION	LABOR CHARGE
ESA ☐	
Insurance ☐	
Warranty ☐	
Chargeback ☐	
Sales ☐	
Service ☐	

MECH. NO	INSTRUCTIONS
	Replace brakes, drums & air bags on trailer.
	Replace bad service valve + bypass air bag discharge.
	Service trailer. Troubleshooting time
	Service tractor, Replace relay in battery box for starter.
	Replace air filter. Replace Regulated check valve on air tank
	Check tach, Tach head going bad
	Check alternator. Charging fine. Guage loosing power to it. "

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
SUBLET REPAIRS	4 USED Steel wheels 4 USED Alum wheels
TAX	
TOTAL	3924.88

Thank You

PARTS TOTAL

P.O. NO.	SUBLET REPAIRS	
	TOTAL SUBLET REPAIRS	

☐ SAVE PARTS
☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS

PARTS	LABOR	TOTAL

REVISED ESTIMATED/ADDITIONAL WORK

PARTS	LABOR	TOTAL

AUTHORIZED BY | ☐ IN PERSON ☐ BY PHONE

DATE | TIME | CALLED BY | PHONE NO.

QTY.	PART NO.	DESCRIPTION	PRICE
4	HE91	bushings	
4	pivot	bushings	
1	AD-9	drier	

P.O. NO.	DATE
3629	6-26-18

TIME RECEIVED ☐AM ☐PM

TIME PROMISED ☐AM ☐PM

YR.	MAKE	MODEL	COLOR	LICENSE NO.	MILEAGE	DEL. DATE
1995	KW	T800				

BODY NO. | PAINT & TRIM NO. | V.I.N.

NAME | WRITTEN BY

ADDRES

CIT | STATE | ZIP

EMAIL

PHONE WHEN READY ☐YES ☐NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION	LABOR CHARGE
ESA ☐	
Insurance ☐	
Warranty ☐	
Chargeback ☐	
Sales ☐	
Service ☐	

MECH. NO	INSTRUCTIONS
	Replace rear tracking bushings
	Replace air drier with AD-9 drier
	Repair 3 air leaks
	Needs new fan hose sometime. (SEEPING)
	Tighten loose frame bolts.

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
Press SUBLET REPAIRS	
TAX	
TOTAL	1553.05

Thank You

PARTS TOTAL

P.O. NO.	SUBLET REPAIRS	
	TOTAL SUBLET REPAIRS	

☐ SAVE PARTS
☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS

PARTS	LABOR	TOTAL

REVISED ESTIMATED/ADDITIONAL WORK

PARTS	LABOR	TOTAL

AUTHORIZED BY | ☐ IN PERSON ☐ BY PHONE

DATE	TIME	CALLED BY	PHONE NO.

QTY.	PART NO.	DESCRIPTION	PRICE
	Hose for vibrator		
	Fittings + quick coupler for vibrator		
1	B99	filter	
1	BF7587	filter	
10	15W40	oil	
2	tubes	grease	
1	Q21-6005	speed sensor	
1	P926971	harness	
2	17590	belts	
	R134A o-rings + core		

PARTS TOTAL	483.41

P.O. NO.	SUBLET REPAIRS	
	TOTAL SUBLET REPA RS	

P.O. NO. 3684

DATE 8-16-18 TIME RECEIVED ☐AM ☐PM

TIME PROMISED ☐AM ☐PM

YR.	MAKE	MODEL	COLOR	LICENSE NO	MILEAGE	DEL. DATE
95	KW	T800				

BODY NO. | PAINT & TRIM NO. | V.I.N.

NAME | WRITTEN BY

ADDRE

CITY | STATE | ZIP

EMAIL

PHONE WHEN READY ☐ YES ☐ NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION	LABOR CHARGE
ESA ☐	
Insurance ☐	
Warranty ☐	
Chargeback ☐	
Sales ☐	
Service ☐	

MECH. NO | INSTRUCTIONS

Service tractor after checking for fluid in oil.
Pressure check and tighten leaking hoses.
Replace hose + fittings for vibrator to trailer.
Replace speed sensor + harness
Check A/C, air in system + low pressure.
Found High pressure charge port leaking + replace core.
Add dye to system, evac + charge

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
SUBLET REPAIRS	
TAX	
TOTAL	1113.41

Thank You

☐ SAVE PARTS
☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS

PARTS	LABOR	TOTAL

REVISED ESTIMATED/ADDITIONAL WORK

PARTS	LABOR	TOTAL

AUTHORIZED BY | ☐ IN PERSON ☐ BY PHONE

DATE | TIME | CALLED BY | PHONE NO.

QTY.	PART NO.	DESCRIPTION	PRICE
1	ONDH01020IRW	CAC	
1	CAC	clamp	
1	switch		
1	SR2000020	cut out switch	
2	1889 00MWW	seats	
1	5TL/29541	switch	
	steps ↗		
Misc wiring & hose & fittings			
1	7330		

PARTS TOTAL

P.O. NO.	SUBLET REPAIRS	

TOTAL SUBLET REPAIRS

P.O. NO. 3719

DATE 10-31-18

TIME RECEIVED ☐ AM ☐ PM

TIME PROMISED ☐ AM ☐ PM

YR.	MAKE	MODEL	COLOR	LICENSE NO.	MILEAGE	DEL. DATE
94	KW	T800				

BODY NO. PAINT & TRIM NO. V.I.N.

NAME

WRITTEN BY

ADDRESS

CITY STATE ZIP

EMAIL

PHONE WHEN READY ☐ YES ☐ NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION	LABOR CHARGE
ESA ☐	
Insurance ☐	
Warranty ☐	
Chargeback ☐	
Sales ☐	
Service ☐	

MECH. NO	INSTRUCTIONS
	Replace tractor seats.
	Replace A/c cutout switch & wire in A/c clutch switch
	Replace CAC cooler & clamp
	Repair steps.

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
SUBLET REPAIRS	
TAX	inc
TOTAL	3038.66

☐ SAVE PARTS

☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS

PARTS	LABOR	TOTAL

REVISED ESTIMATED/ADDITIONAL WORK

PARTS	LABOR	TOTAL

AUTHORIZED BY ☐ IN PERSON ☐ BY PHONE

DATE | TIME | CALLED BY | PHONE NO.

Thank You

QTY.	PART NO.	DESCRIPTION	PRICE
1	WB603-5404	washer bottle	
1	4954905	Sensor	
1	109139	TF550 Air Comp	

P.O. NO. 3933

DATE 9-27-1

TIME RECEIVED ☐ AM ☐ PM

TIME PROMISED ☐ AM ☐ PM

YR.	MAKE	MODEL	COLOR	LICENSE NO.	MILEAGE	DEL. DATE
94	KW	T800				

BODY NO. | PAINT & TRIM NO. | **V.I.N.**

NAME | WRITTEN BY

ADDR

CITY | STATE | ZIP

EMAIL

PHONE WHEN READY ☐ YES ☐ NO | RES. PHONE | WORK PHONE | EXT. | CELL

OPERATION		LABOR CHARGE
ESA	☐	
Insurance	☐	
Warranty	☐	
Chargeback	☐	
Sales	☐	
Service	☐	

MECH. NO	INSTRUCTIONS
	Dwight checked Peterbilt for sensor & washer pump, Ordered + gave parts to Justin
	Replace Air compressor on T800

PARTS TOTAL

P.O. NO.	SUBLET REPAIRS	

TOTAL SUBLET REPAIRS

☐ SAVE PARTS

☐ DISCARD PARTS

TERMS: CASH UNLESS PRIOR ARRANGEMENTS ARE MADE

ESTIMATED COSTS

PARTS | LABOR | TOTAL

REVISED ESTIMATED/ADDITIONAL WORK

PARTS | LABOR | TOTAL

AUTHORIZED BY | ☐ IN PERSON ☐ BY PHONE

DATE | TIME | CALLED BY | PHONE NO.

TOTAL LABOR	
TOTAL PARTS	
SHOP SUPPLIES	
GAS, OIL AND GREASE	
SUBLET REPAIRS	
TAX	
TOTAL	773.76

Thank You

16284

DATE IN	01-26-2021 A.M. P.M.
DATE PROMISED	A.M. P.M.
CUSTOMER'S ORDER NO.	
ORDER WRITTEN BY	
NAME	MC Freight
BUS. PHONE	EXT.
ADDRESS	
HOME PHONE	
CITY / STATE / ZIP	
CALL WITH EST.	☐ YES ☐ NO
IF OVER $	
CALL WHEN READY	☐ YES ☐ NO
YEAR, MAKE AND MODEL	1994 Kenworth T800
LICENSE NO.	17KRIT
MILEAGE	846,185
SERIAL NO./V.I.N.	#2 / 6342316
MECHANIC/TECHNICIAN	Aarow/Mike

SERVICES REQUESTED/DESCRIPTION OF WORK	AMOUNT
- Replaced #2 Drive Axle Thirdmember	
- Replaced Temp Sensors in Both Rear Ends	
- Tested Wiring To Sensors	
- Replaced Light Switch on Dash	
- Repaired Bad Wiring on #2 Drive Axle Sensor	
TOTAL LABOR	

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)		AMOUNT
1	RS404-3.50 RK	Rear End	
14 qt	75W90	OIL	
2		Axle Gasket	
1		Sealer	
1	8946K990	Switch	
2	K379-12	Sensor	
1	5-280X	U-Joint	
2		Post Connector	
2		Spade Connector	
2ft		Wire	
2		Cable Tie	

PAID BY ☐ CASH ☐ CHECK ☐ CREDIT CARD

MC VISA AMEX OTHER _____

CC NO. _____ EXP. _____

☐ ACCT. _____ TERMS _____

SIGNATURE

SAVE OLD PARTS ☐ YES ☐ NO

TOTAL PARTS	
TOTAL LABOR	
TOTAL SUBLET	
SERVICE CALL	
SHOP SUPPLIES	
MVI / DOT	
TAX	
TOTAL	2632.19

16768

DATE IN	4-30-21 A.M. P.M.
DATE PROMISED	A.M. P.M.
CUSTOMER'S ORDER NO.	
ORDER WRITTEN BY	
NAME	MC Freight
BUS. PHONE	EXT.
ADDRESS	
HOME PHONE	
CITY / STATE / ZIP	
CALL WITH EST. IF OVER $	☐ YES ☐ NO
CALL WHEN READY	☐ YES ☐ NO
YEAR, MAKE AND MODEL	KW T800
LICENSE NO.	17K RH
MILEAGE	877749
SERIAL NO./V.I.N.	#2 634236
MECHANIC/TECHNICIAN	TED Mike

SERVICES REQUESTED/DESCRIPTION OF WORK	AMOUNT
Replaced Air Compressor	
Replaced Air Compressor oil line	
Replaced Air line from D-2 To Air drier.	
Replaced Air Drier cart.	
Replaced leaking Safety Valve on wet Tank	
Replaced Drain Valve on wet Tank	
Completed Service	
Replaced Air filter	
TOTAL LABOR	

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1	LAF 3551 Air filter	
1	LFP 4005 Oil	
1	LFF 2749 Fuel	
36	Fleet oil	
1	Compressor	
1	O-ring	
1	Safety Valve	
1	PLT 107794	
1	TU12105 Valve Drain	
12	Hose	
1	90° Fitting	
3	Fitting	

PAID BY ☐ CASH ☐ CHECK ☐ CREDIT CARD

MC VISA AMEX OTHER _____

CC NO. _____ EXP. _____

☐ ACCT. _____ TERMS _____

SIGNATURE

SAVE OLD PARTS ☐ YES ☐ NO

TOTAL PARTS	
TOTAL LABOR	
TOTAL SUBLET	
SERVICE CALL	
SHOP SUPPLIES	
MVI / DOT	
TAX	
TOTAL	1230.86

16993

DATE IN	6-15-21 A.M. P.M.
DATE PROMISED	A.M. P.M.
CUSTOMER'S ORDER NO.	
ORDER WRITTEN BY	
NAME	MC Freight
BUS. PHONE	EXT.
ADDRESS	
HOME PHONE	
CITY / STATE / ZIP	
CALL WITH EST.	☐ YES ☐ NO
IF OVER $	
CALL WHEN READY	☐ YES ☐ NO
YEAR, MAKE AND MODEL	RW T800
LICENSE NO.	17K RIT
MILEAGE	890162
SERIAL NO./VIN	#2 634236
MECHANIC/TECHNICIAN	TED

SERVICES REQUESTED/DESCRIPTION OF WORK	AMOUNT
Truck will not crank.	
Found Bad connection @ CB in Battery Box. which controlls power to Cab.	
Tightened loose connections	
Ved Front end for popping. Spring pins and Bushings showing wear.	
Replaced Bad Ujoint on lower steering column & gear Box	
TOTAL LABOR	

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1	1-070 U-joint	

PAID BY ☐ CASH ☐ CHECK ☐ CREDIT CARD

MC VISA AMEX OTHER _____

CC NO. _____ EXP. _____

☐ ACCT. _____ TERMS _____

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.

SIGNATURE

SAVE OLD PARTS ☐ YES ☐ NO

TOTAL PARTS	
TOTAL LABOR	
TOTAL SUBLET	
SERVICE CALL	
SHOP SUPPLIES	
MVI / DOT	
TAX	
TOTAL	161.55

DATE IN	7-8-21 A.M. P.M.
DATE PROMISED	A.M. P.M.
CUSTOMER'S ORDER NO.	
ORDER WRITTEN BY	
NAME	MC Freight
BUS. PHONE	EXT.
ADDRESS	
HOME PHONE	
CITY / STATE / ZIP	
CALL WITH EST. IF OVER $	☐ YES ☐ NO
CALL WHEN READY	☐ YES ☐ NO
YEAR, MAKE AND MODEL	94 KW T800
LICENSE NO.	77K RIT
MILEAGE	894340
SERIAL NO./V.I.N.	#2 634236
MECHANIC/TECHNICIAN	TED

SERVICES REQUESTED/DESCRIPTION OF WORK	AMOUNT
Replaced #1 Axle Rear spring Bushings + pins.	
Completed Service	
Tightened Fan Belts	
TOTAL LABOR	

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
4	Threaded Pin	
1	LFP4005 Oil	
1	LFF 2749 Fuel	
38	Fleet Oil	
1	Washer Fluid	
2	Threaded Bushing	

PAID BY ☐ CASH ☐ CHECK ☐ CREDIT CARD

MC VISA AMEX OTHER _____

CC NO. _____ EXP. _____

☐ ACCT. _____ TERMS _____

SIGNATURE

SAVE OLD PARTS ☐ YES ☐ NO

TOTAL PARTS	
TOTAL LABOR	
TOTAL SUBLET	
SERVICE CALL	
SHOP SUPPLIES	
MVI / DOT	
Freight	
TAX	
TOTAL	8,21.23

INVOICE #:

PAGE: 1

CUSTOMER:

1

PRIMARY: 0 VEHICLE: 1994 KENWORTH T800
SALESMAN: LICENSE: 17KR1T MO MILEAGE: 895972
COLOR: BLACK ENGINE: 3406
VIN: RS634236
Fleet ID 2
INVOICE DATE: 07/14/21 DUE: 07/14/21

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
CLUTCH-FAN		1			
OUTSIDE REPAIR					
AIR HOSE TO FAN CLUTCH		1			
OUTSIDE REPAIR					
R&R FAN CLUTCH AND AIR LINE	88816	3.50			
S-8997					
ZIPTIES		4			
IMBRASS01					
SHOP SUPPLIES					
SS					

MERCHANDISE:
LABOR:
OTHER:
SALES TAX:
INVOICE TOTAL:

FUEL DESK 1504.47

TENDERED BY