QUAN.	PART NUMBER AND DESCRIPTION	PRICE	AMOUNT
	Replace Both Turbos		
	Replace 2 sections of		
	Exh. manifold. center		
	and rear -		
	Replace EGR Cooler + Valve.		
	New oil feed lines		
	for Turbo. New drain tubes.		
	Remove + clean CAC		
	and hot side CAC.		
	Deleted		
(SEE BACK)	TOTAL PARTS *		

ACCESSORIES

	TOTAL ACCESSORIES *		

CUSTOMER INFORMATION

		PHONE	DATE 8/ /22
		CUSTOMER'S ORDER NO.	DATE & TIME PROMISED / / ☐ A.M. ☐ P.M.
CITY		WRITTEN BY	
YEAR-MAKE-MODEL 2012 Ihc Pro Star #12	SERIAL NUMBER 537066 / MOTOR NUMBER	MILEAGE / LICENSE NO.	TERMS

OPER. NO.	INSTRUCTIONS			AMOUNT
	LUBE ☐	CHANGE OIL ☐	OIL FILTER ☐	
	DIFFERENTIAL ☐	AIR CLEANER ☐	TRANSMISSION ☐	
	ADJUST BRAKES ☐	WHEEL ALIGN. ☐	ROTATE TIRES ☐	
	WASH ☐	POLISH ☐	EMISSION SER. ☐	
	VIN# 3HSDJSJR3CN537066			

BILLING:

☐ C.O.D. ☐ Charge

☐ Guarantee ☐ Repeat

	GALLONS GAS	
	QUARTS OIL	
	LBS. GREASE	
	TOTAL GAS,OIL,GREASE *	

TOTAL LABOR *	
TOTAL PARTS *	
ACCESSORIES *	
GAS,OIL,GREASE *	
OUTSIDE WORK	
TIRES-TUBES	
SUB-TOTAL	
TAX	
* TOTAL DUE *	

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE ABOVE DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSES OF TESTING, INSPECTION AND DELIVERY. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE ABOVE DESCRIBED VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

IT IS UNDERSTOOD THAT YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO THE ABOVE DESCRIBED VEHICLE, OR ARTICLES LEFT THEREIN, IN CASE OF FIRE, THEFT, ACCIDENT OR OTHER CAUSE BEYOND YOUR CONTROL.

SIGNED DATE / /

AUTO REPAIR ORDER

MADE IN U.S.A.