VEHICLE ID	MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
3GCUKREC4HG467951	144900	144900	12/10/22 07:43	12/13/22	63802

VEHICLE DESCRIPTION		TAG NO.	STATUS
2017 CHEVROLET SILVERADO		00030	COMPLETE

CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS
114167		135.0					Cash

PHONE 1	PHONE 2	PHONE 3	STOCK NO.	SERV. ADV.	ENG/TRANS

YOU MAY RECEIVE A EMAIL SURVEY FROM GM PLEASE MARK IT 100% SATISFIED, WE NEED YOUR INPUT. IF FOR ANY REASON YOU CAN'T MARK IT 100%
PLEASE CALL ME @ 334-6914
THANK YOU, JOSH MOORE SERVICE MANAGER

MY GM REWARDS
EARN POINTS FOR NEXT SERVICE!
SIGN UP TODAY!
WWW.MYGMREWARDS.COM

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
A	R		A15		Customer	

Concern	CUSTOMER STATES trans has a shudder while driven and up hills check and advise customer states check engine light has been on for awhile
Cause	test drive. torque converter malfunction. transmission has hard shifts and fluid pump whine on accel. fluid burnt. internal transmission damage
Correction	replaced transmission assembly with a GM SRTA. flush cooler and lines. install updated bypass valve. program new tcm and reset adapts. gm srta transmission has a 3 year 100000 mile warranty parts and labor

Part Number	Description	Qty.	Unit Price	Ext. Price
13579649	SEAL	1		
13579648	SEAL	1		
19383805	CONDENSER	1		
19421245	FLUID	10		
20779889	CLAMP	1		
15077362	SEAL	1		
15035747	SEAL	1		
15796802	SEAL	1		
23135703	SEAL	1		
86774933	VALVE	1		
24279064	TRANSMISSION	1		
	CLEAN CORE	1		
	DIRTY CORE	-1		

pd. 6288.73 cc (handwritten)

Parts Total

Line Total...

B	+	R		A15		Customer	

VEHICLE ID	MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
3GCUKREC4HG467951	144900	144900	12/10/22 07:43	12/13/22	63802

VEHICLE DESCRIPTION		TAG NO.	STATUS
2017 CHEVROLET SILVERADO		00030	COMPLETE

LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS
	135.0					Cash

PHONE 1	PHONE 2	PHONE 3	STOCK NO.	SERV. ADV.	ENG/TRANS

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
B +	Continued					

Concern CUSTOMER STATES request to replace trans cooler

Cause customer request new transmission cooler. part of condenser (combicooler)

Correction evac and replace condenser. recharge a/c system repair has a two year unlimited mile warranty

Line Total...

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
C +	9900536		A15		Warranty	

Concern CUSTOMER STATES brake pedal hard to push at times

Cause ABS activates while driven at slow speeds and brake pedal gets hard. test vacuum source to brake booster. vacuum pump failure. #N182202780-02: Special Coverage - Brake Assist Decreased Due to Vacuum Loss

Correction replaced vacuum pump and recheck.

Totals

	Amount
Parts	
SalesTax	
Labor	
Total Amount Due	

Amount Due $6,288.73