DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-JUL-2022	83	30-NOV-2015	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	**SHIP VIA**	**FAIL DATE**	**ENGINE SERIAL NO.**	**CPL NO.**	**EQUIPMENT MODEL**
88405		31-MAR-2022	79799029		579
REF. NO.	**SALES PERSON**	**PARTS DISP.**	**MILEAGE/HOURS**	**PUMP CODE**	**UNIT NO.**
53340	KS914		486818 / 0		83

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT

OSN/MSN/VIN 2XPXD49X9GM277056

TAX EXEMPT NUMBERS:

TOTAL AMOUNT: US $ 37,924.42

DATE_____

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-JUL-2022	83	30-NOV-2015	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	**SHIP VIA**	**FAIL DATE**	**ENGINE SERIAL NO.**	**CPL NO.**	**EQUIPMENT MODEL**
88405		31-MAR-2022	79799029		579
REF. NO.	**SALES PERSON**	**PARTS DISP.**	**MILEAGE/HOURS**	**PUMP CODE**	**UNIT NO.**
53340	KS914		486818 / 0		83

CK ERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
2XPXD49X9GM277056						
	1	4952629	THERMOSTAT	CECO		
	1	3689755	GASKET,LUB OIL CLR HSG	CECO		
	1	FREIGHT	FREIGHT CHRGS SERVICE	C1-FREIGHT		
	1	NOW	NOW CERTIFICATE	CERTIFICATES		
	6	3678506	SCREW,HEX FLANGE HEAD CAP	CECO		
	1	3163087	LUBRICANT	CECO		
	1	3824510	CLEANER,ELC CONTACT	CECO		
	1	3689465	PULLEY,IDLER	CECO		
	1	5550059	KIT,SPEED SENSOR	CECO		
	3	3163075	PAINT	CECO		
	1	4988280	GASKET,HYDRAULIC PUMP	CECO		
	1	2881766	KIT,LOWER ENGINE GASKET	CECO		
	1	4298629	CAMSHAFT	CECO		
	1	5579467	KIT,ROCKER LEVER	CECO		
	52	C891001QT	PB 1 S GN2 15W40 BULK QT	VALVOLINE		
	1	FREIGHT	FREIGHT CHRGS SERVICE	C1-FREIGHT		
	1	D84-1000-6122310	BELT	C1-NSPART2		
	1	D84-1000-6061620	BELT	C1-NSPART2		
	1	F37-6017	A/C DRIER	C1-NSPART3		
	1	5680039RX	PUMP,LUBRICATING OIL	DRC		
	1	3685865D	KIT, LUBE PUMP	CLEAN		
	-1	3685865D	KIT, LUBE PUMP ISX	DIRTY		
	1	308925-20	CLUTCH	C1-NSPART4		
	1	K2468	CLUTCH KIT	C1-NSPART3		

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-JUL-2022	83	30-NOV-2015	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	**SHIP VIA**	**FAIL DATE**	**ENGINE SERIAL NO.**	**CPL NO.**	**EQUIPMENT MODEL**
88405		31-MAR-2022	79799029		579
REF. NO.	**SALES PERSON**	**PARTS DISP.**	**MILEAGE/HOURS**	**PUMP CODE**	**UNIT NO.**
53340	KS014		486818 / 0		83

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
OSN/MSN/VIN		2XPXD49X9GM277056					
1		1	RESUFACE	FLYWHEEL			
1		1	6306LLUA1C3/2E	PILOT BEARING			
3		3	4374074	SCREW,TWELVE POINT CAP			
1		1	3688012	TUBE,LUB OIL DRAIN			
1		1	4928594	SENSOR,PRESSURE			
1		1	3683144	CLAMP,V BAND			
1		1	5406049RX	KIT,EXH RCN VALVE			
1		1	3686640D	KIT, EGR VALVE			
-1		-1	3686640D	KIT, EGR VALVE ISX			
1		1	WF2127	PAC, WF			
2		2	83008GA	SHOCK ABSO RBER			
1		1	F50-6242-1475	HARDLINE A SSY HVAC DIS			
1		1	CM10045867	SEAL KIT DRIVE AXLE			
1		1	RXGF4709ES2G	BRAKE SHOE KIT 20K LINING			
1		1	5317106RX	MODULE,ELECTRONIC CONTRO			
1		1	5290170D	ECM, CM2350A			
-1		-1	5290170D	ECM, CM2350A			
2		2	ENTER PART #	FLANGE GASKET			
2		2	02-02737PLUS-2	F SHOCK			
1		1	K049199BXW	AIR DRIER			
1		1	CLT012P	LINE			

PARTS:
PARTS COVERAGE CREDIT:
TOTAL PARTS: 29,665.02

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
07-JUL-2022	83	30-NOV-2015	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	**SHIP VIA**	**FAIL DATE**	**ENGINE SERIAL NO.**	**CPL NO.**	**EQUIPMENT MODEL**
68405		31-MAR-2022	79799029		579
REF. NO.	**SALES PERSON**	**PARTS DISP.**	**MILEAGE/HOURS**	**PUMP CODE**	**UNIT NO.**
53340	KS914		486818 / 0		83

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT

OSN/MSN/VIN 2XPXD49X9GM277056

COMPLAINT CUSTOMER ADVISED THAT UNIT IS USING 1 1/2 GALLONS OF COOLANT A DAY AND ALSO HAS AN CHECK ENGINE LIGHT.

CAUSE CYLINER HEAD / LINERS

CORRECTION BROUGHT UNIT INTO THE SHOP FOR USING COOLANT WE THEN CHECKED THE EGR COOLER NO ISSUES FOUND WE WORKED WITH TECH SUPPORT AND REMOVED THE CYLINDER HEAD. WE PRESSURE TESTED THE HEAD ADVISED THE CUSTOMER WE ALSO NEEDED TO INSPECT THE LINERS. CUSTOMER WANTED QUOTE TO PERFORM NOW OVERHAUL. WE ADVISED THE FLYWHEEL HOUSING WAS LEAKING. WE THEN REMOVED THE HOOD, RADIATOR, DRIVELINE AND PULLED THE ENGINE AND TRANSMISSION. WE RESEALED THE FRONT STRUCTURE AND REAR STRUCTURE WE THEN INSTALLED NEW PISTONS LINERS AND ALL COMPONENTS WERE INSPECTED PER THE NOW. WE INSTALLED UNIT BACK IN CHASSIS WITH NEW CLUTCH AND THEN REASSEMBLED TO SPEC. WE FOUND THE UNIT HAD FAULTS FOR EGR VALVE AND ECM FAILURE GOT OK TO REPLACE BOTH RAN ENGINE RAN GOOD. WE THEN FOUND IT WOULD NOT BUILD AIR AND THE REAR WHEELSEAL WAS LEAKING ON THE RIGHT REAR AXLE. WE FOUND THE AIR DRYER WAS NOT ALLOWING AIR TO THE LEVELING VALVE REPLACED THE DRIER. WE THEN REMOVED AND REPLACE THE WHEEL SEAL AND BRAKE ON THE RIGHT REAR DUE TO BRAKES WERE CONTAMINATED. WE ALSO REPLACED THE STEER AXLE SHOCKS DUE TO LEAKING. WE RAN THE UNIT NO OTHER ISSUES FOUND AT THIS TIME. BILLABLE

COVERAGE REMARK 3/29/22 11AM DR: UNIT HERE. AWAITING TECH FOR DIAG.

1		CSSNA ISX12N PRO&ELITE	ISX12N PRO & ELITE OVERHAUL		
1		GUARDIAN INSP	GUARDIAN FREE VISUAL INSPECTION		
1	1	5658301RX	HEAD,CYLINDER	DRC	
1	1	4298235D	HEAD, CYLINDER	CLEAN	
-1	-1	4298235D	HEAD, CYLINDER	DIRTY	
1	1	FREIGHT	FREIGHT CHRGS SERVICE	C1-FREIGHT	
1	1	5693737	KIT,OVERHAUL	CECO	
1	1	4955831	KIT,OIL COOLER	CECO	