[redacted]

RO: 11457P
Invoice: 12756P
Date: 06/22/2024
Serial Number

[redacted]

Cond | Description | Quantity

RO Open Date: 03/01/24

001 LS190 SKIDSTEER
D LS190 SKIDSTEER SN:LMU018465 OIL LEAK IN BELLY. CHECK PARK BRAKE?. INSTALL NEW FEMALE COUPLER ON FRONT (LEAKING). CUSTOMER BROUGHT IN. NO BUCKET OR SIDE PANELS.
F WASHED. PULLED IN TO SHOP. TOOK SIDE SHIELDS OFF CAB. PULL BELLY PAN OFF. PULLED FLOOR PAN OUT OF CAB. UNBOLTED CAB. UNHOOKED HEATER LINES OFF BACK OF CAB. TIPPED CAB. FOUND OIL UNDER HYDRAULIC TANK. TOPPED OFF HYDRAULIC OIL .LOWERED CAB BACK DOWN. TOOK TO WASH BAY TO WASH OUT BELLY OF SKID STEER. LET SIT OVER NIGHT. FOUND OIL BACK UNDER HYDRAULIC TANK. FOUND SUCTION LINE CLAMPS WERE LOOSE, TIGHTENED DOWN CLAMPS. WASHED OUT BELLY. LET SIT OVER NIGHT. FOUND NO MORE LEAKS. PULLED BACK INTO SHOP. PUT FLOOR AND SIDE CAB PANELS BACK ON. TESTED FOR LEAKS. NO LEAKS FOUND. PUT BELLY PAN BACK ON. CUSTOMER WANTS QUOTE TO REPAIR/REPLACE MISSING BRAKE LINKAGE AND REPAIR BOOM LOCK?? BRAKE LINKAGE: ORDERED ALL LINKAGE FOR LH SIDE BRAKE. FOUND LH SIDE ARM WAS BROKEN ON HYRDOSTAT AND SPRING MISSING. REPLACED ARM & SPRING.. BOOM LOCK: PULLED PLUG OUT OF VALVE BODY AND INSTALLED NEW BOOM LOCK SELENOID. RAN UNIT AND FOUND IT DIED AFTER A WHILE. TESTED AND FOUND OIL PRESSURE SENSOR BAD. REPLACED SENSOR-RAN OK. RETURNED TO SERVICE.
CL L CUSTOMER LABOR
LABOR TO REPAIR CUSTOMER EQUIPMENT
P 87741499 COUPLING
P MISC
COTTER PIN
P 86541448 ROD
P 84151310 SOLENOID
P FREIGHT FREIGHT
P 86511561 SCREW CAP
P 9844882 LEVER
P 87305 NUT JAM
P 86617977 PIN SPLIT
P MC30548 LOCTITE
P 9847720 SWITCH PRE
P FREIGHT FREIGHT

M SHOP SUPPLIES

[redacted]

THANK YOU FOR YOUR BUSINESS!!!

[redacted]

THE PURCHASER MUST BE ENGAGED IN FARMING OR RANCHING AND CERTIFIES THAT THIS EQUIPMENT AND/OR PARTS WILL BE USED ONLY IN FARMING OR RANCHING.

All purchases made during the month are due on the 10th of the following month. If not paid by the 25th of the month, there will be a service charge as follows: Balance under $300.00, 1.75% per month, 21% annual rate. Over $300.00 and under $1000.00, 1.5% per month, 18% annual rate. $1000.00 and up, 1.2% per month, 14.45% annual rate. These percentage rates will be added each month until paid in full.

ALL CLAIMS AND RETURNS MUST BE ACCOMPANIED BY THIS BILL.

Signature: _____

[redacted]

TOTAL	5739.33

CUSTOMER REPRINT

51964

SALES REP	PURCHASE ORDER NO.	R.O. NO.	P.T. NO.	INVOICE DATE	TIME	INVOICE NO. REPRINT
TL			47052	02/09/2024	10:06 AM	43563P

QUANTITIES ORDERED	QUANTITIES B/O	QUANTITIES SHIPPED		PART NUMBER	DESCRIPTION	VENDOR / BIN LOC.	PRICES
1		1	N	86641461	COUPLING	NEW	
				CALL WHEN IT COMES IN			
1		1	N	87741863	CUSHION S	NEW	
1		1	N	87741862	CUSHION S	A-016A	
1		1	N	FREIGHT	FREIGHT		

CHARGE

51964

690.83

THANK YOU FOR YOUR BUSINESS
HAVE A NICE DAY!!!

SHIP
VIA

THE PURCHASER MUST BE ENGAGED IN FARMING OR RANCHING AND CERTIFIES THAT THIS EQUIPMENT AND/OR PARTS WILL BE USED ONLY IN FARMING OR RANCHING.

All purchases made during the month are due on the 10th of the following month. If not paid by the 25th of the month, there will be a service charge as follows: Balance under $300.00, 1.75% per month, 21% annual rate. Over $300.00 and under $1000.00, 1.5% per month, 18% annual rate. $1000.00 and up, 1.2% per month, 14.45% annual rate. These percentage rates will be added each month until paid in full.

ALL CLAIMS AND RETURNS MUST BE ACCOMPANIED BY THIS BILL.

Signature: _____

PARTS	
FREIGHT	
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	**690.83**

Copyright (c) 2019 HBS Systems