

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4955		RW4955P003332	24370W	TRACTOR

0100Q -F-0000711 Retail

COMPLAINT:

2- CAMSHAFT, REPLACE

CORRECTION:

2- CAMSHAFT, REPLACE

TOOK APART SPLIT TRACTOR TOOK ENGINE APART PULLED CAMSHAFT ASSEMBLED NEW PUT ENGINE AND TRACTOR TOGETHER RAN AND CHECKED IT IS OK.

Service Accessories

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
26H72		1.00				N
AR61533	PLUG	1.00				N
AR61589	PLUG	1.00				N
R57636	WASHER	1.00				N
R57637	SEALING WA	1.00				N
R66452	Connecting Rod Bolt	2.00				N
R73599	O-RING	1.00				N
RE27839		1.00				N
RE32442	SEAL	1.00				N
RG22421		1.00				N
U12037	O-RING	1.00				N

Labor:	Parts:	OL&M: \$0.00	Misc: \$0.00	Sub-Total:
--------	--------	--------------	--------------	------------

/10090130S-F-0018932 Retail

COMPLAINT:

3- CHECK DOOR

CORRECTION:

CONTINUED ON NEXT PAGE->

JOHN DEERE 4955

Meter:

Serial Number:

RW4955P003332

/10090130S-F-0018932 Retail
3- CHECK DOOR

DOOR PINS FROZEN IN LUBED UP TRIED TO REMOVE THEY WERE STUCK. FINALLY GOT
CLEANED ALL RUST FROM HINGES. INSTALLED NEW BUSHINGS AND PUT NEVER SEIZ
CHECKED DOOR OPERATION IT IS OK.

Part Number	Description	Quantity
24H1302	WASHER	2.0
34H247	SPRING PIN	2.0
R135428	PIN FASTEN	2.0
R65570	BUSHING	4.0
Labor:	Parts:	OL&M:
		Misc:

5581W1 -F-0005694 Retail
COMPLAINT:
5- U-JOINTS, REPLACE

CORRECTION:
5- U-JOINTS, REPLACE

CLEANED DRIVE SHAFT REMOVED U-JOINTS INSTALLED NEW.

Part Number	Description	Quantity
AR69444B	GALLON HYGARD HYDRAULIC OIL	4.00
RE37355	KIT	2.00
Labor:	Parts:	OL&M:
		Misc:

/DETAIL -F-0018697 Retail
COMPLAINT:

SERVICE INVOICE

Invoice Number: 300101150
 Invoice Date: 8/11/2005
 Location: 03
 Work Order Number: 300101150
 Payment Type: Account
 Page: 1 of 3

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4955	238329	RW4955P003332	24370W	TRACTOR

01-2030AQ -9 Retail

COMPLAINT:

CRANKSHAFT OIL SEAL AND WEAR SLEEVE, REAR, REPLACE

CORRECTION:

LOOK OVER SOME AND CALL IF OTHER REPAIRS ARE NEEDED!!
 2030W-MAIN BEARING CLEARANCE, CHECK WITH PLASTIGAGE (Does No
 5525A-TRACTION CLUTCH, R&R
 1515A-FRONT END AND ENGINE FROM CLUTCH HOUSING SEPARATION
 4010E-BATTERY BOX, R&R OR REPLACE
 4010B-BATTERY(S), R&R OR REPLACE
 8020A-HOOD, R&R
 1515A-FRONT END AND ENGINE FROM CLUTCH HOUSING SEPARATION
 4010E-BATTERY BOX, R&R OR REPLACE
 4010B-BATTERY(S), R&R OR REPLACE
 8020A-HOOD, R&R
 4010E-BATTERY BOX, R&R OR REPLACE
 4010B-BATTERY(S), R&R OR REPLACE
 4010B-BATTERY(S), R&R OR REPLACE
 8020A-HOOD, R&R
 Remove: Seal housing Oil seal and wear sleeve
 Reinstall to specifications.
 CHECK TRACTION CLUTCH AND REPLACE C2 HUB, RESEAL PISTONS.
 R&R INPUT PLANETARY, DISASSEMBLE AND INSPECT ALL IS OK
 FOUND ONE BROKEN RING ON CLUTCH SHAFT
 INSPECT TRANS OIL PUMP, IS OK
 R&R FRONT PTO SHAFT AND RESHIM

Labor:	Parts:	OL&M:	Misc:	Sub-Total:
--------	--------	-------	-------	------------

02-7025F -9 Retail

COMPLAINT:

DRAFT SHAFT SEALS, REPLACE

CORRECTION:

CONTINUED ON NEXT PAGE->

Make/Model:

JOHN DEERE 4955

Meter:

238329

Serial Number:

RW4955P003332

Eq ID

24370

02-7025F -9 Retail

Labor:

03-NOSPG -9 Retail

COMPLAINT:

RESEAL INJECTION PUMP GOV HOUSING MOUNT

CORRECTION:

RESEAL FUEL SHUTOFF SHAFT

RESEAL FUEL SHUTOFF SHAFT

Labor:

04-NOSPG -9 Retail

COMPLAINT:

SERVICE BATTERYIES AND CLEAN CABLES

CORRECTION:

FILL BATTERIES WITH WATER AND CHARGE AND TEST, CLEAN CABLES

FILL BATTERIES WITH WATER AND CHARGE AND TEST, CLEAN CABLES

Labor:

05-4020D -9 Retail

COMPLAINT:

STARTER, R&R OR REPLACE

CORRECTION:

CHECK CRANKING SPEED BEFORE REPLACIGN STARTER, 130RPM

CHECK SPEED AFTER REPLACING STARTER 190RPM

Make/Model:

JOHN DEERE 4955

Meter:

238329

Serial Number:

RW4955P003332

Work

Eq

243

05-4020D -9 Retail

CHECK CRANKING SPEED BEFORE REPLACIGN STARTER, 130RPM
CHECK SPEED AFTER REPLACING STARTER 190RPM

Labor:

OL&M:

PARTS Retail
COMPLAINT:
CONVERSION PARTS

CORRECTION:
CONVERSION PARTS

Labor:

OL&M:

Customer PO No:

Tax Exempt No:

Advisor:

*** DOCUMENT COPY ***

Inspect & Repair Now. Be Ready Later. Save on equipment inspections & get a FREE inspection with every Cr

ATTENTION: Part(s) values for this invoice have changed

Invoice Number: 14
Invoice Date: 2/7/12
Location:
Work Order Number:
Payment Type:
Page:

Make/Model:

JOHN DEERE 4955

Meter:

Serial Number:

RW4955P003332

Eq ID:

24370W

Fleet No:

TRACTOR

/10060080S-F-0018312 Retail

COMPLAINT:

2- GEARSHIFT REPAIR

CORRECTION:

TAKE APART PULL SHIFTER ASSEMBLY. TAKE APART AND REPLACE LEVER PUT BACK TOGETHER. INSTALL IN TRACTOR AND ADJUST.
Service Accessories

Part Number

11M7082

Description

COTTER PIN

Quantity

1.00

List PriceNet PriceExtended PriceTax

R105814

2.00

RE20884

1.00

Labor:

/10090091S-F-0018345 Retail

COMPLAINT:

6- A/C SYSTEM, R&R

CORRECTION:

R&R A/C belt.

DIAGNOSE AC FOUND IT NEEDED RETROFITTED. TALKED TO MARVIN AND HE SAID TO FIX IT. TAKE APART SYSTEM AND FLUSH OUT. TAKE APART, REPLACE CAB CORNER LINES. PUT BACK TOGETHER AND PUT REST OF SYSTEM TOGETHER. EVACUATE AND CHARGE. RUAN AND CHECK ALL IS OKAY.

Part Number

03M7193

Description

BOLT

Quantity

8.00

List PriceNet PriceExtended PriceTax

14M7274

10MM HEX NUT

8.00

24H1219

WASHER

8.00

AR58278

LINE

1.00

AR65755

A/C LINE

1.00

H77698

15" TIE BAND

25.00

CONTINUED ON NEXT PAGE.

JOHN DEERE 4955

Meter:

Serial Number:

RW4955P003332

/10090091S-F-0018345 Retail

R10093	O-RING	3.00
R113050	O-RING	1.00
R117977	O-RING	4.00
R33259	WASHER	2.00
R57636	SEALING WA	1.00
R57637	CAB REC. FILTER - Foam	1.00
R65450	INSULATOR	1.00
R77896	MANIFOLD	2.00
RE10981	A/C VALVE R.L.	1.00
RE10982	ELECTRICAL	1.00
RE12362	AIR FILTER	1.00
RE12793	EXPANSION VALVE	1.00
RE206757	LINE	1.00
RE33514	COMPRESSOR	1.00
RE57343	O-RING	1.00
RE62129	O-RING	2.00
SE501464	12oz. R-134A Refrigerant	1.00
T143166	1 Qt. Secondary A/C System Flush	3.00
T143169	AG/CCE GREEN SPRAY PAINT	2.00
TY15949	Brake & Parts Cleaner	1.00
TY25600	134A REFRIG W/DYE	1.00
TY25624		2.00
TY26101		
3012UV		

Miscellaneous

Description

Quantity

List

Make/Model:

JOHN DEERE 4955

Meter:

Serial Num

RW4955P

/10020100 -F-0018585 Retail

COMPLAINT:

1-INFRAFRAME OVERHAUL

CORRECTION:

BRANCH #3

Drain all fluids.

Remove engine.

Tear down and inspect.

Install all necessary parts.

Reinstall engine.

Fill and check all fluid levels.

Start and run.

10-020-060

TEAR DOWN CLEAN AND REBUILD ENGINE. PUT BACK TOGETHER, RUN ON D

Service Accessories

<u>Part Number</u>	<u>Description</u>
11M7083	COTTER PIN (3MM X 50)
12H304	3/8" LOCK WASHER
14H1086	3/4 FINE SLOTTED NUT
19H1800	CAP SCREW
19H2128	CAP SCREW
19H2549	3/8" X 1- 7/8" GR5 BOLT
19H2639	Cap Screw
19H3217	
24H1305	WASHER
24H1682	WASHER
34H329	SPRING PIN
A4847R	WASHER
AR103220	STRAINER
AR48675	180 DEG. THERMOSTAT

JOHN DEERE 4955

Meter:

Serial Number:

RW4955P003332

/10020100 -F-0018585 Retail

AR61533	PLUG	
AR61589	PLUG	
AR69444B	GALLON HYGARD HYDRAULIC OIL	
AR72337	CAP	
AR80652	Primary Air Filter Element (Outer)	
AR86603	4" RAIN CAP	
AR86745	FUEL FILTER	
AR94510	HYD.-TRANS. FILTER	
JD5929	SMV EMBLEM	
R102882	SHIELD	
R102981		
R192450		
R34733	SEALING WA	
R50386	OIL TUBE	
R51936	SEALING WA	
R54500	SCREW	
R62952	OIL TUBE	
R63845	WASHER	
R66452	Connecting Rod Bolt	
R73189	V-BELT	
R73599	O-RING	
R76371	RADIATOR H	
R78202	HYD. Pump Drive Cushion	
R87732		
R87733		

Make/Model:

JOHN DEERE 4955

Meter:

Serial Number

RW4955P003

/10020100 -F-0018585 Retail

R88353	
R88995	HOSE
R93616	HOSE
R94447	SUCTION HOSE
RE15018	GASKET
RE166242	PULLEY WIT
RE39103	CLAMP
RE41286	FILLER CAP
RE41942	
RE524630	BELT SET
RE57394	ENGINE OVE
RE63291	OIL FILTER (DZ101880)
RG30466	ENGINE OIL
TY22062	KIT
TY22466	2.5 GAL HY-GARD OIL
TY22467	#12 HOSE CLAMP
TY22472	CLAMP
TY22475	CLAMP
TY25624	CLAMP
TY26101	AG/CCE GREEN SPRAY PAINT
TY26576	Brake & Parts Cleaner
TY26661	2.5 GAL. COOL-GARD II PRE-MIX COOLANT
TY6382	1 Gal. BREAK-IN PLUS N/A 10W-30 OIL
U17409	LUBRICANT
07485	O-RING
	ROLOC PAD

Miscellaneous

Description

Quantity

Make/Model:

JOHN DEERE 4955

Meter:

/10020100 -F-0018585 Retail
3750

Labor:

JD FREIGHT

Parts:

OL&M:

/10110060S-F-0018364 Retail
COMPLAINT:
3- AXLE SEAL

CORRECTION:
TAKE APART TAKE APART CLEAN AND RESEAL RIGHT HAND AXLE. PUT BA
CHECK. ALL IS OKAY.

Part Number
R109808

Description
BUSHING

R56757

O-RING

R73635

BUSHING

R79996

PIN

R87047

RING

RE154869

SEAL

RE208256

SEAL

RE70230

SEAL

TY26101

Brake & Parts Cleaner
LUBRICANT

TY6382

Labor:

Parts:

OL&M:

1708D1 -F-0004379 Retail
COMPLAINT:
4-PIVOT PIN BUSHINGS, R&R

CORRECTION:

SERVICE INVOICE

Invoice Number:
 Invoice Date:
 Location:
 Work Order Number:
 Payment Type:

Make/Model:

JOHN DEERE 4955

Meter:

Serial Number:

RW4955P003332

Eq ID:

24370W

Fleet No:

TRACTOR

1708D1 -F-0004379 Retail

REPLACE BOTH INNER TIE RODS. TAKE APART, PULL AXLE AND REPLACE PIVOT PINS AND BUSHINGS. REINSTALL AXLE AND PUT BACK TOGETHER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price
RE12325	TIE ROD EN	2.00			
Labor:	Parts:	OL&M:	Misc:	Sub-Total:	

SERVICE -F-0010594 Retail
 COMPLAINT:
 5- SERVICE

CORRECTION:

- * Change oil & oil filter
- * Change fuel filters
- * Change outer air filter
- * Change cab & fresh air filter
- * Change transmission & Hyd oil & filters
- * Check all fluids

CHANGE HYDRALIC OIL AND FILTERS
 CHANGE OIL IN FRONT DIFF.
 GREASE FRONT END



CONTINUED ON NEXT PAGE-

IP
 R44302
 22328

JOHN DEERE 4955

Meter:

2702

Serial Number:

RW4955P003332

Eq ID

2437

/30SERIESINSPECTIONV Retail

COMPLAINT:

01 ULTIMATE PERFORMANCE INSPECTION VINTAGE ROW CROP TRACTORS
30 SERIES ONLY

CAUSE:

inspected machine.

CORRECTION:

ENGINE
COOLING SYSTEM
ELECTRICAL
POWER TRAIN
STEERING & BRAKES
HYDRAULIC SYSTEM
OPERATOR'S STATION

Inspected machine.

1 hour.

Had trouble with machine on the dyno since it over heated and was smoking from under the cab. Also had trouble with the forklift to use the PTO on dyno.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>
AR80652	Primary Air Filter Element (Outer)	1.00
AR80653	Secondary Air Filter Element (Inner)	1.00
AR86745	FUEL FILTER	1.00
AR94510	HYD.-TRANS. FILTER	1.00
DZ118156	Engine Oil Filter (RE57394)	1.00
IPSKIT1	OIL SCAN KIT	1.00
R44302	7" TIE BAND	72.00
TY22328	5/8" HEATER HOSE	168.00
TY22465	#10 HOSE CLAMP	4.00

Meter:	Serial Number:	Eq ID
2702	RW4955P003332	2437

/30SERIESINSPECTIONV Retail

TY26186	Wire Loom, 3/8" (per foot)	7.00
TY26188	Wire Loom, 1/2" (per foot)	3.00
TY26190	Wire Loom, 3/4" (per foot)	4.00
TY26632	ELECTRONIC CONTACT CLEANER	1.00
TY27048	14 AWG RED WIRE 15FT	1.00
TY27057	18 AWG WHITE WIRE 30FT	1.00
TY27058	18 AWG GREEN WIRE 30FT	1.00
TY27072	"1/4"" Black Heat Shrink Tubing	2.00

Miscellaneous

3970	<u>Description</u>	<u>Quantity</u>
3970	Comments: Inspection discount	1.00
	Comments: Labor discount	1.00

Labor:

Parts:

OL&M:

Misc:

/GEN-HITCH Retail

COMPLAINT:

02 General hitch repairs.

- Check hitch make sure 3 point etc works

CAUSE:

Wires under the cab were torn not letting hitch operate.

CORRECTION:

Checked hitch operation and found the hitch would not raise, checked machine for codes and found code 41. but machine would not enter calibration. Checked wires and found wires under the cab were torn, had to remove wires. Tried to calibrate hitch and it started giving code 258. checked harness and found the wires to the hitch. Removed harness and fixed wires, ran machine and checked hitch operation. Found hitch was working fine but clear.

Part Number

Description

Quantity

List Price



Invoice Nu
Invoice
Lo
Work Order N
Paymen

JOHN DEERE 4955	Meter: 2702	Serial Number: RW4955P003332	Eq ID: 24370W
-----------------	-------------	------------------------------	---------------


/GEN-HITCH Retail			
R113476	Nut		
R89518	Panel	2.00	
TY22062	2.5 GAL HY-GARD OIL	1.00	
TY6354	HY-GARD 1 GAL.	2.00	
		1.00	

Labor: [REDACTED]	Parts: [REDACTED]	OL&M: [REDACTED]	Misc: [REDACTED]
-------------------	-------------------	------------------	------------------

/TRACTORCOMPLETESERV Retail
COMPLAINT:
03 TRACTOR - COMPLETE MACHINE SERVICE

CAUSE:
Service machine by replacing engine oil filter along with air filters fuel filters and hydraulic filters.

CORRECTION:



FOR THE TRACTOR
COMPLAINT
OF TRACTOR WORK ON DETAILED EXAMINATION



SE
Invoice Number:
Invoice Date:
Location:
Work Order Number:
Payment Type:

JOHN DEERE 4955

Meter:

2702

Serial Number:

RW4955P003332

Eq ID:

24370W

Page:

/TRACTORCOMPLETE SERV Retail
SERVICE TRACTORCOMPLETE MACHINE SERVICE

- Change engine oil and filters
- Clean or replace all air filters as needed
- Grease machine
- Blow out cooling package
- Check all fluid levels
- Re-set service hours
- Change fuel filters
- Drain clean oil reservoir.
- Change transmission/hydraulic oil and clean transmission filter screen.
- Clean transmission filter screen
- Replace transmission/hydraulic filters (both filters).
- Clean hydraulic oil suction screen.
- Change MFWD Or Independent Link Suspension wheel hub oil. (single wheels only)
- Change MFWD differential oil.
- Lubricate Independent Link Suspension axle—internal tie rod ball joints.
- Lubricate draft link support shaft bushing.
- Check auxiliary drive belt.

Drained engine oil and removed filter. Replaced with new, replaced fuel and air filters.

Removed hydraulic filters and replaced with new.

Part Number	Description	Quantity	List Price	Net Price
AR94510	HYD.-TRANS. FILTER	1.00		
RE260688	Module	1.00		
TY22324	5/16" FUEL & OIL HOSE	6.00		
TY22462	#4 HOSE CLAMP	2.00		
TY6390B	PLUS 50 II bulk quart	23.00		
Labor:	Parts:	OL&M:	Misc:	Sub-

/DETAIL Retail
COMPLAINT:
04 WASH, WAX OR DETAILED CLEANING



Invoice Number:	2252727
Invoice Date:	11/30/2022
Location:	03
Work Order Number:	368590
Payment Type:	Finance
Page:	6 of 9

meter:	2702	Serial Number:	RW4955P003332	Eq ID:	24370W	Fleet No:	TRACTOR
--------	------	----------------	---------------	--------	--------	-----------	---------

EXPERT-1000000071317 Retail

Labor:	Parts:	OL&M:	Misc:	Sub-Total:
--------	--------	-------	-------	------------

/Gen-Fuel,Air,Coolin Retail
COMPLAINT:
07 Fuel, Air, Cooling System Repairs

CAUSE:
Heater hoses were torn and hose from radiator to tank were torn.

CORRECTION:
Fuel, Air, Cooling System Repairs

Checked coolant and found it was low. Filled machine with water and found it was leaking out of the cab heater hoses. Removed hoses and replaced them with new. Filled machine with water and ran machine and drained it, flushing the system twice. Filled machine with coolant and ran, found there was a hose leaking from the radiator to the reservoir. Removed and replaced with new, ran and checked for leaks and found none. Finished job.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14H819	WING NUT	1.00				
TY26575	COOL-GARD II Pre-Mix 1-GAL	1.00				
TY26576	2.5 GAL. COOL-GARD II PRE-MIX COOLANT	3.00				
Labor:	Parts:	OL&M:	Misc:	Sub-Total:		

/Gen-Electrical Retail
COMPLAINT:
08 ELECTRICAL REPAIRS

CAUSE:
Wire loom missing on engine harness.

CORRECTION:

SERVICE INVOICE	
Invoice Number:	2252727
Invoice Date:	11/30/2022
Location:	03
Work Order Number:	368590
Payment Type:	Finance
Page:	7 of 9
Eq ID:	24370W
Fleet No:	TRACTOR

**/Gen-Electrical Retail
ELECTRICAL REPAIRS**

Engine harness had torn and missing wire loom. Installed new wire loom on harness.

**/Gen-Hydraulic Retail
COMPLAINT:
09 Hydraulic Repairs**

- Replace High Pressure Pump and line also bracket

CORRECTION:

Hydraulic Repairs

Tried to pull drive shaft, cover stuck, got slid back enough to get to drive shaft bolts. Pulled bolts, one bolt came out hard, pulled shaft and shield. Got shield pulled apart and cleaned. Took apart and removed hydraulic pump, tore down, cleaned and rebuilt. While apart, replaced small steering bleed line that was almost rubbed through. Installed pump and put together. Checked hole in MFWD yoke where bolt came out hard, ran tap through threads they were ok. Ran tap through other holes, got two new bolts. Installed driveshaft and shield, took apart and removed pressure line to rock shaft. New line was different, got routed and installed. Installed new clamps on line, ran and checked, all ok. Topped off with hydraulic oil.

Part Number	Description	Quantity	List Price	Net Price	Extended Price
AR101237	SHIELD	8.00			
AR56065	OIL LINE	1.00			
AR69444B	GALLON HYGARD HYDRAULIC OIL	1.00			
R105583	VALVE SEAT, HYD. PUMP	8.00			
R49297	DISK	8.00			
R51655	HALF CLAMP	2.00			
R56751	O-RING	10.00			
R70648	DRAIN PLUG	8.00			
R72507	THRUST WAS	2.00			

CONTINUED ON NEXT PAGE->

SERV

Invoice Number:
Invoice Date:
Location:
Work Order Number:
Payment Type:

Page:

JOHN DEERE 4955

Meter:

2702

Serial Number:

RW4955P003332

Eq ID:

24370W

/Gen-Hydraulic Retail

R73189	V-BELT	1.00
R76182	TUBE NUT	1.00
R76183	BACK-UP RI	1.00
R78202	HYD. Pump Drive Cushion	1.00
R79151	LOCK WASHE	1.00
R80623	.268" I.D. Tubing 3,000 Inch Roll	1.00
R85169	SCREW	60.00
RE10712	CONTROL VALVE	1.00
RE13271	SCREW	1.00
RE19233	ELBOW FITT	1.00
RE29109	KIT	1.00
RE41942	BELT SET	1.00
RE49923	OIL LINE	1.00
T28549	SNAP RING	1.00
TY22466	#12 HOSE CLAMP	1.00
TY22563	3/4" OIL HOSE (Sell by Inch)	2.00
TY26101	Brake & Parts Cleaner	9.00
U15980	O-RING	1.00
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>
3750	JD FREIGHT	1.00

Labor:

Parts:

OL&M:

Misc:

Sub-Total

/WINTERSPECIAL Retail
COMPLAINT:

10 WSI-OFFICIAL JOB CODE FOR WINTER SERVICE SPECIALS. NO PARTS OR LABOR POSTED.

CONTINUED O

JOHN DEERE 4955

WINTERSPECIAL Retail
CORRECTION:
WSI JOB CODE FOR WINTER SERVICE SPECIALS.

Meter:

2702

Serial Number:

RW4955P003332

Invoice
Invo
L
Work Order N
Payment

Eq ID:

24370W

Labor

Parts:

OL&M:

Mis

INVOICE CONTAINS

DISCOUNT

Finance Information

Type: FARM PLAN

Merchant N

*** DOCUMENT COPY ***

Inspect & Repair Now. Be Ready Later. Save on equipment ins

Inspection with every Crop Swap.

