[redacted]

Invoice

Invoice #	SO-55004
Date	9/18/2026

PO Number	Sales Rep	Due Date	Payment Terms
#12	Elias Deleon	10/3/2026	Net 15

Product	Description	Quantity	Unit Price	Special Tax Rate	Sub-Total
22-903/10021PP	Kit, Service; Pivot Bushing OEM#334-1576 (S-24691) Other Part 22-903	4	[redacted]	Taxable	$483.52
035-58460	Steel Flex Bow Socket	1		Taxable	$100.51
035-58460	Steel Flex Bow Socket	1		Taxable	$100.51
035-56187	Bow Composite 101" Lg X 13/8" Diameter	1		Taxable	$173.16
S-20924	Hendrickson Inner Alignment Washer Flanged	4		Taxable	$115.72
S-20925	Hendrickson Outter Alignment Washer Flanged	4		Taxable	$115.72
Labor	Labor	12		Non-Taxable	$1,560.00

Remarks: Install New Bushigs On Both Axles On End Dump #12 + Replaced Tarp Bows & Brackets

Sub-Total	[redacted]
Tax	
Total	$2,717.21

Signature

[redacted]