

FH6452

INVOICE

44208

Printed Date: 02/12/2026

Work Completed: 02/10/2026

2005 Ford - F-650 -

Odometer In : 1

Lic # :

VIN # : 4V685084

Qty	Sale	Ext	Labor Description	Ext
-----	------	-----	-------------------	-----

TRANSMISSION ISSUES - SHIFT 3RD AND REVERSE ONLY
SOLENOIDS AND SENSORS HAVE BEEN REPLACED
SPEEDOMETER INOP

Inspected system - checked TCM powers and grounds - good voltage on the communication lines but no communication on scan connect - found TCM failing - sent in for rebuild - tcm was internally failed and could not re-furbished - installed new TCM - truck would intermittent loose communication with the TCM - after line testing all engine wiring traced source to bad ground connection at batteries in engine harness - repaired adn replaced all faulty connections - test drove - checks out

PAID ☐ CASH
☐ CHECK
☐ CREDIT

Org. Estimate

Labor:
Parts:

SubTotal:
Tax:
Total:
Bal Due: \$3,291.37

[Payments -]

Vehicle Received: 2/10/2026

Customer Number :

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection.

Signature _____ Date _____