

6/25/2026 8:44:16 AM CDT

Repair Order #2157

Page:1

Phone:

Vehicle : 2012 Ram 2500HD 5.7 L 345 CID V8 Hemi

Tag/State : /KS

VIN : 3C6LD5ATOCG145618

Fleet #/Driver :

Odometer In :

Created : 6/12/2026 10:06:09 AM CDT

Odometer Out :

Labor/Notes

Technician

Description

CAMSHAFT Remove & Replace

Price
\$2,090.00

Includes: R&I Cylinder Heads.

Includes: R&I Oil Pan.

Includes: R&I Timing Chains.

Parts

Qty Code

Description

Condition

Unit Price

Price

1

Dorman - HELP Exhaust Manifold Hardware Kit

\$58.96

1

Dorman Exhaust Manifold Hardware Kit

\$58.96

1

Duralast Engine Oil Pan Gasket DL-A1310021

\$142.53

1

FEL - PRO FEL-PRO Engine Water Pump Gasket
35907

\$18.68

1

FEL-PRO Engine Intake Manifold Gasket Set

\$34.63

1

NAPA Proformer Engine Oil Filter

\$8.24

7

OIL

\$56.00

2.5

ANTIFREEZE

\$40.00

6

HOSE CLAMP

\$14.52

1

BOLTS, NUTS, WASHERS

\$6.00

1

CAMSHAFT & LIFTER KIT

\$1,500.00

Labor

Parts

Supplies & Disposal

Sales Tax

.....
\$1,953.26 less discount: \$14.74

\$2,090.00

\$1,938.52

\$19.99

SALES TAX @ 9%

\$364.37