



## Time & Cost Tracking

### PARTS USED

|                                         |  |
|-----------------------------------------|--|
| 6.7 long block .....                    |  |
| 6.7 injectors with feed tubes .....     |  |
| 6.7 push rod .....                      |  |
| John Deere Break in oil .....           |  |
| 86733 fuel filter .....                 |  |
| 650832AA body bolt .....                |  |
| 4596198 radiator cap .....              |  |
| 5012557AA .....                         |  |
| 5014169AB .....                         |  |
| 5083285AA oil filter .....              |  |
| 53041138AE belt .....                   |  |
| 68002980AA exhaust .....                |  |
| 68534176AA dodge thermostat .....       |  |
| TCS46174 crank seal .....               |  |
| 5003619AB block heater dodge .....      |  |
| 68282012AB intake sensor dodge .....    |  |
| 4429862 exhaust nut .....               |  |
| 5017783AA O-ring oil dipstick .....     |  |
| 5086853AA seal .....                    |  |
| 68002992AA fuel line washer .....       |  |
| 68038153AA seal trans .....             |  |
| 5189966AE tranmission fluid dodge ..... |  |
| F64525G Fram 15w40 .....                |  |
| XQ22 Wiper Blade .....                  |  |
| 889787 75w140 quart .....               |  |
| 5183354AB gasket .....                  |  |
| 68003277AA o-ring dodge .....           |  |
| 53034051AB factory air filter .....     |  |
| 26813 ac o-ring kit .....               |  |
| 5183354AB turbo gasket .....            |  |
| 26224 trubo hose .....                  |  |
| R134a bulk .....                        |  |
| 904-418 crank case filter .....         |  |
| <b>Total Part Costs</b> .....           |  |

## 🕒 TIME ENTRIES

Dean Mac Donald .....

**Total Time Duration** .....

**Total Time Costs** .....

## \$ ADDITIONAL COSTS

ac manifold line rebuild from max air (Other) .....

mad piston receipt (Other) .....

labor from mad piston (Other) .....

Tow bill died while driving (Other) .....

**Total Additional Costs** .....

**Total Work Order Costs****\$13,886.93**

## 📎 COST ATTACHMENTS

📎 [8310towbill.pdf](#)

## ☰ PROCEDURE

**Before and After Procedure****3 / 3**

Fields completed

Describe solution:

Diag and replaced long block assembly and 6 injectors necessary other parts. Changed out break in oil at 113875 miles.

mileage:

113767

