2015 CATERPILLAR AP1000F ASPHALT PAVER

Equipment	2015 Caterpillar AP1000F	Auction item	FK2214
Serial number	CATAP100JAC400132	Meter reading	3,611 hours*
Fuel / engine	Diesel / Caterpillar C7.1	Seller	

REPAIR HISTORY

DATE	WORK PERFORMED	REPORTED COST
04/29/2026	New screed plates installed; software updated; screed adjusted.	$8,638.23
04/29/2026	Screed plates, six heating elements, screed plate field kit, and temperature sensor.	$12,898.13†
01/07/2025	TA2 inspection; 2,000-hour and 3,000-hour services; hitch/push roller replaced; auger conveyor segments replaced; left and right steering guides replaced; transmission hoses replaced.	$18,722.03
03/04/2025	Left and right hopper flashing replaced; depth gauge markers, step, dash gauge, fuse box cover, engine belt, and blower replaced.	Not provided

Total of three reported priced entries: $40,258.39