

**Customer Comments**

LOF  
Brake lights inoperative - loose connection?

**Recommendations**

Brake light failure is due to failed TIPM. TIPM is limited availability.

**Basic engine oil service**

Engine oil and filter change. Includes tire pressure check/adjust, fluid level check/adjust, maintenance reminder reset.

**Subtotal****Description**

- 1 Engine Oil Filter
- 2 530  
Note: 5W-30 engine oil
- 3 Engine oil service

EPA (1%)

Shop Supplies (2%):

Tax (9.1%):

**Total:****Electrical System Inspect**

Performed in-depth electrical testing. Traced failure of brake and turn signals to Total Integrated Power Module. Will require replacement.

**Subtotal****Description**

- 1 Electrical System Inspect

**Total:**

Parts .....  
Labor .....  
Subtotal .....  
Shop Supplies .....  
EPA .....  
Tax .....  
Grand Total .....  
Paid To Date .....

**REMAINING BALANCE****\$218.92**