Ditch Witch

| Code | Description |
|---|---|
| R121402 | CYLINDER HEAD NEW REMAN |
| NR123960S | PIN BUSHINGS BORABLE |
| R501124 | ROD BOLTS |
| RP813 | ENGINE KIT STD RODS AND MAINS |
| NR85363 | HEAD BOLTS |
| NRE48786 | FUEL INJECTOR NEW |
| NR107731 | PUSHROD |
| NRE59997 | TURBOCHARGER NEW |
| NRE64354 | THERMOSTAT |
| NRE505981 | WATER PUMP NEW |
| REBUILD | RODS |
| R74012 | GROMMET |
| R51936 | GROMMET |
| R79605 | GROMMET |

| Code | Description |
|---|---|
| 19M7810 | EXHAUST BOLTS |
| RE60021 | FILTER FUEL |
| 84243 | OIL FILTER |
| 14M7066 | NUT |
| METRIC | HARDWARE |
| R87732 | EXHAUST SPACER |
| R123246 | EXHAUST ELBOW |
| RE565560 | OIL CAP |
| RE59296 | OIL COOLER |
| | SHOP SUPPLIES |
| | CUSTOMER BROUGHT ENGINE IN TO REPAIR...ENGINE WAS LOCKED UP... DISASSEMBLE AND FOUND NO 1 CYLINDER WITH BOKEN VALVE AND PISTON DAMAGED...DISASSEMBLE AND ORDER PARTS..FIND CYLINDER HEAD...OVERHAUL ENGINE...REPLACE 2 PUSHRODS AND ALL INJECTORS...INSTALL NEW TURBO..INSTALL NEW EXHAUST ELBOW AND SPACER...INSTALL ALL NEW EXHAUST HARDWARE....INSTALL NEW OIL COOLER...INSTALL NEW WATER PUMP .INSTALL NEW THERMOSTAT..NOTE.. BOTH FUEL AND OIL FILTERS HAVE BEEN FILLED...CUSTOMER HAS DONE RADIATOR AND WILL INSTALL NEW HOSES... |
| | TAX |
| | NOTE ..ONE YEAR WARRANTY ..NOT COVERING CUSTOMER RELATED OVERHEATING AND ABUSE...LABOR ONLY ... PARTS SUBJECT TO MANUFACTURES WARRANTY |

[redacted]

[redacted]

***Total*** **$11,345.97**