Make/Model	Serial Number	Meter	Equipment ID	Fleet Number
JOHN DEERE 635 D	H00635D730486	30.00	126047PLP	

//SER - Retail

COMPLAINT:

Service Call Location:
(Miles Round Trip)
C/S he can't get his header to calibrate, has 2 sensors giving codes

REPAIR:

Service Call
Location:
(42 Miles Round Trip)
Went to machine.
Pinned header tires in the up position.
Went through calibration for header.
Got accumulator pressure code.
Test pressure and found it was bad installed accumulators.
Recalibrated header and it threw another code for left float sensor out of range high.
Tested wiring to sensor and verified wiring was good.
Repositioned sensor and got header to calibrate successfully.

Part Number	Description	Quantity	Unit Price	Extended Price
Part - AXE68944	Hydraulic Accumulator	2.00		

Misc Charges	Description	Quantity	Unit Price	Extended Price
Misc	SERVICE CALL FEE	1.00		

Labor	Parts	Misc	OL&M	Subtotal

//SER - Retail

COMPLAINT:

Service Call Location:
(30 Miles Round Trip)
C/S he has no reel speed showing & can't slow it down, reel is going too fast. Getting code for mass flow sensor & alarms going off all the time. Would like help setting the machine

REPAIR:

Service Call
Location:
(Miles Round Trip)
C/S he has no reel speed showing & can't slow it down, reel is going too fast. Getting code for mass flow sensor & alarms going off all the time. Would like help setting the machine

Checked out the machine,
Had to calibrate the head & when running out the platform, 1 belt broke & the cleaning fan belt was in terrible shape.
Replaced the shoe drive belt and cleaning fan belt.
Operated the machine and adjusted machine for crop.

Part Number	Description	Quantity	Unit Price	Extended Price
Part - HXE15594	V-Belt	1.00		
Part - HXE82335	V-Belt	1.00		

Misc Charges	Description	Quantity	Unit Price	Extended Price
Misc	SERVICE CALL FEE	1.00		

Labor	Parts	Misc	OL&M	Subtotal

Customer PO #	
Tax Exempt #	
Advisor	

Labor	
Parts	
Misc	
OL&M	
Subtotal	
Tax	
Total	$1,188.43

[redacted]

[redacted]

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
Eq ID: 126047PLP		Make: JOHN DEERE	Model: 635 D	PIN: H00635D730486		Hours: 52		
1.00	0.00	AXE14338	Universal Driveshaft				[redacted]	

Invoice Notes:

Customer PO No: [redacted]
Tax Exempt No:
Salesperson:

* * * DOCUMENT COPY * * *

Parts:	[redacted]
Misc:	
Sales Tax:	
Deposit:	
Total:	$1,631.34

TERMS AND CONDITIONS

Terms are Net 30. A Finance Charge of 2% per month which is an annual rate of 24% will be added to all past due invoices. Please note there will be a fee on all returned checks. Invoices can be viewed at anytime on our customer portal at the following [redacted]

No returns allowed on electrical components. A 25% handling fee will be charged unless due to defective goods or our error. Goods cut to length or special order goods are not returnable. NO RETURNS OR REFUNDS AFTER 30 DAYS. If not paid as agreed, this credit agreement provides for your payment of reasonable costs of collection, including, but not limited to, court costs, attorney fees and/or collection fees. Invoices can be viewed at anytime on our customer portal at the following [redacted]

Received by: ..... Date: .....

Make/Model	Serial Number	Meter	Equipment ID	Fleet Number
JOHN DEERE 635 D	H00635D730486	0	126047PLP	

Complaints:

Service Call
Reel is working erratically

Repair:

Header was experiencing multiple issues such as reel was not working, header pressure, and header tilt
Removed all of the solenoids on the right hand side of the header
Checked pressure on the valve stack of the combine to make sure that it had enough pressure, it was good
Pulled the 31 pin connector out and plugged them into each other without using the multi coupler
The combine still showed that there was no header detected
Used a blank connector pin and tried to clean out the female side
Put everything back together
The header appeared on the display and all the functions started working again
Noticed the multi coupler moved a lot when using the functions
Found the pins would lose contact when using header functions due to the block not fitting tight when latched
Also some of the hydraulic fittings were worn from it moving up and down whenever the functions were being used
Ordered a new face plate and installed the top right, top left and bottom right hydraulic couplers on the header side
Also replaced the top left and bottom left on the combine side
Replaced the 31 pin connector on the combine and the header
Installed all new pins into the new housing
Tested for leaks and to see if the header connected to the combine, everything worked as it should

Part Number	Description	Quantity	Unit Price	Extended Price
H202071	BUSHING	2		
R26906	O-RING-9760STS	5		
R26375	O-RING-	2		
R78065	SOCKET CON (	35		
HDW8	OZ GR8 HARDWARE BLUE	18		
R78066	PIN CONTAC (	35		
AH201340	Plate	1		
AH168766	Elec. Connector	1		
TY26101	Brake & Parts Cleaner	4		
K40016	3/4" LOCK NU	1		
AXE60985	HYDR. QUIC	2		
AXE60983	HYDR. QUIC	3		
AH168765	Elec. Connector	1		
19H2001	3/4 X 5 1/2	1		

Part Number	Description	Quantity	Unit Price	Extended Price
P3750	SHIPPING & HANDLING	1		

Misc Charges	Description	Quantity	Unit Price	Extended Price
SERVICE CALL FEE	SERVICE CALL FEE	1		

Segment Summary:

//SER - Retail

Labor	OL&M	Parts	Subtotal

JD Finance:

Terms & Conditions: This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Order Summary:

Parts:	
OL&M:	
Misc:	
Labor:	
Subtotal:	
Tax:	
Total:	$4,264.10

[redacted]

Mobil [redacted] Mobile [redacted]

Make/Model	Serial Number	Meter	Equipment ID	Fleet Number
JOHN DEERE 635 D	H00635D730486	0.00	126047PLP	

//SER - Retail

COMPLAINT:

Service Call
C/S there is a pin he has out of gauge wheel that has play
Head won't calibrate is just bounces side to side

REPAIR:

Checked out the LH header gauge wheels and ordered parts for it and the RH side
Adjusted the feeder house raise and lower speed because they said it was too fast
Went back out with the new parts
Installed a new arm and inner bushing on the LH side
Installed new arm bushings and inner bushing on the RH side
Tried to calibrate the header and the float sensors that were previously installed were incorrect
Installed the correct sensors
Voltage was sporadic and it still would not calibrate
Multiple pins in the electrical connector at the single point connector were loose in the plug
Repinned and installed new connector
Went through calibration procedure and adjusted sensors until voltage was within spec and header calibrated
Installed a new hydraulic coupler in the combine top RH side and a seal kit in the top RH side on the header
Test ran it and everything worked
A couple days later, header coupler was leaking
Found the top right was still leaking
Took the header side apart and it was clean
Installed a complete cartridge on it and installed a new coupler on the combine
Tested for leaks, everything worked as it should

Part Number	Description	Quantity	Unit Price	Extended Price
Part - 14M7303	M6 FLANGE NUT	2.00	[redacted]	

Invoice #

Part - 14M7303	M6 FLANGE NUT	1.00
Part - 19M7721	6M X 65	1.00
Part - 19M7796	6M X 30 FLAN	2.00
Part - 24M7242	Washer	4.00
Part - A31870	M20 LOCKNUT	2.00
Part - AH168765	Elec. Connector	1.00
Part - AXE10163	Arm	1.00
Part - AXE17227	Sensor	1.00
Part - AXE17227	Sensor	1.00
Part - AXE57295	Sensor	2.00
Part - AXE60984	Hydr. Quick Coupler Socket	2.00
Part - AXE60986	Hydr.Quick Coupler Plug	1.00
Part - GX10120	EXTENSION	1.00
Part - H165942	Shift Collar	2.00
Part - H201027	SCREW-PLF	2.00
Part - H227224	Plate	1.00
Part - H235476	Screw	2.00
Part - HXE10102	BUSHING	1.00
Part - JD7797	LUBRICATIO	1.00
Part - R26375	O-RING-	1.00
Part - R78066	PIN CONTAC (	11.00
Part - T77857	O-RING-9760ST	2.00
Part - TY26101	Brake & Parts Cleaner	2.00

Misc Charges	Description	Quantity	Unit Price	Extended Price
Misc	SERVICE DISCOUNT ALLOWED	1.00		
Misc	SERVICE CALL FEE	1.00		

	Labor	Parts	Misc	OL&M	Subtotal

Customer PO #	**JD Finance**		**Labor**
Tax Exempt #	Card #:		**Parts**
Advisor	Credit Plan:		**Misc**
	Descriptive Billing Code:		**OL&M**
	Authorization #:		**Subtotal**
			Tax
			Total $5,158.16

JD Finance

Terms and Conditions: This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Payment	Check#/Auth#/Override#	Credit card type	Credit card #	Signature	Amount

EMV Invoice Details

Received By:_____ Date:_____

Terms & Conditions

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Signed: ..... Date: .....

Thank you

PARTS INVOICE

Invoice No:	
Date:	10/3/2025
Page:	1 of 1
Payment Type:	Account

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
1.00	0.00	AXE12533	Flat Belt	32B04-02				N
12.00	0.00	14M7528	M6 LOCKNUT	42B10-F				N
12.00	0.00	H169640	SCREW	11H00-06H				N
2.00	0.00	H216392	BAR-635D ALUMINUM	30B01				N

Customer PO No:
Tax Exempt No:
Salesperson:

*** DOCUMENT COPY ***

Parts:	
Misc:	
Sales Tax:	
Deposit:	
Total:	$794.34

JOHN DEERE

TERMS AND CONDITIONS

Terms are Net 30. A Finance Charge of 2% per month which is an annual rate of 24% will be added to all past due invoices. Please note there will be a fee on all returned checks. Invoices can be viewed at anytime on our customer portal at the following https:/

No returns allowed on electrical components. A 25% handling fee will be charged unless due to defective goods or our error. Goods cut to length or special order goods are not returnable. NO RETURNS OR REFUNDS AFTER 30 DAYS. If not paid as agreed, this credit agreement provides for your payment of reasonable costs of collection, including, but not limited to, court costs, attorney fees and/or collection fees. Invoices can be viewed at anytime on our customer portal at the following

Received by: ..... Date: .....

...ons:

...ase is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money ...erest, except as limited in that agreement, in the goods described.

...yment Details:

Payment	Check#/Auth#/Override#	Credit card type	Credit card #	Signature	Amount
					$4,264.10

EMV Invoice Details:

Received By: _____

Date: _____

Terms & Conditions:

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Signed: _____ Date: _____

Thank you