

Mike Brown
120 Calvin Dr.
Hartsburg, MO 65039

WORK PERFORMED	CUSTOMER INFORMATION	OTHER
Replace clutch 6 pad disc reseal clutch booster reseal brake valve reseal MCV valve Replace a/c wiring changed hydraulic fluid and filter replace a/c line Replace cab mounts Replace cooler lines Replace steering pump 13gpm Repair misc oil leaks Replace bushings steer cyl.	Adam Martin	Date: 04/25/13
	Ashland	PAYMENT
	MO	Cash <input type="checkbox"/>
	65010	RATE
	Make: ih 986	Labor \$50.00/hr.
	CURRENT PROBLEMS	Serv Call <input type="checkbox"/>
		Hourly <input type="checkbox"/>
		PM Call <input type="checkbox"/>
		CHARGES
		Labor Hours 31= 1550.00.
Parts \$2400.00		
Down Payment <input type="checkbox"/> Yes <input type="checkbox"/> No	Amount \$	Gas/Oil/Grease \$328.00
I hereby authorize NAME OF COMPANY to perform the above work to be done with the necessary materials and grant permission to operate car/truck herein described on streets or highways for the purpose of testing. As explained to me a mechanics lien may be placed on said vehicle in order to obtain unpaid repairs/services left at Joe's Diesel Service for more than 30 days. I understand JDS is not responsible for loss or damage to vehicles or articles left in car/trucks in case of fire, theft or any other cause beyond our control.	Outside Repairs \$76.00	
	Storage Fee(s) \$	
	Tax \$	
	AMOUNT DUE	
Customer Signature	Date	\$ 4354.00