

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hli@heritagetractor.com

Heritage TRACTOR

WWW.HERITAGETRACTOR.COM



JOHN DEERE

SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Phone: 913-592-3264

Invoice Number: 1253454
Invoice Date: 12/19/2013
Branch: 6
Repair Order Number: 45182
Payment Type: Finance

Make/Model: JOHN DEERE-7320
Meter Reading: 2353
Serial Number: RW7320R039889
Equipment Number: 12005W
Page: 9 of 9

GEN7 Retail

\$492.00

COMPLAINT:

7. REPLACE PIVOT PINS AND BUSHINGS

CAUSE:

CORRECTION:

REMOVED FENDERS. RAISED TRACTOR UP AND PUT STANDS UNDER TRACTOR.
UNHOOKED STEERING LINES AND REMOVED TIRES. REMOVED BOLTS THAT HOLD FRONT AXLE ON A DN REMOVED
AXLE. REMOVED AND REPLACED BUSHINGS. REMOVED PINS AND INSTALLED NEW PINS. PUT AXLE BACK ON
TRACTOR AND INSTALLED BOLTS. HOOKED UP STEERING LINES. REINSTALLED FENDERS AND TIRES AND GREASED.
STARTED TRACTOR AND CHECKED FOR LEAKS.

| Part Number | Description | Quantity | Unit Cost | Value | Taxed |
|-----------------|--------------|-----------------|----------------|--------------|-----------------|
| L111817 | Pin Fastener | 2.00 | 70.97 | \$141.94 | N |
| L76471 | Bushing | 2.00 | 22.72 | \$45.44 | N |
| L80423 | Washer | 1.00 | 9.71 | \$9.71 | N |
| T77613 | O-Ring | 1.00 | 1.29 | \$1.29 | N |
| T77857 | O-RING | 4.00 | 1.40 | \$5.60 | N |
| Labor: \$492.00 | | Parts: \$203.98 | Sublet: \$0.00 | Misc: \$0.00 | Total: \$695.98 |

Finance Information

Customer PO No.:
Tax Exempt No.: ON FILE
Advisor: LIBBY SPRING

Type: Multi-use Acct US
Auth. No.: 320799
Card No.: xxxxxxxxxxxx4869
Bill Code: 704 - JD TRACTOR PARTS/SERVICE
Credit Plan: 22438 - 90 DAYS NO PAYMENTS/NO INTEF

Merchant No.: 37000286

Labor: \$3,550.59
Parts: \$1,452.39
Sublet: \$0.00
Misc: (\$234.91)
Sales Tax: \$0.00
Total: \$4,768.07

TERMS AND CONDITIONS

Finance Charges are 1.5% per month (APR of 18%) and will be charged on balances over 30 days past due.
No returns after 30 days and 15% restocking fee on all special order items.
No returns on electrical items.

SUBMITTED TO
JOHN DEERE FINANCIAL
PAY JOHN DEERE
FINANCIAL DIRECTLY

Signed:

Date:

1110 E 23rd St.
Lawrence, KS 66044
Phone: 785-843-8444
hli@heritagetractor.com



WWW.HERITAGETRACTOR.COM



SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

Phone: 913-592-3264

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Invoice Number: 1253454

Invoice Date: 12/19/2013

Branch: 6

Repair Order Number: 45182

Payment Type: Finance

Make/Model: JOHN DEERE 7320

Meter Reading: 2353

Serial Number: RW7320R039889

Equipment Number: 12005W

Page: 2 of 9

- THERMOSTATS
- 3.FUEL SYSTEM
 - FUEL LEAKS
 - TANKS AND FILTERS
 - TRANSFER PUMP
 - NOZZLES AND LINES
 - INJECTION PUMP TIMING
 - ANEROID ADJUSTMENT
 - FUEL SHUT-OFF OPERATION
 - THROTTLE LEVER FRICTION
 - MAKE POWER CHECK
- 4.ELECTRICAL SYSTEM
 - BATTERY
 - CONDITION
 - ELECTROLYTE LEVEL
 - SPECIFIC GRAVITY
 - BATTERY CABLES/ENDS
 - STARTER OPERATION
 - NEUTRAL START SYSTEM
 - PRESENCE OF STARTER TERMINAL GUARD
 - GENERATOR/ALTERNATOR CHARGING
 - LIGHTS/TURN SIGNALS
 - INSTRUMENTS/INDICATOR LIGHTS
 - STARTING AID OPERATION
 - WIRING HARNESSES
 - TACHOMETER FOR STORED CODES
- 5.POWERTRAIN
 - CLUTCH FREE PLAY
 - SYSTEM OPERATING PRESSURE
 - LUBE PRESSURE
 - PTO CLUTCH AND BRAKE OPERATION
 - TRANSMISSION OPERATION
 - TRANSMISSION PARK MECHANISM
 - DIFFERENTIAL LOCK OPERATION
 - FRONT DIFFERENTIAL-MFWD
 - U-JOINTS AND SHIELDING-MFWD
 - FINAL DRIVES
 - AXLES-OUTER AXLE SEAL AND BEARING CONDITION
 - LEAKS
 - DIFFERENTIAL LOCK/BRAKE PEDAL ADJUSTMENT

1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hli@heritagetractor.com



JOHN DEERE

SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Phone: 913-592-3264

Invoice Number: 1253454
Invoice Date: 12/19/2013
Branch: 6
Repair Order Number: 45182
Payment Type: Finance

Make/Model: JOHN DEERE 7320
Meter Reading: 2353
Serial Number: RW7320R039889
Equipment Number: 12005W
Page: 1 of 9

//100100M-7320 Retail

\$610.90

COMPLAINT:

1. SERVICE INSPECTION W/DYNOMETER

CAUSE:

CORRECTION:

1.ENGINE

-INTAKE SYSTEM

HOSE CONDITION
CLAMP TIGHTNESS

AIR FILTERS

VACUUM SWITCH OPERATION

TURBO INSPECTION

AIR CLEANER UNLOADING VALVE

-EXHAUST SYSTEM

-HEAD GASKET

-VALVE LASH ADJUSTMENT

-CRANKSHAFT DAMPER

RUNOUT
CONDITION

-HIGH AND LOW IDLE SPEEDS

-OIL LEAKS

-PULLEYS AND BELTS

-CLEAN CRANKCASE VENT TUBE

2.COOLING SYSTEM

-RADIATOR CAP

-RADIATOR

-HOSES AND CLAMPS

-WATER PUMP

SHAFT END PLAY

WEEP HOLE FOR SIGNS OF LEAKAGE

-COOLANT LEAKS

-COOLANT

CONDITION

LEVEL

FREEZING POINT

ADD/CHANGE COOLANT CONDITIONER

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hti@heritagetractor.com

Heritage

TRACTOR

WWW.HERITAGETRACTOR.COM



JOHN DEERE

SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Phone: 913-592-3264

Invoice Number: 1253454

Invoice Date: 12/19/2013

Branch: 6

Repair Order Number: 45182

Payment Type: Finance

Make/Model: JOHN DEERE 7320

Meter Reading: 2353

Serial Number: RW7320R039889

Equipment Number: 12005W

Page: 3 of 9

MAINTENANCE ITEMS

- TRANSMISSION/HYDRAULIC FILTERS
- CLUTCH FILTER
- TRANSMISSION/HYDRAULIC/MFWD OIL
- TRANSMISSION/MFWD BREATHER
- TRANSMISSION SUMP SCREEN
- FRONT DIFFERENTIAL OIL LEVEL-MFWD
- LUBRICATE SHIFT LINKAGE
- 6. STEERING AND BRAKES
 - STEERING OPERATION
 - STEERING VALVE
 - STEERING MOTOR, CYLINDERS, AND HOSES
 - STEERING WHEEL FREE TRAVEL
 - TIE ROD AND DRAG LINK ENDS
 - STEERING ARM
 - FRONT AXLE PIVOT BUSHINGS
 - FRONT AXLE SPINDLE BEARINGS
 - FRONT WHEEL BEARINGS
 - BRAKE OPERATION
 - BRAKE VALVES
- 7. HYDRAULIC SYSTEM
 - MAIN PUMP COUPLER
 - MAIN PUMP STANDBY PRESSURE
 - MAIN PUMP QUICK CHECK
 - ROCKSHAFT/EH HITCH
 - OPERATION
 - CYCLE TEST
 - ADJUSTMENTS
 - STORE HCU CODES
 - DRAFT SENSING CYLINDER/STRAP
 - SELECTIVE CONTROL VALVE AND COUPLER
 - OPERATION
 - CYCLE TESTS
 - LINES AND CLAMPS
 - LEAKS
 - MANUAL BYPASS VALVE OPERATION
 - SEAT ACCUMULATOR PRECHARGE
- 8. OPERATOR'S STATION
 - SEAT BELT

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hti@heritagetractor.com

Heritage

TRACTOR

WWW.HERITAGETRACTOR.COM



SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

| | | |
|---|---|--|
| TOM EWING 21684 W 191 ST SPRING HILL KS 66083 Phone: 913-592-3264 | TOM EWING 21684 W 191ST STREET SPRING HILL KS 66083 Phone: 913-592-3264 | Invoice Number: 1253454 Invoice Date: 12/19/2013 Branch: 6 Repair Order Number: 45182 Payment Type: Finance |
|---|---|--|

| | |
|--------------------------|-----------------|
| Make/Model: | JOHN DEERE 7320 |
| Meter Reading: | 2353 |
| Serial Number: | RW7320R039889 |
| Equipment Number: | 12005W |
| Page: | 4 of 9 |

- SEAT OPERATION
- SOUND-GARD BODY
- SOUND-GARD BODY MOUNTING
- SOUND-GARD BODY GLASS
- SOUND-GARD BODY FILTER CONDITION
- SOUND-GARD BODY WIPERS/WASHERS
- SOUND-GARD BODY CLEANED
- WIPER BLADE CONDITION
- BLOWER MOTOR OPERATION
- HEATER OPERATION
- AIR CONDITIONING
- OPERATION
- SYSTEM CHARGE
- CHECK FOR EXTERNAL PLUGGING
- CONDENSER
- EVAPORATOR
- HEATER CORE
- MIRRORS
- ROPS
- 9.MISCELLANEOUS
- DRAWBAR
- FRAME AND WEIGHTS
- SIDE FRAME CAPSCREW TORQUE
- BOTTOM FRAME PLATE CAPSCREW TORQUE
- SHEET METAL
- PTO SHIELD
- SMV SIGN
- WHEELS AND TIRES
- FRONT AXLE HARDWARE TORQUE
- FRONT WHEEL BEARINGS
- GREASE ENTIRE MACHINE
- SAFETY DECALS
- FIRE EXTINGUISHER (IF EQUIPPED)

| | | | | | |
|------|--------------------------------|------|---------|------------|---|
| 3951 | DYNO CHARGE | 1.00 | 60.00 | \$60.00 | N |
| 3970 | SVC LBR DISC ALLOWED - AG ONLY | 1.00 | -280.91 | (\$280.91) | N |

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hli@heritagetractor.com

Heritage TRACTOR

WWW.HERITAGETRACTOR.COM



JOHN DEERE

SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

| | | |
|---|---|--|
| TOM EWING 21684 W 191 ST SPRING HILL KS 66083 Phone: 913-592-3264 | TOM EWING 21684 W 191ST STREET SPRING HILL KS 66083 Phone: 913-592-3264 | Invoice Number: 1253454 Invoice Date: 12/19/2013 Branch: 6 Repair Order Number: 45182 Payment Type: Finance |
|---|---|--|

| | |
|--------------------------|-----------------|
| Make/Model: | JOHN DEERE 7320 |
| Meter Reading: | 2353 |
| Serial Number: | RW7320R039889 |
| Equipment Number: | 12005W |
| Page: | 5 of 9 |

//100100M-7320 Retail

| | | | | | |
|------------------------|--------------------------------|----------------------|-----------------------|-------------------------|------------------------|
| 3980 | SVC N-LBR DISC ALLOW - AG ONLY | 1.00 | -60.00 | (\$60.00) | N |
| WS6TR13 | WINTER SERVICE TRACT.2013 | 1.00 | 0.00 | \$0.00 | N |
| Labor: \$610.90 | | Parts: \$0.00 | Sublet: \$0.00 | Misc: (\$280.91) | Total: \$329.99 |

GEN2 Retail

\$437.33

COMPLAINT:
2. REPLACE FUEL LINES

CAUSE:

CORRECTION:
REMOVED FLOOR MAT AND COVER OVER FUEL SENDER. DISCONNECTED FUEL SUCTION AND RETURN HOSES AND FUEL SENDER WIRING. REMOVED FUEL SENDER AND ADDED A TUBE ON THE RETURN SIDE. INSTALLED SENDER BACK INTO TANK. REMOVED RETURN LINE AND CUT NEW HOSE AND INSTALLED NEW HOSE TO LENGTH AND INSTALLED ON TRACTOR. REMOVED FUEL PUMP AND REPLACED WITH A NEW FUEL PUMP. REMOVED HOSE FROM FILTER TO PUMP AND REPLACED WITH NEW. REMOVED HOSE FROM OUTSIDE ON FUEL PUMP TO FILTER. REPLACED WITH NEW. REMOVED HOSE ON FUEL COOLER AND REPLACED WITH NEW. TEST RAN TO CHECK FOR LEAKS.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>Unit Net</u> | <u>Value</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|------------------------|-----------------------|----------------------|------------------------|
| 3771 | SERVICE ACCESSORIES | 1.00 | 40.00 | \$40.00 | N |
| AL113086 | Filler Cap | 1.00 | 30.01 | \$30.01 | N |
| AL170540 | Kit | 1.00 | 32.81 | \$32.81 | N |
| AL171434 | Tune-Up Kit | 1.00 | 311.01 | \$311.01 | N |
| FREIGHT | FREIGHT | 1.00 | 6.00 | \$6.00 | N |
| TY22462 | CLAMP | 9.00 | 0.80 | \$7.20 | N |
| TY22502 | Hose | 20.00 | 1.33 | \$26.60 | N |
| Labor: \$437.33 | | Parts: \$407.63 | Sublet: \$0.00 | Misc: \$46.00 | Total: \$890.96 |

1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hti@heritagetractor.com



SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Phone: 913-592-3264

Invoice Number: 1253454
Invoice Date: 12/19/2013
Branch: 6
Repair Order Number: 45182
Payment Type: Finance

Make/Model: JOHN DEERE 7320
Meter Reading: 2353
Serial Number: RW7320R039889
Equipment Number: 12005W
Page: 6 of 9

GEN3 Retail

COMPLAINT:

3. REPAIR LEAKS UNDER DASH

\$657.36

CAUSE:

CORRECTION:

REMOVED COWLING ON DASH, GAUGE CLUSTER, STEERING LINES AND STEERING MOTOR. DISASSEMBLED MOTOR AND REMOVED ALL O-RINGS. REPLACED O-RINGS. REASSEMBLED AND TORQUED TO SPEC. REINSTALLED MOTOR ON TRACTOR AND HOOKED UP STEERING LINES. TESTED FOR LEAKS AND PROPER OPERATION. REINSTALLED ALL REMOVED PARTS, DASH AND COWLING.

| Part Number | Description | Quantity | Unit Net | Value | Taxed Ind |
|-------------|-------------|----------|----------|---------|-----------|
| 51M7041 | O-RING | 1.00 | 1.66 | \$1.66 | N |
| 51M7043 | O-Ring | 4.00 | 1.86 | \$7.44 | N |
| AL112819 | Seal Kit | 1.00 | 69.34 | \$69.34 | N |
| TY26633 | DEGREASING | 2.00 | 3.29 | \$6.58 | N |

Labor: \$657.36 Parts: \$85.02 Sublet: \$0.00 Misc: \$0.00 Total: \$742.38

GEN4 Retail

COMPLAINT:

4. SERVICE TRANSMISSION AND FRONT END AND REPLACE FUEL FILTERS

\$410.00

CAUSE:

CORRECTION:

DRAINED HYDRAULIC OIL AND REMOVED SUMP SCREEN AND CLEANED REMOVED FILTERS AND REPLACED. REINSTALLED SUMP SCREEN AND PUT IN NEW OIL. DRAINED FRONT AXLE AND CLEANED DRAIN PLUG & REINSTALLED. PUT NEW OIL IN FRONT AXLE.

| Part Number | Description | Quantity | Unit Net | Value | Taxed Ind |
|-------------|-------------|----------|----------|---------|-----------|
| 51M7119 | O-Ring | 1.00 | 3.34 | \$3.34 | N |
| AL118036 | HYDRAULIC | 1.00 | 47.00 | \$47.00 | N |
| AL156625 | OIL FILTER | 1.00 | 46.45 | \$46.45 | N |

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hti@heritagetractor.com

Heritage

TRACTOR

WWW.HERITAGETRACTOR.COM



SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Invoice Number:

1253454

Invoice Date:

12/19/2013

Branch:

6

Repair Order Number:

45182

Payment Type:

Finance

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

Phone: 913-592-3264

Make/Model:

JOHN DEERE 7320

Meter Reading:

2353

Serial Number:

RW7320R039889

Equipment Number:

12005W

Page:

7 of 9

GEN4 Retail

AR69444

HY-Gard TM

L78457

O-Ring

RE509031

FILTER ELE

RE509036

FUEL FILTE

TY22062

HY-Gard TM

TY26815

Lubricant

TY6296

LUBRICANT

| | | | |
|------|-------|----------|---|
| 3.00 | 71.04 | \$213.12 | N |
| 1.00 | 2.10 | \$2.10 | N |
| 1.00 | 25.77 | \$25.77 | N |
| 1.00 | 22.44 | \$22.44 | N |
| 1.00 | 37.73 | \$37.73 | N |
| 2.00 | 21.66 | \$43.32 | N |
| 4.00 | 7.85 | \$31.40 | N |

Labor: \$410.00

Parts: \$472.67

Sublet: \$0.00

Misc: \$0.00

Total: \$882.67

\$410.00

GEN5 Retail

COMPLAINT:

5. ADJUST VALVES

CAUSE:

CORRECTION:
REMOVED AIR COOLER AND TUBE FROM COOLER TO TURBO. REMOVED MUFFLER AND EXHAUST PIPE. REMOVED VALVE COVER AND ADJUSTED VALVES. CLEANED VALVE COVER AND REINSTALLED WITH NEW O-RINGS. REINSTALLED MUFFLER AND PIPE. REINSTALLED AIR COOLER AND RAN TO CHECK FOR LEAKS.

Part Number

Description

Quantity

Unit Cost

Value

Taxed Ind

AL167083

Band

1.00 80.51 | \$80.51 | N |

R123543

Gasket

1.00 24.10 | \$24.10 | N |

R123575

O-Ring

6.00 0.81 | \$4.86 | N |

Labor: \$410.00

Parts: \$109.47

Sublet: \$0.00

Misc: \$0.00

Total: \$519.47

1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hti@heritagetractor.com



 JOHN DEERE

SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

| | | |
|---|---|---|
| TOM EWING 21684 W 191 ST SPRING HILL KS 66083 Phone: 913-592-3264 | TOM EWING 21684 W 191ST STREET SPRING HILL KS 66083 Phone: 913-592-3264 | Invoice Number: 1253454 Invoice Date: 12/19/2013 Branch: 6 Repair Order Number: 45182 Payment Type: Finance |
| | | Make/Model: JOHN DEERE 7320 Meter Reading: 2353 Serial Number: RW7320R039889 Equipment Number: 12005W Page: 8 of 9 |

GEN6 Retail

\$533.00

COMPLAINT:

6. REPLACE WATER PUMP GASKETS AND THERMOSTATS

CAUSE:

CORRECTION:
DRAINED COOLANT. REMOVED BELT AND HOSES. REMOVED WATER PUMP AND CLEANED GASKET SURFACES.
INSTALLED PUMP WITH NEW GASKET. REINSTALLED HOSES. REMOVED THERMOSTAT HOUSING AND OLD
THERMOSTAT. INSTALLED NEW THERMOSTAT. REINSTALLED HOUSING. FILLED WITH COOLANT AND CHECKED FOR
LEAKS. WENT TO INSTALL BELT AND FOUND ALTERNATOR BRACKET WAS BROKEN. REMOVED A/C COMPRESSOR
AND BRACKET. INSTALLED NEW BRACKET AND REINSTALLED A/C COMPRESSOR. PUT BELT ON AND TEST RAN
CHECKING FOR LEAKS.

| Part Number | Description | Quantity | Unit Net | Value | Taxed Ind |
|-----------------|-------------|-----------------|----------------|--------------|-----------------|
| 07480 | ROLOC DISC | 1.00 | 2.06 | \$2.06 | N |
| L167673 | Bracket | 1.00 | 113.40 | \$113.40 | N |
| PM710XX280 | Sealant | 1.00 | 10.29 | \$10.29 | N |
| R123226 | Seal | 1.00 | 8.79 | \$8.79 | N |
| R123417 | GASKET | 1.00 | 17.33 | \$17.33 | N |
| R89944 | O-RING | 1.00 | 2.18 | \$2.18 | N |
| RE517011 | Thermostat | 1.00 | 18.57 | \$18.57 | N |
| TY22471 | Clamp | 1.00 | 1.00 | \$1.00 | N |
| Labor: \$533.00 | | Parts: \$173.62 | Sublet: \$0.00 | Misc: \$0.00 | Total: \$706.62 |

Heritage Tractor, Inc.
1110 E 23rd St.
Lawrence, KS 66046
Phone: 785-843-8444
hli@heritagetractor.com

Heritage TRACTOR

WWW.HERITAGETRACTOR.COM



SERVICE INVOICE

Invoice To Account No.: 5628

Deliver To:

TOM EWING
21684 W 191 ST
SPRING HILL KS 66083

TOM EWING
21684 W 191ST STREET
SPRING HILL KS 66083

Phone: 913-592-3264

Phone: 913-592-3264

Invoice Number: 1253454
Invoice Date: 12/19/2013
Branch: 6
Repair Order Number: 45182
Payment Type: Finance

Make/Model: JOHN DEERE 7320
Meter Reading: 2353
Serial Number: RW7320R039889
Equipment Number: 12005W
Page: 7 of 9

| | | | | | |
|-----------------|-----------------|----------------|--------------|-----------------|---|
| GEN4 Retail | | | | | |
| AR69444 | HY-Gard TM | 3.00 | 71.04 | \$213.12 | N |
| L78457 | O-Ring | 1.00 | 2.10 | \$2.10 | N |
| RE509031 | FILTER ELE | 1.00 | 25.77 | \$25.77 | N |
| RE509036 | FUEL FILTE | 1.00 | 22.44 | \$22.44 | N |
| TY22062 | HY-Gard TM | 1.00 | 37.73 | \$37.73 | N |
| TY26815 | Lubricant | 2.00 | 21.66 | \$43.32 | N |
| TY6296 | LUBRICANT | 4.00 | 7.85 | \$31.40 | N |
| Labor: \$410.00 | Parts: \$472.67 | Sublet: \$0.00 | Misc: \$0.00 | Total: \$882.67 | |

GEN5 Retail

\$410.00

COMPLAINT:
5. ADJUST VALVES

CAUSE:

CORRECTION:
REMOVED AIR COOLER AND TUBE FROM COOLER TO TURBO. REMOVED MUFFLER AND EXHAUST PIPE. REMOVED VALVE COVER AND ADJUSTED VALVES. CLEANED VALVE COVER AND REINSTALLED WITH NEW O-RINGS. REINSTALLED MUFFLER AND PIPE. REINSTALLED AIR COOLER AND RAN TO CHECK FOR LEAKS.

| Part Number | Description | Quantity | Unit Net | Value | Taxed Ind |
|-----------------|-----------------|----------------|--------------|-----------------|-----------|
| AL167083 | Band | 1.00 | 80.51 | \$80.51 | N |
| R123543 | Gasket | 1.00 | 24.10 | \$24.10 | N |
| R123575 | O-Ring | 6.00 | 0.81 | \$4.86 | N |
| Labor: \$410.00 | Parts: \$109.47 | Sublet: \$0.00 | Misc: \$0.00 | Total: \$519.47 | |