

Model #	D7F	Serial #	94W7885	Hours	511
Name	Willy Godden			Date	10/3/11
Address				Phone	
City			State	Zip	

QTY	DESCRIPTION	PRICE	AMOUNT
	Left Final Drive was leaking and found Iron in oil. Tore Final Drive apart, Replaced Bull Gear (C.G.R.) Root Rebearinged Resealed, pressed sprocket on to 60 Ton, Holder on to 20 Ton. Set preload on bearings. wrapped track.		
	J. Robert Lamm		
	Parts		
19.25	Travel & Labor		
		TAX	
Received By		TOTAL	

01207

All claims and returned goods
MUST be accompanied by this bill

Thank You