

Sales Link - Sales Reps

Rodney Warren

Launch! Accounts Issues Leads Opportunities Activities Requests Sales Inventory Quotes Links

Look For Customers with Customer Name that Contains in General Line (G) View Mine Search Adv. Search

All A E G R T
General LineCustomer Info
Customer Profile
Sales Analysis

Issues

Lead(0)

Opportunities(0)

Bids (0)

Sales Rep Notes(0)

Documents(1)

Rental Equipment (0)

Equipment List

Latest Work Orders

UCC Information(0)

Accounts Receivable

New (0)

Done

Hold (0)

Invalid (0)

Follow-up Required (0)

Follow-up Completed (0)

Activities Outstanding(0)

Activities Completed (65)

Surveys(5)

Lost Sales Report

COMPARE Report

NOMUG CONSTRUCTION LLC (017105)

Tel: 620 431 3742 City: CHANUTE Branch: 00 Acct Type: DBS 5 Business Type: End-User

Work Order History

Stock No: 00-821	Make: AA	Model: D5C HST	Serial No: 07PS01505	Division: G	FPC: A
Eq Sts: U	Inv Sts: B	Last SMU: 7446 H	SMU Date: Jan 30, 2014 12:00 AM		
Eng Make: AA	Eng Model: 3046	Eng S/N: 05XK27732	Eng Arr No: 1498747	Trans Make:	Trans S/N:

Segment View

Invoice View

Cust:

All

Job

All

Comp

All

Customer Open Date	Hours	Work Order	A/I	Job	COMP	Pt	Cust	Lbr	Cust	Misc	Cust	Seg	Total	Notes
017105	Jun 03, 2014 12:00 AM	0	2109068 - 01	C	010	1401							425.11	REPLACED BOTH BATTERY'S
WO Total:													425.11	
017105	Jan 30, 2014 12:00 AM	7446	2108279 - 01	C	010	5057							270.23	COMPLAINT: MACHINE IS LEAKING OIL CAUSE: HOSE FOR PILOT VALVE IS LEAKING HYDRAULIC FLUID. CORRECTION: REMOVED FLOOR PLATE. REMOVED BOTTOM GUARD. REMOVED HOSE. INSTALLED NEW HOSE. REASSEMBLED MACHINE AND CHECKED FOR LEAKS. TOPPED OFF HYDRAULIC OIL.
WO Total:													481.05	
017105	Nov 21, 2013 12:00 AM	7434	2107908 - 01	C	010	5057							1,002.14	COMPLAINT: MACHINE IS LEAKING HYDRAULIC FLUID. CAUSE: HYDRAULIC HOSE COMING FROM HYDRAULIC PUMP TO THE LEFT DRIVE MOTOR WAS RUBBING ON BOTTOM GUARD. CORRECTION: REMOVED BOTTOM GUARD. REMOVED CAB FLOOR PAN. REMOVED HOSE. INSTALLED NEW HOSE. TIED HOSE UP AWAY FROM POTENTIAL RUB SPOTS. REASSEMBLED. REFILLED WITH HYDRAULIC OIL. CHANGED HYDRAULIC FILTERS.
WO Total:													238.11	
017105	Nov 21, 2013 12:00 AM	7434	2107908 - 02	C	014	2529							238.11	COMPLAINT: CYLINDER IS LEAKING. CAUSE: RIGHT HAND LIFT CYLINDER IS LEAKING FROM U-CUP. CORRECTION: DISASSEMBLED CYLINDER. RESEALED. REASSEMBLED. OPERATED AND CHECKED FOR LEAKS.
WO Total:													423.78	
017105	Nov 21, 2013 12:00 AM	7434	2107908 - 03	C	014	6701							423.78	COMPLAINT: BOTH ANGLE BLADE CYLINDERS ARE LEAKING. CAUSE: U-CUP SEALS ARE TORN. CORRECTION: DISASSEMBLED. INSTALLED NEW SEAL KITS.

								REASSEMBLED, OPERATED AND CHECKED FOR LEAKS.	
							WO Total:	1,664.03	
017105	Sep 04, 2013 12:00 AM	7406	2107447 - 01	C	023	7320	445.74	REPLACE BOTH CONDENSER MOTORS	
							WO Total:	445.74	
017105	Aug 23, 2012 12:00 AM	7300	2105315 - 01	C	041	7524	382.90	COMPLAINT: SERVICE DUE CAUSE: TIME CORRECTION: CHANGED ENGINE OIL AND FILTER, REPLACED FUEL AND AIR FILTERS, CLEANED OUT WATER SEPARATOR BOWL, CHECKED ALL OTHER FLUIDS, AND GREASE MACHINE.	
							WO Total:	382.90	
017105	Oct 31, 2011 12:00 AM	7231	2103668 - 01	C	010	1062	44.45	COMPLAINT: MUFFLER IS LEAKING. CAUSE: RUSTED OUT. COMPLICATION: / CORRECTION: REMOVED HOOD. REMOVED MUFFLER. INSTALLED NEW MUFFLER. REASSEMBLED MACHINE.	
							WO Total:	44.45	
017105	Apr 29, 2011 12:00 AM	0	2102669 - 01	C	023	7320	920.37		
							WO Total:	920.37	
017548	Aug 25, 2010 12:00 AM	7000	2101450 - 01	C	540	7525	580.73	COMPLAINT: 500 HOUR SERVICE. CAUSE: / CORRECTION: CHANGED ENGINE OIL. CHANGED ALL LUBE AND FUEL FILTERS. TOOK OIL SAMPLES.	
							WO Total:	580.73	
017548	Jun 24, 2010 12:00 AM	6960	2101141 - 01	C	023	7320	330.47	COMPLAINT: POOR A/C CAUSE: CONDENSOR FAN BAD CORRECTION: CHECKED PRESSURE TO HIGH FOUND CONDENSER MOTOR BAD DID NOT HAVE ONE HAD TO ORDER..COULD NOT GET OLD FAN OFF, INSTALLED NEW FAN ON MOTOR AND INSTALLED IN CONDENSOR UNIT .WASHED OUT EVAPORATOR AND CHECKED CHARGE. OK	
							WO Total:	330.47	