

Print Date: 2015.01.29 at 07:57:11 CST

PIN : DW772DX612926

SPINK COUNTY HIGHWAY DEPT	Customer Number	: 303885125
1518 E 7TH AVE	Purchase Type	: COUNTY
REDFIELD SD US 574691815	End Use Code	: HIGHWAYS & STREETS

Home	:	Delivery Date	: 14 May 2007
Cell	:		
Business	:	US6054720828	

Selling Dealer	:	178711-RDO CONSTRUCTION EQ CO MW,BURNSVILLE,MN
Responsible Dealer	:	178716-RDO CONSTRUCTION EQ CO MW,ABERDEEN,SD

Model	: 772D	Description	: 772D MOTOR GRADER	Model Year	: 2006
Latest Delivery Date	: 14 May 2007	Last Reported Registration Measurement	: 4224		
Machine Build Date	: 19 Apr 2007	Last Reported Claim Measurement	: 5398		
Approximate Cumulative Rental Days*	: N/A				
Machine status 1	: Used Machine				

*See John Deere Warranty System for accumulated rental days/detailed rental history

Warranty Coverage

Warranty type	Coverage term	Expiration Date	Days Remaining (may be estimate)
Basic Warranty	6m/0h	15 Nov 2007	0
StructurALL	36m/10000h	14 May 2010	0
Emissions Warranty	60m/3000h	15 May 2012	0
Extended Warranty (Comprehensive)	84m/8000h	14 May 2014	0

Component Serial Numbers

Component	Serial Number
PUMP, HYD. VARIABLE DISPLACEMENT	SA071203839
GEAR BOX	151170
VALVE, CONTROL, ASSEMBLY	K561
ENGINE CONTROLLER	103147
SEAT, OPERATOR	S5037761
CANOPY	733
PUMP, HYDRO VARIABLE DISPLACEMENT, FRONT	S0107000454
PROPEL DRIVE, RIGHT	CEHDFWB100279
TRANSMISSION	YZTF18C063470
HFWD CONTROLLER	5100229
ROPS, WITH OPERATOR ENCLOSURE	MA370
TRANSMISSION, CONTROLLER	520547
SHIFTER	102839
ENGINE (DEERE MANUFACTURED)	RG6081H297756
VALVE, STEERING	ADR305
PROPEL DRIVE, LEFT	CEHDFWA151296
AXLE	PEAG251237630
VALVE, HYD MECHANICALLY OPERATED	G437

PUMP, HYDRO VARIABLE DISPLACEMENT, REAR	S0107000400
AIR CONDITIONER	498899
MONITOR	600411

Order BASE / Option Codes

Code	Component	Invoice / Transfer Date
9060T2060	14FT MOLDBOARD W/8IN EDGE	20 Apr 2007
9060T2120	BLADE WEAR INSTS-STD DUTY	20 Apr 2007
9060T2220	CRCLE INSRT-NYLON-S.D. NO CL	20 Apr 2007
9060T4420	14R24 SNOW G2 RADIAL TIRE	20 Apr 2007
9060T5020	LOW CAB W FIXED WINDOWS	20 Apr 2007
9060T5520	NO AUTO SHIFT TRANSMISSION	20 Apr 2007
9060T6030	NO PRECLEANER OPTION	20 Apr 2007
9060T6120	DELUXE CLOTH SEAT/AIR SUSPEN	20 Apr 2007
9060T6540	RH 7F CONT VLVE(4+3 AUX)	20 Apr 2007
9060T6620	LH 5F CONT VLVE(4+1 AUX)	20 Apr 2007
9060T7160	DEL LGHT PKG(LED)-SNOW PLOW	20 Apr 2007
9060T7520	1400CCA BATTERIES	20 Apr 2007
9060T9001	10 X 24 MULTI PIECE RIMS	20 Apr 2007
9060T9004	HFWD NARROW FRONT FENDER	20 Apr 2007
9060T9007	ROTARY EJECTOR PRECLEANER	20 Apr 2007
9060T9020	8" OVRLY END BITS,REVERSIBLE	20 Apr 2007
9060T9030	24"LH MOLDBOARD EXTENSION	20 Apr 2007

9060T9140	WIPER-LOWER FRONT WINDOW	20 Apr 2007
9060T9160	RADIO AM/FM/WB	20 Apr 2007
9060T9190	30 AMP CONVERTER 24V TO 12V	20 Apr 2007
9060T9210	PEDAL DECELERATOR	20 Apr 2007
9060T9270	SNOW LIGHT BRACKET	20 Apr 2007
9060T9280	SLOW MOVING VEHICLE EMBLEM	20 Apr 2007
9060T9290	BEACON BRACKET	20 Apr 2007
9060T9360	ENGINE HEATER COOLANT (110V)	20 Apr 2007
9060T9370	ETHER START AID	20 Apr 2007
9060T9510	REAR HITCH AND PIN	20 Apr 2007
9060T9545	TRANS SOLENOID VALVE GUARDS	20 Apr 2007
9060T9620	HYDRAULIC VALVE COVERS	20 Apr 2007

Customer History**Customer 1 of 1**

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD US 574691815

Customer Number : 303885125
Purchase Type : COUNTY
End Use Code : HIGHWAYS & STREETS

Home :
Cell :
Business : US6054720828

Delivery Date : 14 May 2007

Selling Dealer : 178711-RDO CONSTRUCTION EQ CO
MW,BURNSVILLE,MN
Responsible Dealer : 178716-RDO CONSTRUCTION EQ CO
MW,ABERDEEN,SD

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
,
REDFIELD SD 57469

Branch		*REPRINT*	
Date	Time	Page	
07/02/14	18:10:11 (B)	01	
Account No.	Phone No.	Invoice No.	
0828013		W43786	
Ship Via	Purchase Order		
DKE			
GOVT			
			Salesperson
			DCI

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5494	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

REPAIR# 1 C JWR01 STT-25 06/25/14 06/25/14 07/16/14
TRAVEL, ROUND TRIP 1.11 HRS

CONDITION:

FAN DRIVE BEARING HAS FAILED
PARTS AND SERVICE WARRANTY FROM W35471

CORRECTION:

Travel to and from machine location.

	LABOR	47.96
536030AB	REPAIR TOTAL==>	47.96

REPAIR# 3 C JWR01 10-050-121 06/25/14 06/26/14 07/16/14
FAN DRIVESHAFT, R&R 2.00 HRS

CONDITION:

BEARING HAS FAILED

CAUSE:

Fan drive bearing failed.

CORRECTION:

- Removed belt.
- Remvoed pulley.
- Removed fan drive shaft from hub.
- Removed hub from machine.
- Disassembled hub.
- Cleaned hub and assembled with new bearing and retainers.
- Installed hub, drive shaft, pulley, and belt.
- Ran engine.

AE53905	BEARING	1	46.21	46.21
FRTIN	SHIP/HANDLING	1	10.00	10.00
T231645	ADJUSTER NUT	1 N	28.52	28.52
T24513	RING	1 N	5.91	5.91
	PARTS			90.64

CONTINUED ON PAGE 02

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
,
REDFIELD SD 57469

Branch		*REPRINT*	
Date	Time	Page	
05/23/14	17:54:44 (B)	01	
Account No.	Phone No.	Invoice No.	
0828013		W42416	
Ship Via	Purchase Order		
W99/EE4			
GOVT			
		Salesperson	
		DKE	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

REPAIR# 1 C BV301 RDO-050-DIAG 04/16/14 04/17/14 04/30/14

POWER TRAIN DIAGNOSTICS

5.10 HRS

CONDITION:

Extended Warranty - 8,000 - X (Expires: 05/14/2014)

Check Hubs Also

Willie

460-0859

-High levels of metal indicated in last two oil samples.

CAUSE:

Bearing failure in differential.

CORRECTION:

-Remove drain plug, small amount of metal filings were present on drain plug.

-Ordered parts to repair differential.

Had to wash machine in order to perform repair.

-Remove panels, take machine to wash bay and steam clean engine and transmission areas.

-Clean wash bay.

LABOR 550.80

10403099 10501051

REPAIR TOTAL==> 550.80

REPAIR# 2 C BV301 00201A093 04/16/14 04/17/14 04/30/14

FINAL DRIVE SEALANT APPLICATION (FINAL DRIVE TO DIFF.) REPLA 68.00 HRS

CONDITION:

Differential bearing failure.

CAUSE:

Pinion shaft input bearings have failed.

CORRECTION:

Drain tandems, differential.

CONTINUED ON PAGE 02

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
,
REDFIELD SD 57469

Branch

Date

05/23/14

Time

17:54:44 (B)

Page

02

Account No.

0828013

Phone No.

Invoice No.

W42416

Ship Via

W99/EE4

Purchase Order

GOVT

Salesperson

DKE

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

X079444

MOTOR GRADERS

5398

DW772DX612926

11/15/07

9999

772D

RG6081H297756

05/14/14

8000 X

Lift rear of machine, support on stands.

Remove wheels, tandems.

Disconnect all lines to differential.

Remove differential.

Disassemble and inspect for failure.

Found pinion shaft bearings had failed.

Bearing RE49486 was (30) worn severely.

Clean components.

Repair components back to new specification, Input pinion,
right and left planetaries, right and left pivot housings,
and differential.

Complete assembly of differential, pressure test brakes,
differential lock, and air test complete assembly for leaks.

All tests passed.

Install differential to chassis.

Connect all lines, wire harness, and drive shaft.

Flush diff.

Install tandems and tires.

Remove stands.

Operate machine, verify differential temps.

Inspect for any leaks, was dry. Turn in parts for
warrenty.

ADDITIONAL DESCRIPTION:

Key Part: JD8272

General Repair (Fail) Area: DIFFERENTIAL

Failure Type Code: 30

DTAC Case / Solution #:

Labor Hours: 63.62

Diagnostic Hours: 5.10

Cleanup Hours:

CONTINUED ON PAGE 03

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

SAME AS BELOW

Ship to:

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE

REDFIELD SD 57469

Branch

Date

Time

Page

05/23/14

17:54:44 (B)

03

Account No.

Phone No.

Invoice No.

0828013

W42416

Ship Via

Purchase Order

W99/EE4

GOVT

Salesperson

DKE

SERVICE INVOICE

STK#/FLEET#

X079444

MOTOR GRADERS
772D

HRS

5398

PIN/EIN

DW772DX612926
RG6081H297756

WARRANTY DATE

11/15/07
05/14/14

HRS

9999
8000 X

STK#/FLEET#	DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE
AR40418	HOSE CLAMP	1	2.33	2.33
AR75527	SEAL	2	30.16	60.32
AT191095	PUMP	1 N	816.76	816.76
AT306605	HYDRAULIC	1	78.28	78.28
A4365R	O-RING	2	.87	1.74
A4540R	O-RING	1	4.73	4.73
F3171R	O-RING	9	2.31	20.79
JD8159	BEARING CO	1	39.81	39.81
JD8210	BEARING CU	1	19.25	19.25
JD8255	BEARING CU	1	28.31	28.31
JD8272	BEARING CU	4 S	39.43	157.72
JD8989	BEARING CO	4 S	72.15	288.60
JD9078	BEARING CO	1	42.07	42.07
JD9156	BEARING CU	1 S	40.18	40.18
JD9601	BEARING CO	1 S	71.94	71.94
L0034-094	105 LUBE	1	9.55	9.55
PM38657	FORM-GASKE	4	18.92	75.68
P42061	O-RING	1	1.28	1.28
RE45315	SEAL KIT	1	70.31	70.31
RE49486	TAPERED RO	1	272.55	272.55
RE52702	CLAMP	2	11.95	23.90
RE53823	DISK	1 N	39.91	39.91
RE65008	BRAKE DISK	10 S	141.94	1419.40
R112079	THRUST WAS	12	19.71	236.52
R116214	SCREW	12 N	2.68	32.16
R120194	BOLT	12 N	2.68	32.16
R150895	PLATE	12 S	116.84	1402.08
R151088	O-RING	1	3.51	3.51
R26287	O-RING	1	1.04	1.04
R26448	O-RING	4	1.51	6.04

CONTINUED ON PAGE 04

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

SAME AS BELOW

Ship to:

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch		
Date	Time	Page
05/23/14	17:54:44 (B)	04
Account No.	Phone No.	Invoice No.
0828013		W42416
Ship Via	Purchase Order	
W99/EE4		
GOVT		
		Salesperson
		DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X
R26906	O-RING	1	2.27	2.27	
R28782	O-RING	2	1.25	2.50	
R29936	O-RING	1	3.24	3.24	
R34513	RING	2 S	8.72	17.44	
R34857	CLUTCH PLA	1 S	40.76	40.76	
R34858	CLUTCH PLA	5 S	41.79	208.95	
R35365	SHIM	2	2.09	4.18	
R35367	SHIM	3	3.26	9.78	
R375R	O-RING	2	1.18	2.36	
R48776	NUT	1	11.38	11.38	
R51196	SHIM	3	1.94	5.82	
R51197	SHIM	3	2.21	6.63	
R51198	SHIM	1	2.32	2.32	
R51199	SHIM	1	2.64	2.64	
R52389	SHIM	1	5.09	5.09	
R59460	THRUST WAS	4	6.33	25.32	
R60038	PACKING	2	1.75	3.50	
R63575	NEEDLE ROL	288 S	1.54	443.52	
R70112	THRUST WAS	4	3.75	15.00	
R70113	THRUST WAS	4 S	1.51	6.04	
R70115	NEEDLE ROL	104 S	.34	35.36	
R78065	SOCKET CON	2	1.22	2.44	
R93623	THRUST WAS	2	23.02	46.04	
R95116	PISTON	1 S	67.01	67.01	
TY22465	HOSE CLAMP	2	.96	1.92	
TY22467	CLAMP	2	.96	1.92	
TY22473	CLAMP	1	1.16	1.16	
TY22562	BULK HOSE	1	.20	.20	
TY22563	BULK HOSE	2	.30	.60	
TY24415	BULK HOSE	4	1.97	7.88	
T157952	SNAP RING	6 N	18.04	108.24	

CONTINUED ON PAGE 05

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

SAME AS BELOW

Ship to:

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch

Date

Time

Page

05/23/14

17:54:44 (B)

05

Account No.

Phone No.

Invoice No.

0828013

W42416

Ship Via

Purchase Order

W99/EE4

GOVT

Salesperson

DKE

SERVICE INVOICE

STK#/FLEET#

HRS

PIN/EIN

WARRANTY DATE

HRS

X079444

MOTOR GRADERS

5398

DW772DX612926

11/15/07

9999

772D

RG6081H297756

05/14/14

8000 X

T158511

GASKET

1 N

5.09

5.09

T158580

O-RING

4

20.43

81.72

T160541

O-RING

1 N

6.43

6.43

T205818

RADIATOR H

1

56.61

56.61

T215515

WEAR RING

4

100.07

400.28

T215516

THRUST WASHER

12

19.70

236.40

T217194

HOSE

1 N

79.84

79.84

T41677

O-RING

1

6.73

6.73

U12547

O-RING

1

1.63

1.63

U17409

O-RING

7

3.24

22.68

YZ120167

WASHER

1

2.54

2.54

YZ120398

COMPRESSION SPR

3 N

1.71

5.13

YZ120442

HOUSING

1 N

658.70

658.70

YZ121809

Clutch Disk

4 N

39.91

159.64

YZ123334

Seal

2

12.19

24.38

07485

SURFACE COND

6

3.41

20.46

11M7032

COTTER PIN

1

.41

.41

19H2668

CAP SCREW

8

2.30

18.40

19M7417

CAP SCREW

32 S

3.16

101.12

19M8190

CAP SCREW

24 N

7.48

179.52

24M7338

WASHER

2

1.63

3.26

57M7534

ELEC. CONN

1

2.36

2.36

57M7620

ELECTRICAL

1

.30

.30

PARTS

8464.06

LABOR

6870.96

10501051

REPAIR TOTAL==>

15335.02

REPAIR# 3 C LSD01 00250A041 04/16/14 04/17/14 04/30/14

TANDEM DRIVE OUTBOARD HUB BEARING(S) & SEAL, REPLACE- RT REA 7.80 HRS

CONDITION:

Found LH front hub on tandems leaking oil out of seals.

CONTINUED ON PAGE 06

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch

Date

05/23/14

Time

17:54:44 (B)

Page

06

Account No.

0828013

Phone No.

Invoice No.

W42416

Ship Via

W99/EE4

Purchase Order

GOVT

Salesperson

DKE

SERVICE INVOICE

STK#/FLEET#

X079444

MOTOR GRADERS
772D

HRS

5398

PIN/EIN

DW772DX612926
RG6081H297756

WARRANTY DATE

11/15/07
05/14/14

HRS

9999
8000 X

CAUSE:

Found oil leaking at wheel flange to hub seal.

CORRECTION:

Left

hub was removed. Disassembled hub and removed old bearings.
Cleaned all parts and reassembled with new seals and bearings.

BRAD-

-Drained tandem oil, remove drive chain to front spindle
-Removed spindle from tandem.
-After repair to spindle complete.
-Installed spindle, connect chain, fill tandem with oil.
-Operate and inspect for leaks, was dry.

ADDITIONAL DESCRIPTION:

Key Part: AT363653

General Repair (Fail) Area: WHEEL HUB

Failure Type Code: 14

DTAC Case / Solution #:

Labor Hours: 5.25

Diagnostic Hours:

Cleanup Hours:

STK#	DESCRIPTION	QTY	UNIT	PRICE	TOTAL
AT363653	SEAL	1	N	290.10	290.10
JD8962	BEARING CO	1	S	55.42	55.42
JD9080	BEARING CO	1	S	86.36	86.36
JD9120	BEARING CU	1	S	49.85	49.85
JD9138	BEARING CU	1	S	50.73	50.73
R26448	O-RING	1		1.51	1.51
R28782	O-RING	1		1.25	1.25
T158339	O-RING	1		6.54	6.54

CONTINUED ON PAGE 07

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to: SAME AS BELOW

Invoice to: SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch		
Date	Time	Page
05/23/14	17:54:44 (B)	07
Account No.	Phone No.	Invoice No.
0828013		W42416
Ship Via		Purchase Order
W99/EE4		
GOVT		
		Salesperson
		DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X
T158340	GASKET	1 S	7.99	7.99	
T158513	GASKET	2 N	9.12	18.24	
T41677	O-RING	1 S	6.73	6.73	
U17409	O-RING	1 S	3.24	3.24	
YZ123335	Seal	1 S	12.16	12.16	
11M7021	COTTER PIN	1	.30	.30	
			PARTS	590.42	
			LABOR	567.00	
10501051			REPAIR TOTAL==>	1157.42	

REPAIR# 5 C BV301 00201A038 04/16/14 04/26/14 04/30/14
TANDEM DRIVE OUTBOARD HUB, REPLACE-REAR RIGHT REAR 7.60 HRS

CONDITION:

Right side tandem, front spindle is leaking oil.

CAUSE:

Spindle seal is leaking.

CORRECTION:

Drain tandem, remove drive chain to front spindle.

Lucase removed spindle then replaced bearings and seal.

Installed spindle, chain, and covers.

Filled tandem with new oil.

Operate and inspect for leaks, was dry.

ADDITIONAL DESCRIPTION:

Key Part:AT363653

General Repair (Fail) Area: OUTBOARD HUB

Failure Type Code: 14

DTAC Case / Solution #:

Labor Hours: 7.06

Diagnostic Hours:

Cleanup Hours:

CONTINUED ON PAGE 08

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the Invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch			
Date	Time	Page	
05/23/14	17:54:44 (B)	08	
Account No.	Phone No.	Invoice No.	
0828013		W42416	
Ship Via	Purchase Order		
W99/EE4			
GOVT			
		Salesperson	
		DKE	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

11M7085	COTTER PIN	1	.52	.52
			PARTS	.52
			LABOR	762.48
10501051	REPAIR TOTAL==>			763.00

REPAIR# 6 C BV301 MULTIPLE 04/16/14 04/26/14 04/30/14
TRANSMISSION - R&I 24.60 HRS

CONDITION:

Fly wheel housing leaking oil.

CAUSE:

Anerobic sealant, pm38657 sealant is brittle and hard,
allowing oil to leak.

CORRECTION:

Remove components to access transmission.
Remove hydraulic pumps, lines, wire harness to
transmission.
Lift transmission from chassis.
Clean sealing surface of transmission/flywheel housing.
Install transmission and all componants.
Run machine, inspect for fluid leaks.
Top off hydraulic reservior.
Calibrate Transmission and HFWD.

ADDITIONAL DESCRIPTION:

Key Part: pm38657
General Repair (Fail) Area: FLYWHEEL HOUSING
Failure Type Code: 14
DTAC Case / Solution #:
Labor Hours:23.24
Diagnostic Hours:

CONTINUED ON PAGE 09

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch

Date

Time

Page

05/23/14

17:54:44 (B)

09

Account No.

Phone No.

Invoice No.

0828013

W42416

Ship Via

Purchase Order

W99/EE4

GOVT

Salesperson

DKE

SERVICE INVOICE

STK#/FLEET#

HRS

PIN/EIN

WARRANTY DATE

HRS

X079444

MOTOR GRADERS

5398

DW772DX612926

11/15/07

9999

772D

RG6081H297756

05/14/14

8000 X

Additional SPG: 00300A007 00260A167

AT310272	Hose	1 N	31.06	31.06
F37020159	O-RING	1	4.16	4.16
HDXASP20	HYDREX 5 GAL	1	105.81	105.81
H77698	TIE BAND	30	.28	8.40
PM38657	FORM-GASKE	2	18.92	37.84
P50631	O-RING	1	3.78	3.78
TY22562	BULK HOSE	43	.20	8.60
T186987	SUCTION HOSE	1 N	42.54	42.54
T210520	SUCTION HOSE	1 N	45.79	45.79
20100	CLEANER	2	5.95	11.90
24H1327	WASHER	1	.78	.78
6635	1/4 HOSE	3	1.81	5.43

PARTS 306.09

LABOR 2509.92

10501051

REPAIR TOTAL==> 2816.01

REPAIR# 7 C LSD01 00433C010 04/16/14 04/28/14 04/30/14
FLYWHEEL HOUSING OR GASKET - REPLACE WITH TRANSMISSION OUT O 2.60 HRS

CONDITION:

Customer states flywheel housing and starter are leaking,
and would like torsional isolator inspected for wear also.

CAUSE:

Found flywheel housing and starter gaskets leaking
transmission oil.

CORRECTION:

Transmission previously removed. Removed torsional
isolator, cleaned, and inspected for wear in springs. Found
good. Removed flywheel housing rear engine mounts. Found 1
broken bolt in engine mount on right side. Removed starter

CONTINUED ON PAGE 10

Stocked parts can be returned within 30 days with copy of invoice. Special
order parts \$20.00 and up may be returned within 30 days with copy of
invoice. 20% restock charge will apply to all special order parts. All sales
are final on special order non-returnable parts. All parts must be new,
uninstalled and in original packaging. No returns on electrical components.
No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the
invoice date or in accordance with the terms of your account agreement.
Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to: SAME AS BELOW

Invoice to: SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch		
Date	Time	Page
05/23/14	17:54:44 (B)	10
Account No.	Phone No.	Invoice No.
0828013		W42416
Ship Via	Purchase Order	
W99/EE4		
GOVT		
		Salesperson
		DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

and replaced starter to engine block gasket. Replaced both flywheel turning hole plug and timing lock plug. Cleaned flywheel housing and block of gasket material. Reinstalled flywheel housing and starter with new gaskets and torqued bolts to specification. Reinstalled torsional isolator and torqued bolts to specification.

ADDITIONAL DESCRIPTION:

Key Part: R518995

General Repair (Fail) Area: FLYWHEEL

Failure Type Code: 14

DTAC Case / Solution #

Labor Hours: 2.6

Diagnostic Hours:

Cleanup Hours:

AR61533	PLUG	1	8.54	8.54
AR61589	PLUG	1	7.11	7.11
R518995	GASKET	2	32.52	65.04
R53108	GASKET	1	3.66	3.66
20100	CLEANER	1	5.95	5.95

PARTS 90.30

LABOR 280.80

10501051

REPAIR TOTAL==> 371.10

REPAIR# 8 C LSD01 NA 04/29/14 04/29/14 05/22/14

Extract 1 Broken Bolt. Repair Hole.

1.08 HRS

CONDITION:

Technician states there is a broken bolt through the right rear engine mount to flywheel housing.

CAUSE:

CONTINUED ON PAGE 11

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch		
Date	Time	Page
05/23/14	17:54:44 (B)	11
Account No.	Phone No.	Invoice No.
0828013		W42416
Ship Via	Purchase Order	
W99/EE4		
GOVT		
		Salesperson
		DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

Found broken bolt in flywheel housing fastening right rear engine mount.

CORRECTION:

Drilled out bolt after removal of flywheel housing. Cleaned hole and drilled to final hole size for heli-coil tap. Tapped hole and cleaned threads. Inserted heli-coil and locked into place. Replaced bolt.

ADDITIONAL DESCRIPTION:

=====
Key Part:19H2993
General Repair (Fail) Area: ENGINE MOUNTS
Failure Type Code:3
DTAC Case / Solution #:
Labor Hours:1.08
Diagnostic Hours:
Cleanup Hours:
=====

19H2993	CAP SCREW	1	1.41	1.41
			PARTS	1.41
			LABOR	116.64
10501051	REPAIR TOTAL==>			118.05

REPAIR# 9 C BV301 00360C130 04/16/14 05/01/14 04/30/14
TRANSMISSION CHARGE PUMP (REPLACE WITH TRANSMISSION OUT) 4.60 HRS

CONDITION:

Transmission oil samples have been positive with aluminum.

CAUSE:

Transmission charge pump gears starting to wear on pump housing which is aluminum.

CORRECTION:

Remove pump from transmission, disassemble on bench.

CONTINUED ON PAGE 12

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
,
REDFIELD SD 57469

Branch		
Date	Time	Page
05/23/14	17:54:44 (B)	12
Account No.	Phone No.	Invoice No.
0828013		W42416
Ship Via	Purchase Order	
W99/EE4		
GOVT		
		Salesperson
		DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

Found drive gear inside pump had been wearing on pump case.
Was able to fill a ledge in pump case where gear was running.

Orderd new pump.
Install new pump and pickup tube.
Operate transmission and verify operation.
Calibrate transmission.

ADDITIONAL DESCRIPTION:

=====

Key Part: YZ106550
General Repair (Fail) Area: TRANSMISSION
Failure Type Code: 23
DTAC Case / Solution #:
Labor Hours:2.3
Diagnostic Hours:
Cleanup Hours:

FRTIN	SHIP/HANDLING	1	100.40	100.40
F37030250	O-RING	1 S	5.46	5.46
YZ106550	OIL PUMP	1 N	1306.03	1306.03
	PARTS			1411.89
	LABOR			248.40
10501051	REPAIR TOTAL==>			1660.29

REPAIR# 18 C LSD01 00250A041 04/16/14 05/23/14 04/30/14
TANDEM DRIVE OUTBOARD HUB BEARING(S) & SEAL, REPLACE- RT REA 7.80 HRS

CONDITION:

Found RH front hub on tandems leaking oil out of seals.

CAUSE:

Found oil leaking at wheel flange to hub seal.

CORRECTION:

CONTINUED ON PAGE 13

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
,
REDFIELD SD 57469

Branch ABERDEEN, SD		Page 13
Date 05/23/14	Time 17:54:44 (B)	
Account No. 0828013	Phone No. 605 4725009	Invoice No. W42416
Ship Via W99/EE4		Purchase Order
GOVT		Salesperson DKE

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	MOTOR GRADERS	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

Removed 1 hub from right tandem and cleaned holes and bolts. Disassembled hub and removed old bearings. Cleaned all parts and reassembled with new seals and bearings.

ADDITIONAL DESCRIPTION:

Key Part: AT363653

General Repair (Fail) Area: WHEEL HUB

Failure Type Code: 14

DTAC Case / Solution #:

Labor Hours: 4.8

Diagnostic Hours:

Cleanup Hours:

AT363653	SEAL	1 N	290.10	290.10
JD8962	BEARING CO	1 N	55.42	55.42
JD9080	BEARING CO	1 N	86.36	86.36
JD9120	BEARING CU	1 N	49.85	49.85
JD9138	BEARING CU	1 N	50.73	50.73
R26448	O-RING	1	1.51	1.51
R28782	O-RING	1	1.25	1.25
T158339	O-RING	1 S	6.54	6.54
T158340	GASKET	1	7.99	7.99
T158513	GASKET	2	9.12	18.24
U17409	O-RING	1	3.24	3.24
YZ123335	Seal	1 S	12.16	12.16
11M7021	COTTER PIN	3	.30	.90
	PARTS			584.29
	LABOR			518.40
10501051	REPAIR TOTAL==>			1102.69

***** WORK ORDER TOTALS *****

CONTINUED ON PAGE 14

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch		*REPRINT*	
Date	Time	Page	
05/08/14	18:03:57 (B)	01	
Account No.	Phone No.	Invoice No.	
0828013		W42576	
Ship Via	Purchase Order		
DKE			
GOVT			
			Salesperson
			DCI

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	772D MOTOR GRADER	5398	DW772DX612926	11/15/07	9999
	772D		RG6081H297756	05/14/14	8000 X

REPAIR# 1 C LSD01 NA 04/25/14 04/29/14 04/30/14

CHANGE HUB OIL

CONDITION:

Customer states front hub oil needs to be replaced.

CAUSE:

hubs due for oil change.

CORRECTION:

Lifted front wheels off of ground and rotated to drain oil.
Drained oil and tightened plug. Rotated to fill hubs and
filled to bottom of fill plug. Let oil settle and topped
off hubs. Cleaned hubs, wheels, and tires of left over oil
and set front wheels back on ground.

TY22028	HY GARD	13	2.92		37.96
X1J043-6-6	FITTING	2	18.63		37.26
X11L43-8-6	ELBOW FITTING	2	29.54		59.08
X471TC-6-RL	BULK HOSE	2	5.43		10.86
20100	CLEANER	2	5.95		11.90
	PARTS				157.06
	LABOR				216.00
10403099	REPAIR TOTAL==>				373.06

REPAIR# 2 C LSD01 NA 04/25/14 04/29/14 04/30/14

LEAKING HYD HOSE

CONDITION:

Change leaking hose on front end

CAUSE:

Found 2 short hoses leaking to front auxiliary cylinder.

CORRECTION:

Raised and supported front auxiliary attachment with a
chain. Released hydraulic pressure and removed hoses and

CONTINUED ON PAGE 02

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.

EQUIPMENT CO.

Ship to:

SAME AS BELOW

Invoice to:

SPINK COUNTY HIGHWAY DEPT
1518 E 7TH AVE
REDFIELD SD 57469

Branch

Date

05/08/14

Time

18:03:57 (B)

Page

02

Account No.

0828013

Phone No.

Invoice No.

W42576

Ship Via

DKE

Purchase Order

GOVT

Salesperson

DCI

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X079444	772D MOTOR GRADER	5398	DW772DX612926	11/15/07 9999
	772D		RG6081H297756	05/14/14 8000 X

capped hose ends. Replaced both short stub hoses from cylinder with new ones and torqued to specification. Raised auxiliary attachment up, removed chain and cycled cylinder to bleed air from lines. Topped off hydraulic oil.

	LABOR	108.00
10403099	REPAIR TOTAL==>	108.00

REPAIR# 3 C BV301 10-040-210 04/25/14 04/30/14 04/30/14

SWITCH, TRANSMISSION FILTER RESTRICTION - R&R

CONDITION:

-Change filter and oil (transmission)

CAUSE:

-High levels of aluminum in transmission oil samples

CORRECTION:

-Remove transmission filter, cut open and inspect for aluminum.

-Found very small amount of aluminum in filter pleats.

-Install new filter.

-Found source of aluminum, Transmission charge pump.

-Fill with new oil.

AT305049	TRANS FILT	1	83.79	83.79
----------	------------	---	-------	-------

PARTS 83.79

LABOR 162.00

10403099	REPAIR TOTAL==>	245.79
----------	-----------------	--------

***** WORK ORDER TOTALS *****

PARTS 240.85

LABOR 486.00

164984	8850209600	TOTAL POWERPLAN B/F	726.85
--------	------------	---------------------	--------

CONTINUED ON PAGE 03

Stocked parts can be returned within 30 days with copy of invoice. Special order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

SIGNATURE

TERMS AND CONDITIONS: All invoices are due Net-20 days from the invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.