

Date	Invoice No.
9/6/2007	5348

Phil Knight 1330 18th Rd Lyons, KS 67554

Key Tag #	Terms
	Due on receipt

1	fear	Vehicle Make/Model	Mileage	VIN	Transmissi	on I	Engine	
	350	73 Chevy C60		CCE613V127291	TO COLOR AND THE			
Qty	Item		Desc	ription	PORTIGORIA EL PRIMA LA TRANSICIO CONTROLITA UNI UNI UNI SI CALANTI REPUBBIRINA DA CARANTI REPUBBIRI DE CARANTI El PRIMA CARANTI EL PRIMA CARANTI CONTROLITA UNI UNI UNI UNI CARANTI REPUBBIRI PARA CARANTI CARANTI CARANTI C	Price	Amount	
1 1 1 1 1 1 1 7 4	85794 58-139 60206 20904 86033 A01595 F17250 42052 601-1409 30-1845 1009 33030 86271 40987 279124 583A FL20 15W40 antifreeze hardware	Jasper 350 engine 30 oil filter water pump prem t-stat stat gskt fuel filter water outlet exh gasket grommet shaft distributor dist holddown radiator cap fuel filter fuel pump heater core carb kit float ROTELLA gal. antifreeze parts prep solvent silicone per pint pwr clean ste Parts Subtotal				2,167.10 15.22 69.66 10.98 1.39 6.41 19.31 3.00 4.25 15.14 274.50 8.79 8.55 4.43 26.86 36.81 20.33 17.60 2.96 8.58 22.75 2.99 4.50 7.29	2,167.10 15.22 69.66 10.98 1.39 6.41 19.31 6.00 4.25 15.14 274.50 8.79 8.55 4.43 26.86 36.81 20.33 17.60 20.72 34.32 22.75 11.96 4.50 14.58 2,822.16	
erino controlos	BATANTA Provincia de servicio de sel Angelo de se		A DINN BACKALI YANGAN MENGANTAN TERBANDAN TING ARI SILI BANKALI KEPANCISTI SILI BANKALI KEPANCISTI SILI BANKALI		Subtotal	CONTRACTOR OF STREET HER STREET AND STREET A		
XWARRANTIES ARE NON-TRANSFERABLE					Sales Tax			
				STEPACINET AND ADMITS COMMITTED TO THE STEPACINET AND ADM	Total			
				C	Customer Total Balance			



Date	Invoice No.			
9/6/2007	5348			

Phil Knight 1330 18th Rd Lyons, KS 67554

Key Tag #	Terms
	Due on receipt

Year Vel		Vehicle Make/Model Mileage VIN		VIN	Transmis	sion	Engine
	350	73 Chevy C60	The second secon	CCE613V127291		An environment of the contract	
Qty	Item		Description		Price	Amount	
	labor/CG labor/CG labor/CG labor/CG shop supp	distributor that was in the problems, we also previous repairs to er time for replacing oil rebuild carburator - fl rplc leaking heater co Labor Subtotal	nstalled did not tur o rplcd items that v nsure reliable opera pump drive shaft loat mount loose	block assembly, found in the oil pump, this were less than par and ation.	as the cause of	1,383.34 276.68 138.34 131.42 5.50	1,383.34 276.68 138.34 131.42 1,929.78 5.50
except the all other to your	ala en en esta en eja en especial de la California de la		PPP BROWNESSANS (In the PROPERTY PROPERTY OF A SAME WILLIAM STEEL STEEL STEEL AND A SAME WAY A SAME		Subtotal	MINISTER EXPRESSED CONTROL FOR A STATE OF THE STATE OF TH	\$4,757.44
X_	THE COLUMN				Sales Tax		\$0.00
damag repairs	es to vehicle or it thereto. Labor i	erms of this agreement (additional on reverse is may operate vehicle for inspection, testing, tems left in it. An express Mechanics Lien is a is guaranteed for 90 days or 4000 miles which tturer. Warranty work is based on this repair	delivery at my risk. You wi acknowledged on above veh never comes first. All other	Il not be responsible for loss sicle to secure the amount	Total	\$4,	757.44
		Tepair	and order must be perform	ieu at uns situp.	Continue Total	The I was a second to the seco	erende anvälmige i in grevent løyer til det en d

Customer Total Balance