## **Invoice**

Date	Invoice #
2/5/2015	5056

Bill To

Crossroads Building Co. 6920 McVey Rd. Sedalia, MO 65301



P.O. Number	Terms	Past Due Accounts are subject to a Finance	
	Due on receipt	Charge of 1.5% per month (18% APR).	

FEIN: 46-2060099

Quantity	Item Code	Description	Price / Rate	Amount
20	Repair Shop Service	11/17/2014 - 01/23/2015 Terex 40' Boom - Complaint: Machine won't run; Work: Replaced timing belt on engine; Replaced alternator belt; Installed carburetor kit and dead-man switch; Installed new drive joystick	87.00	1,740.00
2	Repair Service Truck	Responded to Windsor Sale Barn to get unit running long enough to load for pick-up to bring back to shop	125.00	250.00
2	Pick Up / Delivery	Low-boy Pick up machine and deliver to shop	125.00	250.00
1 1 1 1 1	Shop Parts Shop Parts Shop Parts Shop Parts Shop Parts Freight	Dead-man switch Drive Joystick Carburetor Kit Timing Belt Alternator Belt For parts	241.08 664.71 114.74 144.34 26.31 113.42	241.08T 664.71T 114.74T 144.34T 26.31T 113.42