

Mitchell Crane

Invoice

Remit to:
P.O. Box 7197
Bryan, TX 77801
800-826-5612

Billing Inquiries:
10600 Wallisville Rd.
Houston, TX 77013
713-674-7846

Customer No.: L.G. BAR02
Invoice No.: 93895

BILL To: L.G. Barcus & Sons /TX
1430 State Ave.
Kansas City, KS 66102

Ship To: Mitchell Crane
10600 Wallisville Rd. ~~RECEIVED~~
Houston, TX 77013

Date	Ship Via	F.O.B.	Terms		
03/26/12	Service/LS118	Origin	Due on receipt		
Purchase Order Number		Order Date	Sales Person	Our Order Number	
BG03091206		03/09/12	Doug Simon		89449
Required	Quantity Shipped	Item Number B.O.	Description	Unit Price	Amount

Link-Belt LS118
Serial No.: 9LV4685
unit no. 118

BRYAN SHIPMENT*

Unloaded and inspected
unit at Houston, TX
yard.

Removed track pads from
both side and removed all
upper carrier track rollers.

Removed both LH and RH
drive tumbler assemblies.
Drained deck gear oil.

Removed (4) lower track
rollers. Replaced engine
air filter.

Replaced torque converter
oil filter. Removed fleeting
sheave and replaced bushing.

Added new 80/90 gear oil
to machinery deck. Replaced
all brass in drive tumblers.

Replaced all axles/brackets
for upper carrier rollers.
Reinstalled lower track roll

Installed both LH and RH

We accept Visa, MasterCard and American Express

ALL MANUFACTURERS' NAMES, NUMBERS, SYMBOLS, AND DESCRIPTIONS ARE USED FOR REFERENCE PURPOSES ONLY, AND IT IS NOT
IMPLIED THAT ANY PART LISTED AND OFFERED BY MITCHELL CRANE IS THE PRODUCT OF THESE MANUFACTURERS.
ALL RETURNS REQUIRE PRIOR APPROVAL AND MAY BE SUBJECT TO A RESTOCKING FEE.
PAYABLE IN U.S. FUNDS ONLY!

Thank You!

Mitchell Crane

Invoice

Remit to:
P.O. Box 7197
Bryan, TX 77801
800-826-5612

Billing Inquiries:
10600 Wallisville Rd.
Houston, TX 77013
713-674-7846

Customer No.: L.G. BAR02
Invoice No.: 93895

Bill To: L.G. Barcus & Sons /TX
1430 State Ave.
Kansas City, KS 66102

Ship To: Mitchell Crane
10600 Wallisville Rd.
Houston, TX 77013

Date	Ship Via	F.O.B.	Terms	
03/26/12	Service/LS118	Origin	Due on receipt	
Purchase Order Number	Order Date	Sales Person	Our Order Number	
BG03091206	03/09/12	Doug Simon	89449	
Quantity Required	Quantity Shipped	B.O.	Item Number	Description
				drive tumblers and drive chains. Installed track pads
				Adjusted and made shims from drive tumbler assemble
				Adjusted both LH and RH tracks.
				Replaced boom hoist cable and installed. Adjusted (6) hook roller assemblies.
				Tested the machine and OK at this time.

Mitchell Crane

Invoice

Remit to:
P.O. Box 7197
Bryan, TX 77801
800-826-5612

Billing Inquiries:
10600 Wallisville Rd.
Houston, TX 77013
713-674-7846

Customer No.: L.G. BAR02
Invoice No.: 96937

Bill To: L.G. Barcus & Sons /TX
1430 State Ave.
Kansas City, KS 66102

Ship To: Mitchell Crane
10600 Wallisville Rd.
Houston, TX 77013

Date	Ship Via	FOB	Terms	
01/14/13	Service Call	Origin	Due on receipt	
Purchase Order Number	Order Date	Sales Person	Our Order Number	
BG-01111308	12/14/12	Doug Simon	91990	
Quantity Required	Shipped	B.O.	Description	Unit Price
			Link-Belt LS-118 Serial No.: 9LV4685 Unit # 118	Amount

Inspection to be completed
and determine what repairs
to be made on entire machine

Unloading of crane at
Mitchell Crane facility on
12.14.12

Vertical swing shaft
seal leaking. Replaced
oil seal.

Removed rear drum
laggings from unit and
replace w/ new ones.

Laggings supplied by
customer.

Main rear drum cable
replaced. (1) hook roller
bearing assy. replaced.

Installed hydraulic pressure
switch supplied by customer.

Lattice boom repaired
(3) lattice replaced total.

Machinery deck full of water
and repalced with fresh oil

We accept Visa, MasterCard and American Express

ALL MANUFACTURERS' NAMES, NUMBERS, SYMBOLS, AND DESCRIPTIONS ARE USED FOR REFERENCE PURPOSES ONLY, AND IT IS NOT
IMPLIED THAT ANY PART LISTED AND OFFERED BY MITCHELL CRANE IS THE PRODUCT OF THESE MANUFACTURERS.
ALL RETURNS REQUIRE PRIOR APPROVAL AND MAY BE SUBJECT TO A RESTOCKING FEE.
PAYABLE IN U.S. FUNDS ONLY!

Thank You!