

CUSTOMER #: 151585

F2364
238933

INVOICE

DAVID LEE BROUGH

333 33 1/2 RD

PALISADE, CO 81526-9512

HOME: 303-549-4034 CONT: 303-549-4034

BUS: 303-549-4034 CELL:

PAGE 1

SERVICE ADVISOR:

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
WHITE	11	DODGE E		3D6WU7CLXBG502679			111329/111333		TG066
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
23SEP10 DD			17:30 27MAR15				CASH	26MAR15	

R.O. OPENED

BOOKED

OPTIONS: STK:C102679 DLR:44304

ENG:ETJ_6.7L_I6_Cummins_Turbo_Diesel_Engine

TRN:DG3_6-Spd_Auto_AISIN_AS68RC_Transmission

11:23 19MAR15

16:25 26MAR15

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

A TOW IN- CLIENT STATES THE TRANSMISSION IS SHOT. PLEASE CHECK AND

ADVISE

CAUSE: transmission internal failure, abs and engine diagnostic trouble codes

21 TRANSMISSION-T/AXLE

2311 W

1 R8012492AJ TRANS-WITH TORQUE CONVERTER

CORE CHARGE W

3 5189977AB *FLUIDAFT-AUTOMATIC TRANSMISSION

1 4796268 *CLEANER-TRANSMISSION

(N/C)

(N/C)

(N/C)

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

111333 transmission internal failure, abs and engine diagnostic trouble codes 7.60 limp vehicle into shop, slipping badly, wants to move in reverse direction in neutral, fluid full and very black and burnt, smoke coming out of dipstick tube, tcm dtc list: p0706, p0776, p0756, p0761, p0730, p0796, p0766, p2742, cleared dtc list and p0766 returned, perform powertrain authorization procedure, remove and replace AS68RC 4x4 auto trans with skid plate and two piece shaft, reverse flush and flow check cooler system, fill, quick learn and road test for operation

B PERFORM N/C 23 POINT INSPECTION

CAUSE: SEASONAL INSPECTION

INSP PERFORM N/C 23 POINT INSPECTION

2311 C

0.00

0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C** ABS UPDATE

CAUSE: replace broken rear speed sensor connector

08 ELECTRICAL OPS

2311 W

1 5083210AA WIRING-2 WAY

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

111333 replace broken rear speed sensor connector found broken rear

THANK YOU

FOR BRINGING

YOUR VEHICLE

TO US

FOR SERVICE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
GROSS TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: 151585

238933

INVOICE

DAVID LEE BROUGH

333 33 1/2 RD

PALISADE, CO 81526-9512

HOME: 303-549-4034 CONT: 303-549-4034

BUS: 303-549-4034 CELL:

PAGE 2

SERVICE ADVISOR:

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
WHITE	11	DODGE E		3D6WU7CLXBG502679		111329/111333		TG066
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
23SEP10 DD			17:30 27MAR15			CASH	26MAR15	

R.O. OPENED		BOOKED		OPTIONS: STK:C102679 DLR:44304			
				ENG:ETJ_6.7L I6 Cummins Turbo Diesel Engine			
11:23 19MAR15		16:25 26MAR15		TRN:DG3_6-Spd Auto AISIN AS68RC Transmission			
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

,,, wheel speed sensor connector and wires, replace connector

D** CLIENT STATES THE CEL IS ON PLEASE CHECK AND ADVISE

CAUSE: no repairs done at this time

09 ENGINE CONCERN

2311 C				0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00
TOTAL LINE D:				0.00	0.00

,,, 111333 no repairs done at this time

E** CUSTOMER PAY DEDUCTABLE

01 RECOMMENDED SERVICE

2311 CDED				0.00	0.00
MISC CUSTOMER PAY DEDUCTIBLE					
CDED				4200.00	4200.00
PARTS:	0.00	LABOR:	0.00	OTHER:	4200.00
TOTAL LINE E:				4200.00	4200.00

MISC CUSTOMER PAY DEDUCTIBLE

EST: 120.00	19MAR15 11:23	SA: 2331
EST: 11,293.00	25MAR15 11:37	SA: 2331
EST: 15,493.00	26MAR15 16:06	SA: 2331

EST: 120.00 19MAR15 11:23 SA: 2331

EST: 11,293.00 25MAR15 11:37 SA: 2331

CONTACT: L

EST: 15,493.00 26MAR15 16:06 SA: 2331

CONTACT:

**THANK YOU
FOR BRINGING
YOUR VEHICLE
TO US
FOR SERVICE**

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	4200.00
TOTAL CHARGES	4200.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	4200.00