

1995 CAT 990, S/N 7HK00120

Order	Notification	Equipment	Description	Total act.costs	Basic fin. date
10463954	80887474	10026426	Headlights our on 990	64.24	09/19/2008
10459717	80876116	10026426	990 Headlight Out	30.12	08/08/2008
10454521	80860879	10026426	111-4F3 990 Losing Power	158.81	07/10/2008
10451274	80858322	10026426	REPLACE THE BUCKET TOOTH & ADAPTER	219.07	06/20/2008
10451685	80858948	10026426	REPLACE THE A/C FAN MOTOR	151.15	09/11/2008
10443078	80836657	10026426	990 Loader Horn Quit	0.00	04/24/2008
10409134	80769062	10026426	990 Loader Armrest Needs Replacing	424.15	01/31/2008
10405157	80759068	10026426	Broken Grease Line on 990 Loader	175.01	10/16/2007
10404167	80759134	10026426	HORNS STOP WORKING	76.76	10/15/2007
10401065	80753325	10026426	CHECK A/C-NOT COOLING GOOD	64.08	09/28/2007
10397006	80743193	10026426	REPLACE REAR STEPS	158.12	09/24/2007
10394548	80737604	10026426	REPLACE THE BUCKET TEETH	197.40	09/04/2007
10388574	80717647	10026426	990 Loader Pin in Bucket Leaking	294.42	08/06/2007
10389349	80721173	10026426	990 Loader Pin in Bucket Leaking	0.00	08/10/2007
10381377	80707187	10026426	990 Loader has Hydraulic Leak	1,781.90	08/28/2007
10381137	80707708	10026426	990 LOADER/A/C COMPRESSOR NOT WORKING	2,209.15	06/26/2007
10300751	80536187	10026426	990 LOADER/STEP BROKE OFF	990.27	04/25/2006
10298526	80530080	10026426	990 LOADER/DRIVE SHAFT BROKEN	8,082.74	04/13/2006
10298821	80530003	10026426	990 Loader Bucket TIP BROKEN OFF	64.83	04/03/2006
10285740	80500203	10026426	990 LOADER/HYDRAULIC LEAK	1,267.70	01/23/2006
10284037	80497207	10026426	990 LOADER/TEETH BROKEN ON THE BUCKET	303.10	01/12/2006
10281695	80493864	10026426	990 LOADER/HYDRAULIC LEAK	238.70	03/28/2006
10483328	80934877	10026426	REPAIR LIGHTS	73.94	12/19/2008
10477204	80919438	10026426	REPLACE EXHAUST PIPES	0.00	11/07/2008
10473141	80895407	10026426	111-4F3 Controller not locking in on 990	127.69	10/24/2008
10473142	80908547	10026426	REPAIR THE HORNS	118.71	11/14/2008
10475087	80913509	10026426	ROD BROKEN ON THE TILT CYLINDER	162.68	11/04/2008
10470853	80900549	10026426	990 horn and heater hose	227.76	10/03/2008
10469297	80900328	10026426	SERVICE 990 LOADER	0.00	09/18/2008
10468769	80897788	10026426	Steps on 990 need attention	1,014.45	09/22/2008
10462984	80879451	10026426	990 step missing a bolt	90.36	08/19/2008
10374868	80693309	10026426	990/BUILD UP TOOTH ADAPTER ON BUCKET	286.08	05/11/2007
10329262	80598516	10026426	990 LOADER/BOSS BROKEN OFF ON BUCKET	1,697.73	09/29/2006
10323721	80586546	10026426	990 Loader A/C Fan Quit	354.44	08/16/2006
10320227	80578847	10026426	990 LOADER/BOLTS BROKEN IN BUCKET PIN/RE	9,899.62	03/01/2007
10310186	80552810	10026426	990 Loader Needs Work	465.57	10/05/2006
10290981	80508911	10026426	990 Loader needs Maintenance (PO)	2,750.99	03/01/2006
10439240	80831560	10026426	TOOTH ADAPTER BROKEN OFF BUCKET	909.20	06/20/2008
10441432	80835133	10026426	990 Back Step is Broken	248.36	05/01/2008
10446947	80843616	10026426	990 Loader Bolts Broken in Swivel	90.27	07/11/2008
10212485	80358615	10026426	990 LOADER/REPLACED TOOTH ADAPTER	633.14	03/22/2005
10435363	80822597	10026426	990 Loader Horn Won't Work	0.00	03/26/2008
10438546	80830232	10026426	REPLACE THE A/C DRIVE BELT	40.86	04/08/2008
10436303	80825225	10026426	HYDRAULIC LEAK NEAR THE FRONT OF MACHINE	134.08	03/31/2008
10430280	80812090	10026426	BACK UP ALARM DON'T WORK	33.53	02/22/2008
10415957	80783680	10026426	BOLTS BROKE OFF IN BUCKET ARM	384.95	12/31/2007
10426774	80804106	10026426	REPAIR THE BUCKET KICK OUT SYSTEM/REPLAC	13,046.39	03/11/2008
10426294	80801737	10026426	990 Loader Step Broken	33.53	01/25/2008
10376892	80697749	10026426	990 LOADER/REPLACE BUCKET TEETH	97.11	06/12/2007
10364514	80671387	10026426	990 LOADER/BOLTS OUT OF CENTER PIN	300.13	03/15/2007
10364520	80670845	10026426	990 Loader Bucket Lever Needs Repair	66.70	03/19/2007
10358413	80653150	10026426	990 Loader Needs Attention/LIGHTS,BUCKET	1,156.04	01/30/2007
10358961	80659848	10026426	990 LOADER/REPAIR HORNS	390.83	03/01/2007
10358203	80657622	10026426	990 Loader Coolant Leak	1,121.22	03/01/2007
10357297	80656801	10026426	990 LOADER/REPLACE SEAT	1,418.45	03/01/2007
10354272	80650528	10026426	990 Loader Step/BROKEN OFF	34.99	01/31/2007
10356283	80654249	10026426	990 LOADER/HYDRAULIC LEAK	541.86	01/31/2007
10350472	80644225	10026426	990 Loader Step Needs Repair	1,059.57	01/08/2007
10353086	80648050	10026426	990/HYDRAULIC LEAK/TIRE/WINDSHIELD/BOLTS	0.00	01/15/2007

10346314	80635883	10026426	990 Loader/REPAIR BUCKET LEVELER/WORKED	453.64	03/07/2007
10348489	80640123	10026426	990 Rebuilt Trans, Torque	27,648.60	01/02/2007
10339959	80620467	10026426	990 Loader Missing Tooth on Bucket	74.92	11/13/2006
10332643	80605819	10026426	990 Loader/REPAIRS	805.55	10/12/2006
10332645	80606216	10026426	990 Loader/CHECK LIGHTS	101.82	10/17/2006
10332647	80606325	10026426	990 Inframe Engine	29,800.00	3/15/2009