SOLD TO: MID-MO EQUIPMENT BRYANT PAVER

P.O. NO.: IHI 30NX START DATE: 4/09/15 ENDING DATE: 6/03/15

ACCT NO.: CASH SALESMAN: BH

DATE 6/03/15 @ 4:16PM

IHI MODEL:30NX 2067 HRS. SN:WE000205

			J.
QUANTIT	Y DESCRIPTION OF WORK DONE/PART NUMBERS	PRICE	AMOUNT
8.5 5.0 2.5 1.0 1.0 2.0 1.0	O SHOP LABOR DATE: 5/14/15 TECH:ARA	90.00 90.00 90.00 2826.00 8.23	765.00 450.00 225.00 75.00 2826.00 8.23 8.57 27.14 12.04
	COLUMBIA, MO. 65202		

	SI	JBTOTAL	5711.98
		TAX	172.80
TOTAL	AMOUNT	DUE>	5884.78

SOLD TO: MID-MO EQUIPMENT BRYANT PAVER

P.O. NO.: IHI 30NX START DATE: 4/09/15 ENDING DATE: 6/03/15

ACCT NO.: CASH SALESMAN: BH

DATE 6/03/15 @ 4:16PM

IHI MODEL:30NX 2067 HRS. SN:WE000205

IHI MODEL:30NX 2067 HRS. SN:WE000205							
1	QUANTITY	DESCRIPTION OF WORK DONE/PART NUMBERS	PRICE	AMOUNT			
		REPAIR ENGINE ENGINE HAD A DEAD MISS AND WAS BLOWING OIL OUT OF DIPSTICK TUBE. FOUND #2 CYLINDER WAS NOT FIRING. SWAPPED INJECTORS BUT ISSUE STAYED IN #2 CYLINDER. REMOVED CYLINDER HEAD AND FOUND PISTON HAD SLOP IN BEARING. REMOVED ENGINE AND DISASSEMBLED. FOUND ROD BEARING HAD SPUN AND RUINED THE CRANKSHAFT. GOT NEW CRANK AND PISTON AND ROD. ASSEMBLED ENGINE WITH NEW GASKETS AND INSTALLED IN MACHINE. FILLED FLUIDS AND TRIED TO START. FOUND IT WAS NOT GETTING FUEL. FOUND FUEL FILTER WAS PLUGGED UP. REPLACED FILTER AND GOT SYSTEM PRIMED. STARTED MACHINE AND FOUND GLOW PLUGS WOULD NOT SHUT OFF. INSTALLED SHEET METAL AND CANOPY.					
	2 50	INSTALLED TOGGLE SWITCH TO RUN GLOW PLUGS. TESTED AND THEY WORKED CORRECTLY. INSTALLED SEAT.  SHOP LABOR DATE: 4/14/15 TECH:ARA SHOP LABOR DATE: 4/23/15 TECH:KAA SHOP LABOR DATE: 5/12/15 TECH:ARA	90.00 90.00 90.00	225.00			