

Asset Name	Description	Date Completed	Completion Notes	Total All Costs
306-002 CROWN VIC	The left turn signal bulb is not working.	08/08/2014 09.23.39	Could not duplicate.	
306-002 CROWN VIC	Vehicle needs oil change, new windshield wipers and wiper fluid	05/09/2014 11.01.00	Changed oil and filter, air and fuel filter, wiper blades, pass mirror from parts car, inspected / topped fluids	68.69
306-002 CROWN VIC	Won't start	09/12/2014 10.27.46	Battery tests good, replaced bad terminal	10.00
306-002 CROWN VIC	Brake lights do not work on car 42-04 Codes crown victoria., Ck eng light on	23/05/2014 15.07.35	Traced wiring problem down from fuse box to multi-function switch. Spliced in a wire to supply 12v from brake switch. All lights work. Also replaced gas cap for Evap leak. Codes cleared and tested good.	21.91
				<b>100.60</b>

#16