

Asset Name	Description	Date Completed	Completion Notes	Total All Costs
341-009 Silverado [53-09]	9912 stop leak napa\$4.39 invoice no 635290	19/11/2014 08.37.27	added bottle of stop leak to oil to slow down oil leak from engine	4.39
341-009 Silverado [53-09]	driver side door handle 735-2648 \$24.36 napa panel clips \$5.18 oreilly invoice no 0138-179208 replaced drivers side out side door handle already had in stock	10/03/2014 11.10.32	driver side door handle 735-2648 \$24.36 napa panel clips \$5.18 oreilly invoice no 0138-179208 replaced drivers side out side door handle already had in stock	29.54
341-009 Silverado [53-09]	4020pk door panel clips for gm trucks stock parts \$2.46 invoice no 604909	26/03/2014 15.51.55		2.46
341-009 Silverado [53-09]	9912 oil seal treatment \$4.39	29/04/2014 16.06.47	napa invoice no 608559	8.38
				44.77

#13