

Asset Name	Description	Date Completed	Completion Notes	Total All Costs
308-002 CROWN VIC [42-22]	Transmission lines seem to be leaking. There is a big puddle under where we had it parked. It tends to take awhile to shift from reverse to drive and slips when shifting.	25/06/2014 15.06.51	Found output shaft seal leaking -- replaced seal and filled trans. Also checked battery, cleaned terminals, Alt 14 volts loaded, batt at 12.58	25.77
308-002 CROWN VIC [42-22]	Service due	24/02/2015 09.36.56	Changed oil and filter, fuel and air filter, checked all fluids, inspected	51.50
308-002 CROWN VIC [42-22]	Service due	24/02/2015 09.42.15	Service just completed	
308-002 CROWN VIC [42-22]	New Wiper Blade	07/02/2014 09.48.04	Jeff changed wiper blades,	26.94
				104.21

#2