

Asset Name	Description	Date Completed	Completion Notes	Total All Costs
306-005 CROWN VIC	Ford Crown Vic will not stay running. It will turn over and want to run and then quits. The vehicle is in the parking lot behind the Housing Office on North Pine. I have the keys so you will have to call me when your ready to look at it. Vehicle number is 42-24.	08/08/2014 09.26.23	Vehicle retired per Bill Beasley, replaced with PD pass down	
306-005 CROWN VIC	2 Tires	11/02/2014 11.26.40	Kansasland Invoice #144025	229.34
306-005 CROWN VIC	Oil is coming from rear passenger side and pooling on the ground underneath the tire.	18/03/2014 13.59.51	Leak is right rear axle seal. Bearing failed and ate into shaft, Replaced pass axle shaft, bearing and seal, all parking brake shoes, rear pads and rotors. Intake leaking coolant and fouling plugs/boots -- replace intake gaskets and clean plugs / boots.	525.62
306-005 CROWN VIC	Air bag light is on. When I start the car it beeps 3 or 4 times. When I am driving around it will beep periodically during the day.	21/05/2014 11.31.46	Had 2 codes for SRS faults -- clockspring and pass. pretensioner high resistance. Replaced clockspring and Pass shoulder belt	115.09
306-005 CROWN VIC	LOF Check battery	07/01/2014 10.20.33	Replaced battery, changed oil and filter, lubed chassis	140.98
				1011.03

#1

UNIT NO. 42-24

4.6L

2FAHP71WX6X145895

~~JERRY~~ Chris
JERRY

[illegible]