

Bill To:
 Tyler Klein
 5661 258th St.
 Hartford, SD

Invoice #
 5229
Date
 4/15/2013

Make/Model	Unit/Year	License	Miles	P.O. No.	Terms	Due Date
Freightliner C.	PH443995		278716		Due on receipt	4/15/2013

Item	Qty	Description	Rate	Tech	Amount
rebush rear suspension	6	Hrs. Replace bushings	75.00	D	450.00T
repair	3	Hrs. Repair broken spring center bolts; pitch suspension to level bags	75.00	D	225.00T
Welding	0.7	Hr. Rebuild damaged spring seat	75.00	D	52.50T
R782	4	Freightliner rear bushing	52.75		211.00T
CB636	3	Center bolt 1/2" X 5-1/2"	1.53		4.59T
Steel		Steel; flat, angle, tubing, etc.	2.50		2.50T
FL174	2	L/H Rear spring bushing wear plate	12.21		24.42T
FL176	2	R/H Rear spring bushing wear plate	12.21		24.42T
R1051	1	Bronze Wedge 3" x 1 degree	25.20		25.20T
4-417	8	Alignment shim	2.88		23.04T
Rear Alignment		Adjust Tracking	75.00	D	75.00T
Shop Supplies		Grease, corrosion inhibitor, grinding disc, cleaner, welder supplies, tie straps, etc.	25.00		25.00T
		Check #1552			

Sales Tax (6.0%)	\$68.56
Total	\$1,211.23
Payments/Credits	-\$1,211.23
Balance Due	\$0.00

