

# REPAIR ORDER 2-10743

**CUSTOMER:**

COMMUNICATION TECHNOLOGIES LLC  
6375 NE 14TH STREET  
DES MOINES, IA 50313  
ERIC ERDELT 515-238-9087 515-

**STATUS:** (0)pen  
**SERVICE**

*K2206*

*#609*  
*Keep in file*  
(2) on 12-18-15

Vehicle Reference: VVA36737 1997 FORD LOUISVILLE  
Customer Unit ID : 609  
Vehicle Mileage : 426763

Page: 2

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 0.50      | 51.50    | 0.00    | 0.00        | 9.64                  | 61.14       |

**OPERATION #:** 040

**CATEGORY :** 411 Repair Air Conditioning

**CONDITION :** BLOWER MOTOR INOP

| Part Number | Description               | Bin 1 | Bin 2 | Quantity | Unit Price | Ext Price |
|-------------|---------------------------|-------|-------|----------|------------|-----------|
| 507150-4009 | FLANGE MOUNT MOTOR 12V CW | AWD8  |       | 1        | 58.83      | 58.83     |
| 507850-6901 | BLOWER & MODE SWITCH      |       |       | 1        | 18.60      | 18.60     |
| OAP76904    | CONTROL KNOB              |       |       | 1        | 14.76      | 14.76     |

Correction: CHECKED HEATER BLOWER MOTOR, FOUND MOTOR WAS BURNT UP AND

Correction: HEATER REOSTAT ALSO NEEDED REPLACED. REPLACED FAN SPEED

Correction: KNOB. CHECKED OPERATION AND MOTOR OPERATING PROPERLY.

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 1.50      | 154.50   | 0.00    | 92.19       | 34.45                 | 281.14      |

**OPERATION #:** 050

**CATEGORY :** 406 Repair Suspension

**CONDITION :** CHECK FRONT END CLUNKS AND SHAKES WHEN TURNING

| Part Number  | Description        | Bin 1 | Bin 2 | Quantity | Unit Price | Ext Price |
|--------------|--------------------|-------|-------|----------|------------|-----------|
| 202T8-3/4X24 | THREADED ROD       | TRE5  |       | 4        | 23.89      | 95.56     |
| 202DN4       | 3/4"-16 NUT        | MSP4  | MSP8  | 8        | 2.55       | 20.40     |
| 202UBW75     | U-BOLT WASHERS 3/4 | MSP2  |       | 8        | 1.41       | 11.28     |
| 200B1498-43  | SPRING PINS        | DBE1D |       | 6        | 28.84      | 173.04    |
| 20343-692    | FORD SPRING        |       |       | 1        | 441.73     | 441.73    |
| 200E827-43   | H SHACKLE          |       |       | 2        | 230.93     | 461.86    |
| 200E858-43   | HANGER , SHACKLE   |       |       | 2        | 132.39     | 264.78    |
| 125PART      | CROSS TUBE/TIE RO  |       |       | 1        | 371.07     | 371.07    |

Correction: CHECKED FRONT END, FOUND REAR SPRING HANGARS ON BOTH SIDES

# REPAIR ORDER 2-10743

**CUSTOMER:**

COMMUNICATION TECHNOLOGIES LLC  
6375 NE 14TH STREET  
DES MOINES, IA 50313  
ERIC ERDELT 515-238-9087 515-

STATUS: (0)pen  
SERVICE

K2206

Vehicle Reference: VVA36737 1997 FORD LOUISVILLE  
Customer Unit ID : 609  
Vehicle Mileage : 426763

(2) on 12-18-15  
Page: 1

OPERATION #: 010  
CATEGORY : 410 Repair Electrical  
CONDITION : LIGHTS ON BED WORK INTERMITTANTLY

Correction: CHECKED LIGHTS AND LOCATED SHORTED WIRES IN BED. REPAIRED  
Correction: WIRES AND CHECKED ALL OTHER LIGHTS.

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 1.60      | 164.80   | 0.00    | 0.00        | 30.85                 | 195.65      |

OPERATION #: 020  
CATEGORY : 408 Repair Brakes  
CONDITION : CHECK ALL BRAKES

| Part Number | Description                    | Bin 1 | Bin 2 | Quantity | Unit Price | Ext Price |
|-------------|--------------------------------|-------|-------|----------|------------|-----------|
| 2200R65145X | BP-R1 BOBTAIL PROPNG RELAY VLV |       |       | 1        | 234.29     | 234.29    |

Correction: CHECKED ALL BRAKES AND WERE 75% LINING LEFT. ADJUSTED ALL  
Correction: BRAKES.

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 1.00      | 103.00   | 0.00    | 234.29      | 33.34                 | 370.63      |

OPERATION #: 030  
CATEGORY : 408 Repair Brakes  
CONDITION : ELECTRIC TRAILER BRAKES PULSE WITH TURN SIGNALS ON

Correction: CHECKED ELECTRICAL POWER AT TRAILER PLUG AND FOUND NO  
Correction: PROBLEMS. WE WILL NEED TRAILER TO PROPERLY CHECK TRAILER  
Correction: BRAKES.

# REPAIR ORDER 2-10743

**CUSTOMER:**

COMMUNICATION TECHNOLOGIES LLC  
6375 NE 14TH STREET  
DES MOINES, IA 50313  
ERIC ERDELT 515-238-9087 515-

**STATUS:** (0) pen  
SERVICE

K2206

Vehicle Reference: VVA36737 1997 FORD LOUISVILLE  
Customer Unit ID : 609  
Vehicle Mileage : 426763

(2) on 12-18-15  
Page: 3

Correction: OF STEER AXLE SEIZED. NEEDS RIGHT FRONT SPRING REPLACED,  
Correction: BOTH REAR SPRING HANGARS, SHACKLE AND SHACKLE PINS.  
Correction: TIE ROD ENDS BOTH LOOSE AND NEED REPLACED.

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 9.00      | 927.00   | 0.00    | 1839.72     | 283.92                | 3050.64     |

OPERATION #: 060  
CATEGORY : 410 Repair Electrical  
CONDITION : REPLACE STROBE LIGHT

| Part Number | Description              | Bin 1 | Bin 2 | Quantity | Unit Price | Ext Price |
|-------------|--------------------------|-------|-------|----------|------------|-----------|
| 31177753    | 15" STROBE MINI BAR LAMP |       |       | 1        | 442.31     | 442.31    |

Correction: INSTALL NEW STROBE LAMP AND MOUNT ON CAB.

**OPERATION TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 2.50      | 257.50   | 0.00    | 442.31      | 74.74                 | 774.55      |

**GRAND TOTALS:**

| DIAG HRS | DIAG \$ | LABOR HRS | LABOR \$ | MISC \$ | PART/CORE\$ | SHOP SUPPL<br>AND TAX | EXT TOTAL\$ |
|----------|---------|-----------|----------|---------|-------------|-----------------------|-------------|
| 0.00     | 0.00    | 16.10     | 1658.30  | 0.00    | 2608.51     | 466.94                | 4733.75     |
| =====    | =====   | =====     | =====    | =====   | =====       | =====                 | =====       |

I hereby authorize the above repair work to be done along with necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An expressed mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Customer Signature: \_\_\_\_\_ Date: \_\_\_\_\_