

Equip Num: 20.40L**04 KOMATSU PC300LC-7L**Model: PC300LC-7LSerial Number: A86227Date Purchased: 2005/04/01

Vendor And Parts Information					Labor Repair Information		
<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2015/05/11	SWO062796-1		INSTALL NEW FUEL PMP/HY	5,582.19	2015/06/18	welding up oil pan EK	3.00
2015/05/01	PS100550900		COVER SS	246.16	2015/06/17	t/s oil leaks EK	2.00
2015/04/24	SWO063213-1		FUEL REL/SWT/MTR ASSY 85	2,429.56			
2015/04/09	234603		HOSES SS	1,038.00			
2015/04/24	SWO063213-1		REP WTR LK/ENG FUEL PR.8	2,790.51			
2015/04/23	PSO124107-1		FUEL PUMP SS	4,148.90			
2015/04/07	SWO060311-1		SPROCKET/BOLTS CS	2,694.49			
2015/04/07	SWO060311-1		R/R BROKEN SPROCKET/R T	3,347.00			
					2015/04/29	t/s hammer EK	1.00
					2015/04/24	t/s hyd. leak EK	1.50
					2015/04/16	change relay EK	2.00
					2015/04/15	t/s machine shutting off EK	1.00
					2015/03/18	track pads EK	1.50
					2015/02/27	t/s hyd sys EK	1.00
					2015/02/06	rpr leak EK	4.00
					2015/02/03	tighten traks EK	1.00
					2015/01/27	prime fuel sys EK	1.00
					2015/01/24	r/r steer column JM	4.50
					2015/01/22	t/s trans shifter JM	1.50
					2015/01/20	t/s fuel sys, ordr prts JM	5.50
					2015/01/19	t/s fuel sys, leak JM	2.00
					2015/01/16	chk leak EK	3.00

600 hrs
since RPR.

Equip Num: **20.40L**Model: **PC300LC-7L****04 KOMATSU PC300LC-7L**Serial Number: **A86227**Date Purchased: **2005/04/01**

Vendor And Parts Information

Labor Repair Information

Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
2014/12/22	2166-303010		ORING KIT JD	153.99			
					2014/12/20	rpr exhaust EK	4.00
					2014/12/20	r/r exh gasket JM	6.00
					2014/12/19	rpr exhaust leak JM	4.00
					2014/12/19	exhaust leak EK	2.00
					2014/12/16	exh leak EK	1.00
					2014/10/09	t/s fuel sys EK	1.00
2014/09/30	1643199		WELDING JD	1,140.00			
2014/09/27	8/26-9/27/14		WELDING JD	1,140.00			
2014/09/24	PSO099963-1		TURBO/STUD/GASKET JD	1,955.35			
2014/09/25	PSO100169-1		HOSE JD	260.33			
2014/09/05	PS100522412		TAP JD	24.72	2014/09/25	r/r turbo AC	5.00
2014/09/11	PSO098544-1		SEAL/PIN JD	628.78			
2014/09/11	PSO098157-1		PLATE/BOLT/WASHERS JD	532.50			
2014/09/12	PSO098567-1		PIN SEAL JD	619.20			
2014/09/05	0830-148680		TOWELS JD	35.97			
2014/09/09	221139		CAPS/PLUGS JD	73.08			
2014/09/11	PSO097113-1		VALVE/GASKET/ISOL JD	90.36			
2014/09/09	PSO097645-1		SPACER/NUTS/BOLTS JD	466.36			
2014/09/03	PSO096488-1		PLATE/BELTS/VLV JD	62.04			
2014/09/04	PSO097258-1		SEAT JD	1,325.95			
					2014/09/12	pin, seals JD	2.00

Equip Num: 20.40L**04 KOMATSU PC300LC-7L**Model: PC300LC-7LSerial Number: A86227Date Purchased: 2005/04/01

Vendor And Parts Information					Labor Repair Information		
<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2013/09/30	847642-001		HYD HOSE ASSY'S PWS	158.76	2013/09/30	rpr hyd leaks swvl motor JG	6.00
					2013/09/30	inst hyd lines, rpr clmps JG	3.00
					2013/09/28	inst boom stik bckt clys JG	5.00
					2013/09/28	press bush in bckt cyl JG	1.00
					2013/09/28	rpr hyd line clamps JG	2.00
					2013/09/28	rpr door latch JG	1.00
2013/09/20	01026386		BOOM,STICK,BUCKET REPA	14,364.22	2013/09/27	hlp rpr uc JM	4.00
					2013/09/25	.rpr eng oil leak JG	3.00
					2013/09/24	rpr ems console, seat rpr JG	5.00
					2013/09/24	rpr boom wiring JG	1.00
					2013/09/23	rmv stick bushings JG	4.00
					2013/09/23	r/r wiper motor JG	4.00
					2013/09/21	rmv bushings stk, h link JG	7.00
					2013/09/21	remove bushings RA	2.00
					2013/09/18	rpr boom line hose leaks JG	4.00
					2013/09/17	rmv wiper dash assy JG	3.00
					2013/09/16	rmv stick clys, pins, hyd JG	10.00
					2013/09/14	rpr exhaust leak JG	2.00
					2013/09/14	rmv bckt, parts list JG	1.00
					2013/09/14	rpr seat JG	3.00
					2013/09/09	inst bucket RG	3.00
					2013/08/16	weld bckt rpr EK	1.00

32.00 HRS.
SINCE APR.