

Equip Num: **20.56L****02 CAT 330CL QC D TMB HD****24854**Model: **330CL**Serial Number: **DKY00595**Date Purchased: **2002/09/05****Vendor And Parts Information**

<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>
2014/10/18	S39W0736274		STICK RELIEF VLVS BC	465.73
2014/10/18	S39W0736274		R & R 6 INJ & HRNS BC	2,836.00
2014/10/18	S39W0736274		6 NEW INJ & HRNS BC	3,991.00
2014/09/03	476077		WELD CRACKS IN QC BC	270.00
2014/08/14	P39C0283898		SEAL BC	67.84

1,500 HRS
since
RPR.

Labor Repair Information

<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2015/02/09	rmv bckt, cpler, thumb JS	5.00
2014/12/15	wash rack JM	3.00
2014/12/11	wash rack JM	3.00
2014/12/10	from shop 443 to shop 3 CF	11.00
2014/12/09	from shop 443 to shop 3 CF	12.00
2014/12/09	load to shop 3 WO	1.00
2014/12/09	load to shop 3 TG	1.00
2014/11/26	rpr ignition swtch RG	1.00
2014/10/01	chk for rpr WO	2.00
2014/08/27	to wagner RR	2.50
2014/08/27	sched rpr's WO	2.00
2014/08/25	t/s, chk codes RG	2.50
2014/08/25	run parts BF	1.50
2014/08/25	t/s stick drift WO	3.00
2014/08/13	install thumb RG	5.50
2014/08/13	install thumb WO	5.50
2014/08/13	r/r hyd tube, chk fuel lk RG	3.50
2014/08/04	r/r window rollers RG	1.00
2014/08/01	run parts AP	1.00

Equip Num: 20.56L

02 CAT 330CL QC D TMB HD

L4854

Model: 330CLSerial Number: DKY00595Date Purchased: 2002/09/05Vendor And Parts InformationLabor Repair Information

<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2014/07/31	P39C0283446		COVER BC	88.25			
2014/07/30	P39C0283404		WINDOW ROLLERS BC	38.88			
					2014/07/28	chk, rpr hyd leak RG	1.50
					2014/07/24	ordr parts WO	1.00
					2014/07/21	inspect unit WO	1.00
					2014/07/11	thumb cyl rmv, rpr WO	4.00
2014/06/20	P39R0127071		TURBO CORE BC	-673.13			
2014/06/11	P39C0281962		STUDS BC	24.28			
2014/06/14	P39C0282087		PIN KEEPER BC	2.79			
2014/06/14	P39C0282088		TRK PIN-BG	54.05			
2014/06/12	P39R0127011		RTN STUDS BC	-24.28			
2014/06/11	P39C0281961		TURBO BC	1,949.82			
					2014/06/17	rmv side door, chk unit RG	1.00
					2014/06/13	r/r trak pin RG	7.00
					2014/06/13	r/r trak pin WO	1.00
					2014/06/11	parts return RG	1.00
					2014/06/10	r/r turbo RG	5.00
					2014/06/09	chk rad, heat prob, turbo WO	3.00
					2014/06/09	chk turbo RG	0.50
					2014/06/04	rpr bucket pins RG	3.00
					2014/06/03	bucket rpr RG	0.50
					2014/04/17	chk hyd leak, rpr RG	2.00
					2014/04/08	chk hyd leak RG	0.50
2014/03/29	S39W0734204		DIAG & RPLS R IDLER BC	988.14			

1800 HRS
SINCE
RPR

Equip Num: 20.56L

02 CAT 330CL QC D TMB HD

L4854

Model: 330CLSerial Number: DKY00595Date Purchased: 2002/09/05Vendor And Parts InformationLabor Repair Information

<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2016/04/07	PS110835599		PLUG KIT SS	23.04			
2016/04/07	PS110835433		HYD HOSE BC	230.42			
2016/04/07	PS110835596		RETAINER/TIP SS	124.82	2016/04/29	work on pins KM	1.00
					2016/04/25	fix hyd hose KM	2.00
					2016/04/06	multiple repairs WP	12.00
					2016/04/05	insp/found items KM	2.00
2016/03/23	WO110256655		R & R HYD HOSES BC	850.00			
2016/03/23	WO110256655		HYD HOSES BC	226.39			
2015/12/11	SS700018947		RPR HYD LEAKS BC	450.14			
2016/01/26	SS700020179		CYL ROD/SEALS BC	2,524.98			
2016/01/26	SS700020179		RPR HYD LEAKS BC	779.10			
2016/01/26	SS700020179		RBLD THUMB CYL BC	1,930.00			
2015/11/25	PS100575657		SEAL SS	13.96			
2015/10/30	WO110247209		R&R WINDOW LATCHES SS	849.00			
2015/10/30	WO110247209		CAP/HANDLE/TUBE/LOCK S	1,364.01			
2015/10/08	WO110245639		R&R ROCK GUARD SS	1,113.40			
2015/09/29	2376		REPAIR BUCKET SS	600.00			
2015/08/13	WO110240760		KEY SWITCH SS	54.34			
2015/08/13	WO110240760		R&R KEY SWITCH SS	1,420.50			
2015/07/29	WO110239655		REPAIR AC R & R COMPRESS	2,585.00			
2015/07/29	WO110239655		HOSES/COMPRESSOR/SEALS	3,788.25			
2015/07/14	CS110091905		MOTOR SS	503.33	2015/07/22	fix hyd line AC	4.00

700 HRS
SINCE
RPR.1200 HRS
SINCE
RPR.

Equip Num: **20.56L****02 CAT 330CL QC D TMB HD**

14854

Model: **330CL**Serial Number: **DKY00595**Date Purchased: **2002/09/05**Vendor And Parts InformationLabor Repair Information

<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2015/04/17	SS000009555		RESEAL 2 BOOM CYL PWS	914.60			
2015/04/02	PC000006019		PARTS RETURN KK	-4.92			
2015/04/14	PC000006134		LIP SEALS RETURN KK	-194.56			
2015/04/14	PC000006135		PARTS RETURN VLV KK	-75.28			
2015/04/22	PC000006235		PARTS RETURN KK	-115.38			
2015/04/22	PC000006237		PARTS RETURN KK	-206.76			
					2015/04/15	inst cyl, chk fluids, clean JS	5.00
					2015/04/14	install cyls JS	3.00
					2015/04/08	rmv boom cyls, to rpr shop JS	7.50
					2015/04/07	clean up. into shop JS	2.00
					2015/04/07	rpr cracks RA	3.00
					2015/04/06	clean BM	5.00
2015/03/25	PS000041002		RETAINER TUBE KK	127.04			
2015/03/21	PS000040751		SEAT SUSPENSION KK	1,642.87			
2015/03/14	PS000040101		HARDWARE KK	31.34			
2015/03/07	PS000039525		SEALS KK	35.60			
2015/03/05	SS000008823		2 TRACK LINK AS PWS	13,026.61			
2015/03/05	SS000008823		R & I TRACK SHOES PWS	2,412.77			
2015/03/04	PS000039146		BEARING/SLEEVE/SEAL KK	696.56			
2015/03/05	PS000039282		SEALS KK	12.18			
2015/03/05	PS000039281		SEALS KK	17.40			
2015/03/05	PS000039280		BEARING/SLEEVE KK	85.81			
2015/03/05	PS000039279		BEARINGS/SLEEVES/SEALS I	834.29			
2015/03/17	PS000040211		HARDWARE KK	19.74			