

K8104

11/18/2016 1:57 PM

page 1

Vehicle Service History Report (Consolidated)

BRYAN OHLMEIER CONSTRUCTION CO.

2004 Chevrolet Truck Silverado 2500HD 3/4 Ton - Pickup 6.6 L 403 CID V8 Diesel , Driver:FRED, Tag:543 BBN, Vin:1GCH

Labor/Notes

RO #	Item	Category	Tech	Description
16533	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK
16533	GUIDE		SM	WHEEL BEARING, LEFT Front - R&R Includes: Replace inner and/or outer bearings and cups and repack where applicable.
16533	TIR4	TIRE	SM	MOUNT & BALANCE
16533	TIR5	TIRE DISPOSAL		TIRE DISPOSAL
19393	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK TIRE WEAR LEFT FRONT
26819	GUIDE		PC	WHEEL BEARING - R&R RIGHT FRONT Includes: Replace inner and/or outer bearings and cups and repack where applicable.
26819	LABOR		PC	CHECK NOISE IN RIGHT FRONT
29053	TIR4	TIRE	EL	MOUNT & BALANCE 4 NEW TIRES REAR BRAKES 10,000 MILES LEFT FRONT BRAKES 50 % LEFT
29053	TIR5	TIRE DISPOSAL		TIRE DISPOSAL
35067	ALI3	SUSPENSION	EL	ALIGN 2-WHEEL THRUST LT TRUCK LH INSIDE TIRE WEAR
35067	TIR7	TIRE	EL	ROTATE RH TIRES
42021	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK
42021	DOT	PREVENTIVE	SM	DOT INSPECTION SERPENTINE BELT CRACKED NEEDS WIPER BLADES REAR PINION SEAL SEEPS (STILL FULL) R. UPPER CONTROL ARM BUSHING LOOSE
42021	GUIDE		SM	CONTROL ARM SHAFT AND BUSHING - R&R RH UPPER
42021	GUIDE		PC	ALTERNATOR DRIVE BELT - R&R
42021	TIR4	TIRE	SM	MOUNT & BALANCE
42021	TIR5	TIRE DISPOSAL	SM	TIRE DISPOSAL
43440	AC1	AIR	PC	PERFORMANCE TEST A/C SYSTEM COOL AT HWY SPEED, NOT AT IDLE INCLUDES: CHECK AIR CONDITIONING SYSTEM WITH GAUGES AND LEAK DETECTOR. CHECK COMPRESSOR CLUTCH AND DRIVE BELT. TEST TEMPERATURE AT A/C OUTLETS. HIGH SIDE PRESSURE HIGH, COULD HAVE RESTRICTION IN THE ORIFICE & OR COMP GETTING WEAK. CONTROLS IN DASH SEEM TO BE WORKING CORRECTLY STILL NOT COOLING AS WELL AS IT SHOULD
43440	ALI4	SUSPENSION	SM	ALIGN 1 TON & UP

Vehicle Service History Report

(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2004 Chevrolet Truck Silverado 2500HD 3/4 Ton - Pickup 6.6 L 403 CID V8 Diesel , Driver:FRED, Tag:543 BBN, Vin:1GCH

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
43440	BK1	BRAKES	SM	CHECK BRAKES RF BRAKE PADS VERY THIN, CALIPER CHECKED OK REAR ROTORS SURFACE RUSTED AWAY, NOT GETTING FULL CONTACT FROM BRAKE PADS NEEDS: REAR BRAKE ROTORS, SAND REAR PADS (THERE LIKE NEW), REPLACE FRONT PADS, MACHINE FRONT ROTORS, REPLACE BOTH FRONT BRAKE HOSES
43440	BK3	BRAKES	MGR	TURN ROTOR OFF VEHICLE
43440	GUIDE		SM	BRAKE SYSTEM (COMPLETE) - R&R Includes: Replace pads on the front, remove rotors to turn on lathe. replace rear rotors, sand rear brake pads flat, lube all caliper slides
43440	GUIDE		SM	BRAKE HOSE - R&R REPLACE BOTH FRONT Includes: Bleed hydraulic system. Includes: Perform ABS Automated Bleed Procedure.
43440	LABOR			PULLS RIGHT
44024	GUIDE		PC	WHEEL SPEED ABS SENSOR - R&R
44024	LABOR		PC	ABS LIGHT ON - DRAGS WHEN BRAKING SCAN
46156	LABOR		PC	LOW COOLANT LIGHT ON, ADDING COOLANT POSSIBLY PUSHING IT OUT OVER FLOW, DOES NOT RUN HOT BLOCK TEST - FAILED

Parts

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
16533	-	7847	LT245/75R16 E KUHMO KL78	TIRE	4		
16533	GM	15225770	HUB	GENERAL	1		
16533	TT	TT	TIRE TAX	TIRE TAX	4	EACH	
26819	PGB	PBR930416	Hub Assy - Front Wheel		1		
Drivetrain: Four Wheel Drive;							
29053	-	05523	LT245/75R16 E COOPER	TIRE	4		
29053	TT	TT	TIRE TAX	TIRE TAX	4	EACH	
32234	COP	05501	LT245/75R16 E COOPER	TIRE	4		
DID NOT INSTALL ON TRUCK							
32234	TT	TT	TIRE TAX	TIRE TAX	4	EACH	
32539	COP	05501	LT245/75R16 E COOPER	TIRE	-4		
DID NOT INSTALL ON TRUCK							
32539	TT	TT	TIRE TAX	TIRE TAX	-4	EACH	
42021	-	51717	LT245/75R16 COOPER AT/3	TIRE	4		New
42021	NBH	25061177	Belt - Serpentine		1		
42021	NCP	2671461	Control Arm Bushing - Upper -		1		
42021	WIP	60022	Wiper Blade - AccuFit - Front -	PREVENTIVE	2		
42116	TT	TT	TIRE TAX	TIRE TAX	4	EACH	

Vehicle Service History Report
(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2004 Chevrolet Truck Silverado 2500HD 3/4 Ton - Pickup 6.6 L 403 CID V8 Diesel , Driver:FRED, Tag:543 BBN, Vin:1GCH

Parts (continued)

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
43440	BBR	56829RGS	BRAKE ROTOR REAR	BRAKES	2		New
43440	BHH	BH620051	BRAKE HOSE	BRAKES	1		
43440	BHH	BH620052	BRAKE HOSE	BRAKES	1		
43440	NFR	134A	134A FREEON	AIR	4.8	OZ	
43440	PFC	0784.20	BRAKE PADS FRONT HEAVY	BRAKES	1		
44024	-	19300584	ABS SENSOR	BRAKES	2		