

K8106

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 1

Vehicle Service History Report
(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Labor/Notes

RO #	Item	Category	Tech	Description
16320	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK
16320	LABOR		PC	LOW FUEL LIGHT COMES ON WHEN FULL WOULD NEED TO REPLACE FUEL PUMP/SENDER ASSY
16320	LABOR		SM	CHECK FRONT END BALLJOINTS & TIE-RODS OK
16320	LABOR		PC	REPLACE SHIFT CABLE
16320	LABOR		PC	SLIGHT MISS AT IDLE
16320	TUN1	TUNE UP	PC	TUNE UP INCLUDES: REPLACE SPARK PLUGS, FUEL FILTER, CLEAN &/OR REPLACE AIR FILTER. CHECK PCV VALVE. INSPECT DISTRIBUTOR CAP & ROTOR (IF APPLICABLE). INSPECT IGNITION CABLES. CHECK EMISSIONS. ADJUST TIMING AND IDLE SPEED WHEN APPLICABLE.
17832	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK
17832	GUIDE		SM	LEFT UPPER/LOWER BALL JOINT - R&R
17832	LABOR		SM	CHECK FRONT END SQUEAK
18368	GUIDE		PC	MULTI-FUNCTION SWITCH - R&R NOTE: Labor times listed are for R&R only and DO NOT include diagnosis time.
18368	GUIDE		SM	FUEL PUMP - R&R FUEL FILTER WAS JUST REPLACED
18368	GUIDE		SM	FUEL PUMP - TEST FUEL PRESSURE AT IDLE 40 PSI REGULATED & UNREGULATED TEST DRIVE FUEL PRESSURE AT 30 PSI NEEDS: FUEL PUMP
18368	LABOR		PC	HORN INOP- CHECK OUT HORN IN-OP SWITCH ON MULTI-FUNCTION SWITCH NOT MAKING CONTACT WITH AIR BAG CLOCK SPRING NEEDS: MULTI FUNCTION SWITCH

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 2

Vehicle Service History Report (Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GC19

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
19100	GUIDE		PC	FUEL FILTER - R&R FUEL FILTER FULL OF RUST RECOMMEND REPLACING AGAIN & NOTEING IF FULL OF RUST AGAIN
19100	LABOR		PC	CHECK P/S PUMP - LEAKING??? NO PROBLEM SEEN AT THIS TIME
19100	LABOR		PC	CHECK ENGINE LIGHT ON - RUNS GOOD SCAN COMPUTER - LEAN EXHAUST BANK 1 CODE CHECK FUEL PRESSURE
20153	ALI3	SUSPENSION	SM	ALIGN 2-WHEEL THRUST LT TRUCK
20153	BK1	BRAKES	SM	CHECK BRAKES FRONT BRAKE PADS 40 % LEFT RECOMMEND REAR BRAKES
20153	BK3	BRAKES	EL	TURN ROTOR OFF VEHICLE
20153	BRK5	BRAKES	EL	R&R REAR DISC PADS
20153	GUIDE		PC	CHARGING SYSTEM - CHECK Includes: Check battery, regulator and alternator output. CHARGED BATTERY-OK ALTERNATOR FAILED LOAD TEST-VOLTAGE TO ALTERNATOR OK NEEDS: ALTERNATOR
20153	GUIDE		PC	ALTERNATOR ASSEMBLY - R&R CUSTOMER FURNISHED PART-WARRANTY REPLACED REMAN ALT WITH NEW ALTERNATOR
20153	LABOR		SM	NOISE IN FRONT END R&R LH LOWER BALL JOINT
				NOTE: STEERING SHAFT MAKING POPPING NOISE TURNING & HITTING BUMPS-GM MAY STILL MAKE GREASE KIT TO GET RID OF NOISE-OR UPDATED SHAFT VERY COMMON PROBLEM
20153	TIR4	TIRE	MGR	MOUNT & BALANCE 4 NEW TIRES
20153	TIR5	TIRE DISPOSAL		TIRE DISPOSAL

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 3

Vehicle Service History Report
(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Labor/Notes (continued)

RO #	Item	Category	Tech PC	Description
20377	LABOR		PC	WHEN CUSTOMER REPLACED FUEL FILTER FUEL PUMP CAME ON WITH KEY OFF-PUMP TURNED OFF WHEN PRESSURE WAS MAINTAINED CHECK FOR FUEL PUMP COMING ON WITH KEY OFF AFTER PRESS DROP - NO PROBLEM FOUND AT THIS TIME.
20581	GUIDE		PC	FUEL FILTER - R&R
20581	LABOR		PC	CHECK ENGINE LIGHT ON - RUNS FINE SCAN COMPUTER - RANDOM MISSFIRE CODE - ALL CYL SHOW MISSFIRE HISTORY - WILL NOT MISS AT THIS TIME. CHECKED PLUGS - OK
20584	GUIDE		EL	FUEL PUMP - R&R
20729	GUIDE		PC	INTAKE MANIFOLD GASKET - R&R
20729	LABOR		PC	CHECK ENGINE LIGHT ON LEAN EXH BANK 1 & 2, RANDOM MISSFIRE CODES. O2 SENSOR NOT SWITCHING. FOUND VACUUM LEAK UNDER INTAKE
22960	LABOR		EL	CHECK SQUEAK IN REVERSE R&R DRIVE SHAFT & REPLACE REAR U-JOINT
22960	LABOR		EL	CHECK RATTLE/ SQUEK IN FRONT END SLIGHT RATTLE FROM REAR OXYEN SENSORS FRONT STEERING & SUSPENSION-OK RIDES LIKE SHOCKS ARE NOT DOING ANYTHING
24454	ALI3	SUSPENSION	EL	ALIGN 2-WHEEL THRUST LT TRUCK
24454	GUIDE		GO	BALL JOINT - R&R ALL 4 DOES NOT include alignment.
24454	TIR7	TIRE	GO	ROTATE 4 TIRES FRONT TIRES OFF FOR BALLJOINTS
25560	GUIDE		EL	WATER PUMP - R&R REPLACED A/C BELT (CRACKED) REPLACED THERMOSTAT
25560	GUIDE		EL	POWER STEERING PUMP - R&R
25560	LABOR		EL	FIX WASHER FLUID LEAK REPAIRE BROKEN HOSE BY BATTERY (CAUSE BY BATTERY ACID)
25560	LABOR		EL	POWER STEERING LEAK-COMING FROM P/S

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 4

Vehicle Service History Report (Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
25560	LABOR		MGR	ANTIFREEZE LEAK - WATER PUMP LEAKING
25560	SC	PREVENTIVE	MGR	COURTESY CHECK - NO CHARGE
26032	GUIDE		PC	SERPENTINE BELT TENSIONER - R&R
26032	LABOR		PC	WASHER PUMP INOP LINE OFF NEAR WASHER PUMP
26032	LABOR		PC	CHECK PULLEY NOISE EVEN WHEN A/C ON NEEDS TENSIONER & BELT
26032	SC	PREVENTIVE	PC	COURTESY CHECK - NO CHARGE
27818	GUIDE		EL	WHEEL BEARING - R&R LF Includes: Replace inner and/or outer bearings and cups and repack where applicable.
27818	TIR6	TIRE	GO	BALANCE 4 TIRES CHECK BRAKES FRONT 30% LEFT REAR 75% LEFT
30100	LABOR		EL	WON'T CRANK CHECK STARTING & CHARGING SYSTEM BATTERY HAS A SHORTED CELL REPLACE BATTERY
31440	GUIDE		PC	OXYGEN SENSOR - R&R R&R BOTH UPSTREAM OXYGEN SENSORS
31440	GUIDE		EL	BALL JOINT - R&R RIGHT UPPER DOES NOT include alignment. Serviced with Control Arm.
31440	LABOR		PC	CHECK ENGINE LIGHT COMES ON & OFF SCANNER HOOKUP: PO134 LOW ACTIVITY B1 S1 PO135 O2 HEATER CKT B1 S1 PO155 O2 HEATER B2 S1 BOTH UPSTREAM OXYGEN SENSORS NOT RESPONDING FAST ENOUGH RECOMMEND BOTH UPSTREAM OXYGEN SENSORS- MAY NEED DOWNSTREAM IN NEAR FUTURE
31440	LABOR		EL	NOISE IN DRIVE LINE 30-40 MPH WHEN TIRE NOISE-MUD TERRAIN

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 5

Vehicle Service History Report

(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
31440	LABOR		EL	NOISE UNDER HOOD-BEARING
32538	ALI3	SUSPENSION	EL	ALIGN 2-WHEEL THRUST LT TRUCK
32538	LABOR		EL	R&R LH UPPER BALLJOINT
32538	LABOR			NOTE: AIR BAG LIGHT ON
32538	TIR4	TIRE	HH	MOUNT & BALANCE 4 NEW TIRES
				NOTE: LR WHEEL BENT- TOOK EXTRA AMOUNT OF WEIGHT
				WHEELS TORQUED AT 140 LBS
32538	TIR5	TIRE DISPOSAL		TIRE DISPOSAL
33862	AC1	AIR	PC	PERFORMANCE TEST A/C SYSTEM
				NOT COLD
				INCLUDES: CHECK AIR CONDITIONING SYSTEM WITH
				GAUGES AND LEAK DETECTOR. CHECK COMPRESSOR
				CLUTCH AND DRIVE BELT. TEST TEMPERATURE AT A/C
				OUTLETS.
				REPLACE LOW SIDE CORE.
33862	LABOR		PC	REPLACE MANIFOLD SEALS ON COMPRESSOR
34139	GUIDE		EL	DIFFERENTIAL ASSEMBLY - R&R
				SWAP OUT REAR BRAKES
				REPLACED REAR PARKING BRAKE SHOES, ROTORS, &
				PADS
				REPLACED REAR PINION SEAL
34139	LABOR		HH	LEFT REAR AXLE SEAL LEAKING
				BOTH REAR AXLE BEARINGS & AXLES BAD AFTER
				REMOVAL
				FOUND CRACK IN LH TUBE- NEEDS REAR DIFF REPLACED
				BOTH REAR LEAK SPRINGS HAVE BROKEN SPRINGS
34139	LABOR		EL	REPLACE REAR U-JOINT
				WITH DRIVESHAFT OUT
34139	LABOR		EL	REPLACE BROKEN LEAK ON BOTH REAR
34992	BK1	BRAKES	MGR	CHECK BRAKES - RATTLE IN LEFT REAR
				NOISE COMING FROM SLIGHTLY BENT LR AXLE
34992	LABOR		MGR	WARRANTY PINION SEAL
36833	AC1	AIR	PC	PERFORMANCE TEST A/C SYSTEM - INOP
				INCLUDES: CHECK AIR CONDITIONING SYSTEM WITH
				GAUGES AND LEAK DETECTOR. CHECK COMPRESSOR
				CLUTCH AND DRIVE BELT. TEST TEMPERATURE AT A/C
				OUTLETS.
				REPLACE HIGH SIDE SERVICE PORT- LEAKING
				COMPRESSOR LEAKING TO

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 6

Vehicle Service History Report (Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
36833	GUIDE		EL	WATER PUMP - R&R
36833	LABOR			WATER PUMP LEAKING
49986	LABOR		PC	ODOMETER IN-OP
49986	LABOR		PC	TOWED IN, DIED WHILE DRIVING POSSIBLE FUEL
49986	PRODEMAND		PC	FUEL PUMP Remove & Replace
49986	ProDemand		PC	FUEL PUMP Testing
				NEEDS: FUEL PUMP

Parts

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
16320	AC	41985	Spark Plug	TUNE UP	8		
16320	CRB	29399	PCV VALVE	TUNE UP	1		
16320	FF	GK3727	FUEL FILTER	FUEL	1		New
16320	GM	12477640	CABLE KIT	GENERAL	1		
17832	NCP	2601525	Ball Joint - Upper - Front	SUSPENSION	1		
17832	NCP	2601528	Ball Joint - Lower - Front	SUSPENSION	1		
18368	GM	19121626	FUEL PUMP & MODULE GM	FUEL	1		
18368	GM	26100839	GM MULTI FUNCTION SWITCHELECTRICAL		1		
19100	FF	GK3727	FUEL FILTER	FUEL	1		New
20153	-	1784713	LT245/75R16 KUHMO KL78	TIRE	4		New
20153	NCP	2601528	Ball Joint - Lower - Front	SUSPENSION	1		
WARRANTY							
20153	TT	TT	TIRE TAX	TIRE TAX	4	EACH	
20153	WAG	PD792A	CERAMIC PADS	BRAKES	1		
20581	FF	GK3727	FUEL FILTER	FUEL	1		New
20584	GM	19121626	FUEL PUMP & MODULE -	FUEL	1		
20729	GM	89060413	INTAKE GASKET	GENERAL	1		
22960	PUJ	355	U-JOINT	GENERAL	1		New
24454	MOO	K6540	BALL JOINT UPPER	SUSPENSION	2		
24454	MOO	K6541	BALLJOINT	SUSPENSION	2		
25560	-	20-8704	POWER STEERING PUMP		1		New
25560	-	AFU	ANTIFREEZE - UNIVERSAL	PREVENTIVE	1		
25560	HOS	HOS VAC	VAC HOSE	GENERAL	1	FT	
25560	LOW	PS	POWER STEERING FLUID	PREVENTIVE	1		New

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 7

Vehicle Service History Report
(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Parts (continued)

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
25560	NBH	25040378	SERP BLT A/C	EXHAUST	1		
25560	TFW	45005	NEW WATER PUMP	GENERAL	1		
25560	THM	400186	THERMOSTAT		1		
26032	NBH	25060930	BELT	GENERAL	1		
26032	NBH	38158	Drivebelt Tensioner Assy	GENERAL	1		
		Serpentine					
27818	BCA	515036	L. FRONT HUB ASSY	BRAKES	1		
30100	ISB	MT78	INTERSTATE BATTERY	ELECTRICAL	1		
31440	-	19178961	GM OXYGEN SENSOR		2		New
31440	MOO	K6540	BALL JOINT UPPER	SUSPENSION	1		
		WARRANTY					
32538	COP	05501	LT245/75R16 E COOPER	TIRE	4		
32538	MOO	K6540	BALL JOINT UPPER	SUSPENSION	1		
32538	TT	TT	TIRE TAX	TIRE TAX	4	EACH	
33862	-	134 REF OIL	134A REF OIL	AIR	3	OZ	
33862	DEL	15-5375	SCHRADER VALVE	AIR	1		
33862	MRY	DYE	A/C DYE	AIR	1	.25 OZ	
33862	NFR	134A	134A FREEON	AIR	25	OZ	
34139	-	25010532	REAR BRAKE ROTOR		2		New
34139	-	C792	CERAMIC BRAKE PADS REAR		1		New
34139	-	V75W90	VALVOLINE SYN GEAR OIL		3	QT	
34139	NOS	21285	PINION OIL SEAL	GENERAL	1		
34139	PUJ	355	U-JOINT	GENERAL	1		New
34139	RFD	CB-15	BOLT W H		1		
34139	UP	UP10781PB	REMAN PARKING BRAKE	BRAKES	1		
		w/ 8.27 X 1.18" Brakes					
34992	NOS	21285	OIL SEAL	GENERAL	1		
36833	-	59975	A/C FITTING HIGH SIDE	AIR	1		
36833	-	AFU	ANTIFREEZE - UNIVERSAL	PREVENTIVE	1		
36833	NFR	134A	134A FREEON	AIR	29	OZ	
36833	TFW	45005	NEW WATER PUMP	GENERAL	1		
36833	THM	400186	THERMOSTAT		1		

MC LEAN AUTO & TRUCK SERVICE, INC.

31955 OLD K.C. ROAD

P. O. BOX 361

PAOLA KS 66071

(913) 294-5086

WE FIX IT RIGHT THE FIRST TIME

MONDAY - FRIDAY 8:00 AM - 5:30 PM

www.mcleanautotruck.mechanicnet.com

11/18/2016 1:55 PM

page 8

Vehicle Service History Report
(Consolidated)

BRYAN-OHLMEIER CONSTRUCTION CO.

2001 Chevrolet Truck Silverado 1500 1/2 Ton 4WD - Pickup 5.3 L 325 CID V8 , Driver:CORY, Tag:544 BBN, Vin:1GCEK19

Parts (continued)

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
49986	GM	19153711	GM FUEL PUMP MODULE	FUEL	1		

Sublet/Misc.

RO #	Description	Category
30100	TOWING CHARGE	TOWING