-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	UMBER	INVOICE	DATE	CUSTO	MER NO.	CUSTON	ER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006632	22	04-30-	-15	6379	10	381		00	G	040	2	
PSO/WC	NO.	DOC. DA	TE	PC	LC	MC	SHIP	7IA	<u>. </u>		INVOICE S	EQ. NO.
006632	22	04-24-	-15	1G	1G	1G	. ,.					
MAKE	N	ODEL			SERIAL N	UMBER	EQUIPMENT NUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	950F		072	F0091	4		971	1	4951	. 0		
QUANTITY		ITEM		1 •1	WR		DESCRIPTION		UNIT F	RICE	EXTEN	SION

* PROFORMA INVOICE

TROUBLESHOOT BUCKET SPEED

COMPLAINT: LIFT SPEED SLOW

CAUSE: PUMP WORN

CORRECTION: CHECKED CYCLE TIME FOR LOADER RAISE, SPEC IS 6 SECONDS, ACTUAL WAS 9 SECONDS. CHECKED MAIN RELIEF, SPEC IS 3000 PSI, ACTUAL WAS 1600 PSI. NOTICED PUMP WAS MAKING A LOT OF NOISE WHEN STALLED AT LOW OR HIGH IDLE. ALSO FOUND SMALL BRASS PARTICLES IN THE HYDRAULIC FILTERS. IMPLEMENT PUMP WILL NEED TO BE REPLACED AND HYDRAULIC SYSTEM SERVICED.

SHOP LABOR

106.90

TOTAL LABOR

SEG. 01

106.90 *

SEGMENT 01 TOTAL

106.90 T

REMOVE & INSTALL IMPLEMENT PUMP

COMPLAINT: IMPLEMENT PUMP NOT PRODUCING ENOUGH

FLOW

THANK YOU FOR YOUR BUSINESS!

	THIS DUNT	>	CONT'D
AMC	DÚNT DIT	>	

CUSTOMER COPY

WO#3692

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	UMBER	INVOICE	ATE	CUST	MER NO.	CUSTON	IER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006632	22	04-30-	15	6379	10	381		00	G	040	2	2
PSO/WC	NO.	DOC, DA	TE	PC	LC	MC 1	SHIP V	iA:			INVOICE S	EQ. NO.
006632	2	04-24-	15	1G	1G	1G						1
MAKE	, N	10DEL			SERIAL N	UMBER	EQUIPMENT NUMBER	М	ETER R	EADING	MACH.	ID NO.
AA	950F		072	F009:	.4		971	1	4951	. 0		
QUANTITY		пем		1	WR		DESCRIPTION		UNIT F	RICE	EXTEN	SION

PROFORMA INVOICE

CAUSE: WEAR INSIDE OF THE PUMP
CORRECTION: REMOVED SEAT AND FLOOR PLATE. REMOVED
LINES TO THE PUMP AND REMOVED THE PUMP FROM THE
MACHINE. INSTALLED A NEW PUMP AND CONNECTED LINES
TO THE PUMP. REINSTALLED FLOOR PLATE AND SEAT.
OPERATED MACHINE AFTER INSTALLING THE NEW PUMP.
ADJUSTED MAIN RELIEF TO SPECIFICATION AT 3000 PSI.
TESTED CYCLE TIMES AND FOUND THEY WERE WITHIN
SPECIFICATION. LIFT CYCLE TIME IS NOW 6.4 SECONDS,
SPEC IS 6.6 SECONDS. TILT IS NOW 2.1 SECONDS, SPEC
IS 2.2 SECONDS.

1	1P-3705	SEAL	S	2.32	2.32
2	4J-0522	SEAL-O-RING	S	1.79	3.58
1	4V-1878	HOSE	S	24.48	24.48
1	5F-3106	SEAL	S	4.04	4.04
2	5P-0598	CLAMP	S	4.22	8.44
1	6E-6659	PUMP G	N	2609.05	2609.05
1	8C-5172	SEAL	s	3.78	3.78

F/R LBR 1002.15 *
SEGMENT 02 TOTAL 3657.84 T

SEG. 02

TOTAL PARTS

REMOVE & INSTALL HYDRAULIC SYSTEM

THANK YOU FOR YOUR BUSINESS!

PAY THIS AMOUNT	>	CONTID
AMOUNT CREDIT	>	

2655.69 *

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	UMBER	INVOICE	ATE	CUST	OMER NO.	CUSTOM	ER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006632	22	04-30-	15	637	910	381		00	G	040	2	3
PSG/WG	NO.	DOC, DA	TE	PC	LC	MC	SHIP	/IA	•		INVOICE S	EQ. NO.
006632	2	04-24-	15	1G	1G	1G						
MAKE	N	COBL			SERIAL N	UMBER	EQUIPMENT NUMBER	M	हास र	ADING	MACH	ID NO.
AA	950F		07Z	F009	14		971	1	4951	. 0		
QUANTITY		ITEM		1.	N/R		DESCRIPTION		UNIT F	RICE	EXTEN:	SION

PROFORMA INVOICE

FILTER

COMPLAINT: SERVICE HYDRAULIC SYSTEM

CAUSE: MAINTENANCE

CORRECTION: CHANGED HYDRAULIC OIL AND FILTERS.

5	3096931	HYD-ADV10W 5G	S	79.	82 399.10	
2	1R-0722	FILTER A	S	24.	18 48.36	
2	2S-4078	SEAL	S	1.	58 3.16	
2	5H-6733	SEAL-O-RING	S	5.	66 11.32	
1	5M-2057	SEAL	s	1.3	37 1.37	
2	7D-1195	SEAL	S	3.	89 7.78	
		TOTAL PARTS		SEG 04	471 09	, 4

F/R LBR 235.80 *
SEGMENT 04 TOTAL 706.89 T

REMOVE & INSTALL TRANSMISSION OIL PUMP

REPLACE TRANS OIL PUMP, ONE OF THE GEAR SHAFT BEARINGS CAME OUT WITH THE HYD PUMP UPON REMOVAL

COMPLAINT: TRANSMISSION PUMP DRIVE GEAR SUPPORT

BEARING CAME OUT OF ITS BORE.

CAUSE: BEARINGS, GEARS, AND PUMP HOUSINGS SHOW

PAY THIS AMOUNT	>	CONT 'D
AMOUNT CREDIT	>	F

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	JMBER	INVOICE D	ATE	CUSTO	MER NO.	CUSTOM	ER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006632	2	04-30-	15	6379	10	381		00	G	040	2	4
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC	SHIP V	iA .		<u> </u>	INVOICE S	EQ. NO.
006632	2	04-24-	15	1G	1G	1G						
MAKE	N	IODEL			SERIAL N	JMBER	EQUIPMENT NUMBER	M	ETER R	ADING	MACH.	ID NO.
AA	950F		07Z	F0091	4		971	1	4951	. 0		
QUANTITY		ITEM		1.	WR		DESCRIPTION		UNIT F	RICE	EXTEN	SION

PROFORMA INVOICE

EXCESSIVE WEAR AND SCORING CORRECTION: REMOVED LINES FROM THE TRANSMISSION PUMP AND REMOVED PUMP FROM THE MACHINE. INSTALLED A REMAN PUMP AND REINSTALLED LINES TO THE PUMP. TOPPED OFF TRANSMISSION OIL THAT WAS LOST. CUSTOMER DECIDED TO CHANGE THE TRANSMISSION OIL AND FILTER ON THEIR OWN.

PUMP GP GEAR	N	1018.12	1018.12
CORE DEPOSIT	N	548.23	548.23
CORE CREDIT	N	548.23	548.23-
RING	S	2.00	2.00
SEAL	S	2.70	2.70
SEAL O RING	S	4.94	4.94
TOTAL PARTS	SEG. 0	5	1027.76 *
	F/R	LBR	353.70 *
EXPEDITE CHRO	}		71.27
TOTAL MISC CH	IGS SEG. 0	5	71.27 *
SEGMENT 05 T	COTAL		1452.73 T
	CORE DEPOSIT CORE CREDIT RING SEAL SEAL O RING TOTAL PARTS EXPEDITE CHRO	CORE DEPOSIT N CORE CREDIT N RING S SEAL S SEAL S SEAL O RING S TOTAL PARTS SEG. 0 F/R	CORE DEPOSIT N 548.23 CORE CREDIT N 548.23 RING S 2.00 SEAL S 2.70 SEAL O RING S 4.94 TOTAL PARTS SEG. 05 F/R LBR EXPEDITE CHRG TOTAL MISC CHGS SEG. 05

PAY THIS AMOUNT CONT'D AMOUNT CREDIT

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714


INVOICE N	JMBER .	INVOICE	ATE	CUSTO	MER NO.	CUSTON	IER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006632	2	04-30-	15	6379	10	381		00	G	040	2	
PSO/WO	NO.	BOC. DA	TE	PC	LC	MC	SHIP V	iA -	·	1	INVOICE S	EQ. NO.
006632	2	04-24-	15	1G	1G	1G						-
MAKE	<u>}</u>	AODEL .			ERIAL N	JMBER	EQDIPMENT NUMBER	M	ETER R	ADING	MACH.	ID NO.
AA	950F		07Z	F0091	4		971	1	4951	. 0		
QUANTITY		ITEM		• N	VR		DESORIPTION		UNIT F	RICE	EXTEN	SION

PROFORMA INVOICE

15% OFF ALL CAT PPE & SAFETY EQUIPMENT. NOW THRU APRIL 30. 10% OFF GROUND ENGAGING TOOLS. OFFER VALID APRIL 1 THRU 30.

PAY THIS AMOUNT	5924.36
AMOUNT >	
	AMOUNT

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714



QUANTITY		ITEM		1.1	VR		DESCRIPTION		UNIT P	RICE	EXTENS	NON
AA	950F		07Z	F0091	4		971	1	5150	. 0		
MAKE	м	ODEL			ERIAL N	UMBER	EQUIPMENT NUMBER	M	ETER RE	ADING	MÁCH.	ID NO.
006862		10-16-	15	1G	1G	1G					/	
PSO/WO	NO.	DCC, DA	TE	PC	LC	MC	SHIP	/IA			INVOICE'S	EQ. NO.
006862		11-25-		6379				00	Ç	040	2	
INVOICE N		INVOICE I	DATE	CUSTO	MER NO.	CUSTON	ER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE

PROFORMA INVOICE

REMOVE & INSTALL DIFFERENTIAL

COMPLAINT: BRAKES NOT OPERATING PROPERLY
CAUSE: BRAKE DISC INSIDE THE DIFF WERE WORN
CORRECTION: REMOVED DIFF AND SENT IT TO TOPEKA TO
BE REPAIRED. INSTALLED DIFF AFTER REPAIR AND
FILLED WITH NEW OIL AND BLED BRAKES AND CONFIRMED
PROBLEM HAD BEEN RESOLVED.

CHODDEN INTO DEPH WESON	ved.		
2 8T9576	DTO 50W 5G S	91.14	182.28
1 PALLET 93X24-6	93X46 FLAT PALLET N	1500.00	1500.00
1	CORE DEPOSIT N	1500.00	1500.00
1- PALLET 93X24-6	93X46 FLAT PALLET N	1500.00	1500.00-
1-	CORE CREDIT N	1500.00	1500.00-
8 8T-4167	WASHER S	1.37	10.96
	TOTAL PARTS	SEG. 01	193.24 *
		F/R LBR	1179.00 *
1.00-	LABOR ADJUST		250.00-
	TOTAL MISC CHGS	SEG. 01	250.00-*
	SEGMENT 01 TOTAL		1122.24 Т

THANK YOU FOR YOUR BUSINESS!

PAY THIS AMOUNT >	<u> </u>	CONT'D
AMOUNT >	-	

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	JMBER	INVOICE	DATE	CUSTO	MER NO.	CUSTON	IER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006862	0	11-25	-15	6379	10			00	G	040	2	
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC	SHIP V	IA			INVOICES	EQ. NO.
006862	0	10-16-	-15	1G	1G	1G						-
MAKE	N	100EL			SÉRIAL N	UMBER .	EQUIPMENT NUMBER	M	ETER R	ADING	MACH.	ID NO.
AA	950F		07Z	F0091	.4		971	1	5150	.0		
QUANTITY		ITEM			WR		DESCRIPTION		UNIT F	RICE	EXTEN	SION

PROFORMA INVOICE

REMOVE & INSTALL DIFFERENTIAL REAR

COMPLAINT: BRAKES NOT WORKING PROPERLY
CAUSE: BRAKE DISC INSIDE DIFF WORN
CORRECTION: REMOVED DIFF AND SENT IT TO TOPEKA TO
BE REPAIRED. INSTALLED DIFF AFTER REPAIR AND
FILLED WITH NEW OIL AND BLED BRAKES AND CONFIRMED
PROBLEM HAD BEEN RESOLVED.

PROBLEM NAD	DEEM KESOLVED				
2 8T9576		DTO 50W 5G	S	91.14	182.28
1 PALLET	93X24-3	93X24 FLAT PALLET	N	1500.00	1500.00
1		CORE DEPOSIT	N	1500.00	1500.00
1- PALLET	93X24-3	93X24 FLAT PALLET	N	1500.00	1500.00-
1-		CORE CREDIT	N	1500.00	1500.00-
1- PALLET	93X24-3	93X24 FLAT PALLET	N	1500.00	1500.00-
1 PALLET	93X24-3	93X24 FLAT PALLET	S	1500.00	1500.00
1		CORE DEPOSIT	S	1500.00	1500.00
1-		CORE CREDIT	N	1500.00	1500.00~
		TOTAL PARTS	S	SEG. 02	182.28 *
				F/R LBR	1414.80 *
1.00-		LABOR ADJUST			250.00-
		TOTAL MISC CHGS	5 S	BEG. 02	250.00-*
		SEGMENT 02 TO	ral .		1347.08 T

THANK YOU FOR YOUR BUSINESS!

PAY THIS AMOUNT >	>	CONT'D
AMOUNT >	¥	
r -are-	~~ ~~~	~ ~A

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	JMBER .	INVOICE	DATE	CUST	OMER NO	CUSTO	MER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006862	0	11-25-	-15	637	910			00 G	040	2	3	
PSO/WO	NO.	DOC: DA	TE	PC	LC	MC	SHIPV	IA		<u>' </u>	INVOICE S	EQ. NO.
006862	0	10-16-	-15	1G	1G	1G						***************************************
MAKE		MODEL			SERIAL N	UMBER	EQUIPMENT NUMBER	METER READING		ADING	MACH.	ID NO.
AA	950F		07Z	F009	14		971	1	5150	.0		
QUANTITY	Ι	ITEM	•N/R				DESCRIPTION	UNIT PRICE			EXTEN	SION

PROFORMA INVOICE

RECONDITION DIFFERENTIAL REAR

COMPLAINT: REAR AXLE RECONDITION CAUSE: TRANSFERRED METAL FROM THE BRAKES THROUGH THE ENTIRE AXLE COMPLICATION: SIS D/A IS WRITTEN WRONG TELLING YOU HOW TO POSITION THE AXLE TO SET UP THE DIFF AND WHAT ADJUSTMENT NUTS TO CHANGE. EXCESS CLEANING TO REMOVE ALL THE FINE METAL FROM THE AXLE. CORRECTION: THE AXLE WAS DISASSEMBLED, CLEANED AND INSPECTED. I FOUND THAT THE BRAKES, PISTONS, AND REACTION PLATES WERE RUBBING METAL TO METAL, GENERATING FINE METAL THROUGH THE WHOLE AXLE ARRANGEMENT. ON ONE SIDE, THE FRICTION MATERIAL FROM ONE OF THE BRAKE DISC WAS COMPLETELY GONE AND RUBBING METAL TO METAL. THE AXLE HOUSING, CENTER HOUSING, AND ALL OTHER REUSABLE PARTS WERE WASHED AND CLEANED TILL ALL METAL WAS REMOVED. THE AXLE ARRANGEMENT WAS ASSEMBLED WITH ALL NEW: SEALS (BRAKE SEALS WERE UPDATED PER SERVICE MAGAZINE SEPD1026), BEARINGS (INCLUDING UPDATED SLEEVE

BEARINGS FOR THE TRUNNION SUPPORTS PER SERVICE MAGAZINE SEPD0696-00), THRUST WASHERS, DIFF

THANK YOU FOR YOUR BUSINESS!

PAY THIS AMOUNT	>	CONT'D
AMOUNT CREDIT	>	Administration and the second

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE N	UMBER	INVOICE	ATE	CUSTO	MER NO.	CUSTOA	HER PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
006862	20	11-25-	15	6379	10		***************************************	00	G	040	2	4
PSO/WO	NO.	DOC, DA	TE	PC	LC	MC	SHIPV	IA		<u> </u>	INVOICE S	EQ. NO.
006862	20	10-16-	15	1G	1G	1G						2
MAKE	v N	IODEL			SERIAL N	JMBER	EQUIPMENT NUMBER	M	ETER R	ADING	MACH.	ID NO.
AA	950F		07Z	F0091	4		971	1	5150	. 0		
QUANTITY		ITEM		1.0	WR .		DESCRIPTION	''	.UNIT F	RICE	EXTENS	SION

PROFORMA INVOICE

HOUSING BOLTS (TORQUE TURNED), BRAKE DISCS (WORN BEYOND LIMITS / FRICTION MATERIAL GONE), REACTION PLATES (STEP WORN), BRAKE PISTONS (STEP WORN), PINION HOUSING (GROOVES WORN WHERE TRUNNION SUPPORT RIDES, REAR TRUNNION (GROOVES WORN WHERE TRUNNION SUPPORT RIDES), YOKE ASSEMBLY (STEP WORN WHERE U-JOINT RIDES), DIFF SIDE GEARS (PITTED AND TOOTH PROFILE CHANGED), DIFF SPIDER GEARS (TOOTH PROFILE CHANGED), LEFT SUN GEAR (PITTED), SPIDER (STEP WORN), SPRING PINS (UPDATED PER SERVICE MAGAZINE SEPD0959-00 NOW USES PIN INSIDE A PIN), YOKE LIP SEAL (UPDATED PER SERVICE MAGAZINE SEPD0347-00 DID NOT NEED NEW LIP SEAL RETAINER SINCE OLD RETAINER PART NUMBER WORKED WITH NEW SEAL), PRESSURE RELIEF FITTING (UPDATED PER SERVICE MAGAZINE SEPD0144-00), TUBE, FITTINGS, AND MAGNETIC PLUG. THE FINAL DIFF BACKLASH WAS SET TO THE NOMINAL .013IN. ROLLING TORQUE OF THE PINION ALONE AND IN THE AXLE WAS SET TO SPEC. DURING THE BRAKE ASSEMBLY THE BRAKE PISTONS WERE OPERATIONALLY TESTED BY APPLYING TO THE PRESSURE PORT AND THE PISTONS POPPED UP LIKE THEY SHOULD. THE BRAKES WERE TESTED INDIVIDUALLY AFTER THE AXLE ARRANGEMENT WAS ASSEMBLED. BRAKES WERE TESTED WITH 500PSI AND HELD WITH NO DROP FOR 15 MINUTES. ALL BOLTS WERE TORQUED TO SPEC.

1 1J-2860 CUP S 65.84 65.84

PAY THIS AMOUNT	>	CONT D
AMOUNT CREDIT	>	

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

INVOICE NU	IMBER I	INVOICE I	DATE	CUSTO	MER NO.	CLIST	ONED DIE	CHASE OB	DER NUMBER	STORE	l DIV	I a		
006862		11-25-		6379			CIVIER FOR	CHASE ON	DER NOMBER	00	G	SALESMAN		PAGE
PSO/WO		DOC. DA		PC	Tier	MC	-		SHIP VI		<u> </u>	040	2	5
006862	0	10-16-	-15	1G	1G	1G	 		<u> </u>	^			INVOICE S	
MAKE		DOEL			ERIAL N		·	EQUIPM	ENT NUMBER	М	ETER RE	ADING	MACH.	1D NO.
AA	950F		072	F0091	4			971	1515					
QUANTITY		ITEM		1.0	I/R		DE:	CRIPTION			UNIT P	RICE	EXTEN	SION
						•								
				* *	*	PROF	ORMA 1	INVOIC	E * *	*				
	7 4855			_				_						
	J-4757			_	ONE			S			4.44		104	
	D-9454			_	UP			s		_	8.68			.68
	D-9455				ONE			s			1.56			. 56
	K-0715				ashei	•		s			6.31			. 62
	P-1373			_	UP			N			6.18		112	
	B-0551 B-0551				LUG			S			9.84			. 84
	K-0158				LUG			s s			9.84		-	. 84 -
	E-3896				EAL OLT			S		5	3.81		107	
	E-3897			_				S			.16			. 32
	E-3037				OCK IN			S			.18			.36
	H-6520			-	ING			S			3.46	•		. 92
	K-7239				OWEL			S			4.67		_	. 67
	H-3701				CREW			S			2.08 4.30			.16
- •	K-9243			_	LBOW			S			4.30 1.65			.60 .65
	P-4484			_	LUG			S			6.72		_	. 63 . 72
	P-5528			-	DOG DAPTI	מי		S			3.78			. /2 . 12
	V-1274				PIDE			N			3.78 7.99		337	
	K-2430			_	EAL	`		S			4.12			. 12
	V-7732				OLT			S		-	1.29			.74
	W-1638				ashe!	•		N			0.22			. 22
	Y-2538				ONE	•		N			9.67		169	
	Y-2538			_	ONE			N			9.67		169	
	Y-2539			_	ONE			s			7.22			. 2 <i>2</i>
	M-8485				EAL			s			1.34			. 02
	V-3791				UARD			Ŋ			8.91		_	. 91
	V-3791			_	UARD			N			8.91			. 91 -
- ,				. •	•••••					_				
				:					,					
									PAY THIS					
									AMOUNT			CO	NT'D	
									AMOUNT	>				
									CREDIT		<u> </u>			

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

	NIMBER	INVOICE		CUSTO	MER NO.	. CUS	TOMER P	URCHASE ORDER	NUMBER	STORE	DIV	SALESMAN	TERMS	PAG
00686		11-25-		6379	10					00	G	040	2	
PSO/W		DOC. DA		PC	rc	MC			SHIP VI	A	·		INVOICE S	EQ. NO
00686		10-16-	15	1G	1G	1G								
MAKE		00EL			ERIAL N	UMBER	,	EQUIPMENT	TNUMBER	M	ETER RE	ADING	MACH.	ID NO.
AA	950F		07Z	F0091				971		1	5150			
QUANTITY	<u> </u>	ITEM		, N	/R			ESCRIPTION			UNIT F	RICE	EXTEN	SION
				* * :	*	PRO	FORMA	INVOICE	* *	*				
	8B-6342				ONE			N		12	0.31		240	.62
	8B-6343				UP			s			0.00		80	.00
_	8R-1703				INIO	N		N			9.21		796	
	8R-1704				EAR			N			9.62		359	
	BR-4568				ISTO	N		N			4.56		729	.12
	8R-9207				EAL			S		3	6.73		73	.46
	BT-0336				ITTI			s			1.76		1	.76
6	BT-2925			P:	IN-S	PRINC	3	s			1.91		11	.46
1	9C-6327			G	AGE A	A.		N		24.04			24.04	
6	9C-7727			B	EARII	NG		N		7:	2.12		432	. 72
1 :	9C-8287			N	UT			N		4	9.83		49	. 83
2	9C-8418			P	LATE			N		41	5.88		831	. 76
1	9C-8492			T	UBE A	A		N		2	4.56		24	. 56
1	9C-9191			T	RUNN:	ION		N		67	1.66		671	. 66
1 :	9C-9194			H	OUSI	NG		N		43	3.39		433	. 39
12	9C-9537			W.	ASHE	R		s		!	5.51		66	.12
2	9G-5315			S	EAL (G		s		7	2.84		145	. 68
	98-7698			E	LBOW	90 I	DEG	N		!	5.12		5	.12
1	9S-7720			E	LBOW			N			1.75		1	. 75
1	98-7752				EE			N			8.96		8	. 96
1	9U-1912			S	LEEV	ΕA		s		17	7.24		177	. 24
	9U-1913				LEEV		\$	S			9.03		129	
	9X-2027				ASHE			s			.21			. 26
	9X-2619				IN			N		1	0.34			. 36
	9X-2620				IN			Ŋ			1.94			.76
	9X-6493				OLT			N			6.34		126	
	030-006	1			ONE A	A		S			3.81		43	

SHIP TO

-RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

	INVOICE NUMBER INVOI		ATE	CUSTOMER NO. CUSTOMER PURCHASE ORDE			RCHASE ORDER	NUMBER	STORE	DIV	SALESMAN	TERMS	PAG	
		11-25-	15	.5 637910						00	G	040	2	
PSO/WO NO. DOC. DA		TE	PC LC MC			SHIP VIA			· · · · · ·	INVOICE SEO. NO				
0068620 10-16-		15	_1G	1G	1G									
MAKE MODEL			SERIAL NUMBER				EQUIPMENT NUMBER		METER READING		MACH. ID NO			
AA	AA 950F		07Z	7ZF00914				971		15150.0		.0		
QUANTITY		ITEM		* N	R		DE	SCRIPTION			UNIT P	RICE	EXTENS	SION
				* * *	•	PROF	RMA	INVOICE	* *	*	,			
1 1	12-077	9		GI	EAR	SET-BV	L	N		261	7.54		2617	. 54
1 1	23-400	3		SI	EAL-	LIP TY	P	s		21.48			21.48	
4 1	35-294	6		В	EARI	NG		S		31.48			125.92	
6 1	38-164	5		P	IN-S	PRING		S		1.25			7.	.50
1 1	59-184	7		Y	OKE .	AS		N		409.92			409.92	
2 1	2 162-8772			WASHER-THRUS			S	N		21.96			43.92	
1 1	1 164-6476			GEAR-SUN				N		760.41			760.41	
1 2	13-136	5		BEARING			S	148.42				148.42		
1 2	13-137	0		BI	RG S	LEEVE		S		10	5.32		105	. 32
4 2	17-368	0		W.	ASHE	R-THRU	S	N		2	5.41		101.	. 64
6 2	93-360	9		SI	RIN	G		s			7.82		46.	. 92
2 3	25-378	0		SI	EAL	D RING	ļ	N		3	4.20		68.	.40
2 3	25-378	1		R	ING	BACKUE)	N		3	6.17		72.	. 34
2 3	34-103	4		D	sc-	FRICTI	0	S		25	6.50		513.	.00
					то	TAL PA	RTS		SEG. 0	4		;	12040.	. 37
									F/R	LBR			6366.	. 60
1.00	1.00				EX	PEDITE	CHR	G					11.	. 88
					TO	TAL MI	SC C	HGS	SEG. 0	4			11.	. 88
					s	EGMENI	04	TOTAL					18418.	. 85

REPAIR SERVICE BRAKE

PAY THIS AMOUNT	>	CONTID
AMOUNT CREDIT	>	

- RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

NVOICE NUMBER NVOICE D/ SS000014028 11-26-	15 637910	2015-1			00	G	040	TERMS 2	8
PSW/WO NO DOC DATE 0068620 10-16-		MC 1G		SHIP VIA		经世界测数		INVOICE SEC	
MAKE MODEL	Personal Company of the Company of t	A CONTRACTOR OF THE CONTRACTOR	EOHIBMENT	NEMDED	SCHOOL STREET	METER R	EADING H	93358 MACH ID	
	07ZF00914		971	NUMBER		15150.		MACH ID	VO.
UANTITY ITEM	- PMR	DES	CRIPTION.	美国共和国		UNIT PE	RICE	EXTENSI	ON
REAR DIFF HOUSING. RESERVOIR IS EMPTY REMAINED FULL. RECERTACES.	네 돼.뭐.뭐.!! 요즘 하는 그 그 그리다 가게 하다.	RONT RE	ESERVOIR	HAS					
		SHOP LA	ABOR					416.91	
	TOT	AL LABO	OR	SEG.	05			416.91	*
	LES		%-LABOR		<i>∞™</i>			208.44	
	SE	GMENT C	5 TOTAL					208.47	Т
	L DIFFERENTIA	ΣL							
CONT COMPLAINT: REPLACE DIFFERENTIAL-FRONT CAUSE: SEALS BADLY	GASKET/RESEAL	ı	E FRICTIO	N					
COMPLAINT: REPLACE OF THE PROPERTY OF THE PROP	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT	CONS THE FRICTION CED BRAK SIDE BOT	N DISC'S KES TH HELD 5	00					
COMPLAINT: REPLACE OF STREET OF STRE	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT S SHIPPED. PISTON	CONS THE FRICTION CED BRAKE SIDE BOT COS OF W	N DISC'S KES TH HELD 5 WORN SEAL N	00	007700	54.56		729.12	
COMPLAINT: REPLACE OF STREET OF STRE	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT S SHIPPED. PISTON SEAL	CONS THE FRICTION CED BRAN BIDE BOT COS OF W	N DISC'S KES TH HELD 5 WORN SEAL N	00		36.73		73.46	
ONT COMPLAINT: REPLACE DIFFERENTIAL-FRONT CAUSE: SEALS BADLY DISC'S HAD GOTTEN HORRECTION: REPLACE NO PUT IN NEW STYL NDIVIDUALLY RIGHT DES. PSI FOR 5 MIN. NO W.O. & HOW IT WA 2 8R-4568	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT S SHIPPED. PISTON	CONS THE FRICTION CED BRAN BIDE BOT COS OF W	N DISC'S KES TH HELD 5 WORN SEAL N	00					
COMPLAINT: REPLACE OF STREET OF STRE	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT S SHIPPED. PISTON SEAL	CONS THE FRICTION CED BRAN BIDE BOT COS OF W	N DISC'S KES TH HELD 5 WORN SEAL N	00 S		36.73		73.46	
2 8R-9207	GASKET/RESEAL WORN AND PIST OT D PISTONS & F E SEALS, TEST SIDE - LEFT S CAN SEE PHOT S SHIPPED. PISTON SEAL	CONS THE FRICTION CED BRAN BIDE BOT COS OF W	N DISC'S KES TH HELD 5 WORN SEAL N S S	00 S		36.73	CON	73.46	

JOLD IO

SHIP TO

- RENO COUNTY PUBLIC WORKS 600 SCOTT BLVD SOUTH HUTCHINSON KS 67505-8714

PSW/V		DOC DA		PC LC	The same of the sa	建造加支援	SHIP VIA			INVOICE SE	
MAKE AA	950F	EL		AL NUMBER F00914		EQUIPMENT 971	NUMBER	METER 15150	READING . 0	MACHLID	NO.
UANTI	TY	M	1	/R	DES	CRIPTION	的學術學	UNIT	PRICE	EXTENS	SION
2	325-378 334-103				BACKUP C-FRICTIO	N S		36.17 256.50		72.34 513.00	
				7	TOTAL PART	S	SEG. 06	i		1456.32	2 *
					SEGMENT 0	6 TOTAL	F/R I	BR		1650.60 3106.92	
					DEPT POL W			208.44			

BOGO FILTERS. BUY ONE. GET ONE. SEE YOUR FOLEY PARTS REP. 15% OFF COOLANT. VALID NOVEMBER 1 TO NOVEMBER 30.

THANK YOU FOR YOUN WOLFESS

PAY THIS AMOUNT	₽	24203.56
AMOUNT CREDIT	₽	