To: GRIMM GARDENS 2991 GOLDFINCH RD. HIAWATHA, KS. 66434

Type inv	vice#	Description	Amo	unt.	Payment	Balance	
-		Engine cost W/ labor and shipping	550	0.00			
		additional core charge not recoverable due to head					
		being cracked	40	0.00			
		Additional labor due to pump, sensors, wiring					
*		repaired or replaced 9 hrs @ \$50 per hr	45	0.00	·		
		Radiator repair	8	5.25			··· ···
	***************************************	filters	. 11	3.62			
	depriorie	sensors	14	9.63			
	Control	shop supplies (rags, cleaner, floor dry ect)	54	00.0			
	uneappropria	radiator hoses	8	5.42			
		fluids(engine ail, coolant., hydraullo)	13	.83			
		fees from atchison votech	7	.00	,		:
					and the same		ŧ
					Total	25	