

INVOICE**7647****INVOICE**

Work Completed Date : 10/20/2016

Vehicle Received: **10/19/2016**Invoice Date: **10/20/2016**

1990 Freightliner -

Lic # : - IL

Unit # : 509

VIN # : MP50672

Odometer In : 838302

Odometer Out : 838302

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Differential SQHP-390	1.00	1962.50	1962.50	Rear diff	510.00
75-90 Synthetic 7590	4.00	37.79	151.16	R & R Rear differential	
Shop Supplies			26.24	Hazardous Materials	3.50

Labor:	510.00
Parts:	2,139.90
SubTotal:	2,649.90
HazMat:	3.50
Tax:	171.19
Total:	2,824.59
Bal Due:	\$2,824.59

Description	Qty	U/M	Rate	Amount
Service order 4215 Service Performed: Freightliner Semi #509 1FUYDCYB2MP506725				
Mileage 838302				
1/6 ST Cut existing spring hanger and equalizer from frame . Pivot hole oblonged in all brackets. Need to replace brackets, bushings and pivot pin. Source and order replacement parts. Inform customer of repairs needed and time frame.				
1/10 ST Install new L suspension hanger, equalizer, control arm and related bushings. Adjust rear axle tracking.				
1/11 ST Install new bolts and nuts. Torque to specs.				
04-9/16"x2" G8 Bolt	3		2.22	6.66T
04-9/16" G8 Locknut	3		0.66	1.98T
99-Misc Supplies 1/6	1		11.00	11.00T
Shop Time 1/6	3.75	hr	120.00	450.00
Shop Time 1/10	2.5	hr	120.00	300.00
20-M83117Hanger	1		181.32	181.32T
20-EQ003Equalizer	1		151.03	151.03T
20-BKT4014 EquilizerBoltKit	1		44.78	44.78T
20-334-896TorqueArmBushing	2		78.36	156.72T
04-GR8 FLG 5/8NCX2 PO	6		2.66	15.96T
04-5/8-11PO Flange Nut	6		1.43	8.58T
Shipping and Handling 1/10	1		32.00	32.00
20-Torque Arm 345-164	1		48.60	48.60T
99-Misc Supplies 1/10	1		11.00	11.00T
99-Misc Supplies 1/11	1		9.00	9.00T
Shop Time 1/11	1.5	hr	120.00	180.00
Sales Tax			8.00%	51.73

Total \$1,660.36

Payments/Credits \$0.00

Balance Due \$1,660.36