

Invoice Number: **231019**
 Invoice Date: 3/28/2016

Page: 1 of 3

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8100	8050	RW8100P011159	LF8100	

Segment 1 Retail

COMPLAINT:

01 Front axle seal leak

CORRECTION:

1. Tech Comments; Replace LH MFWD seals and orings. Change front axle and hub oils. Replace LH tie rod end and adjust toe in. Breakin axle seals. Calibrate transmission.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7092	Cotter Pin	1.00	0.30	0.30	\$0.30	N
H36256	O-Ring	2.00	1.66	1.66	\$3.32	N
R236289	Bushing	1.00	11.40	11.40	\$11.40	N
R87047	Ring	1.00	6.68	6.68	\$6.68	N
R95119	Seal	2.00	15.13	15.13	\$30.26	N
RE173541	Tie Rod End	1.00	250.00	250.00	\$250.00	N
RE265933	Hub Kit	1.00	227.49	227.49	\$227.49	N
BTY26814	GL5 GEAR LUBE 85W140	7.00	4.75	4.75	\$33.25	N
Labor: \$677.74		Parts: \$562.70	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,240.44	

Segment 2 Retail

COMPLAINT:

02 Oil leak at engine oil cooler.

CORRECTION:

2. Tech Comments; Replace lower gasket and orings on engine oil cooler. Replace lower gasket , orings and tubes.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R47153	O-Ring	8.00	1.67	1.67	\$13.36	N
R51053	Oil Tube	2.00	29.51	29.51	\$59.02	N
R530687	Gasket	2.00	2.06	2.06	\$4.12	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8100	8050	RW8100P011159	LF8100	

Segment 2 Retail							
3750	FREIGHT		1.00	5.00	5.00	\$5.00	N
Labor: \$153.88	Parts: \$76.50	OL&M: \$0.00	Misc: \$5.00	Sub-Total:	\$235.38		

Segment 3 Retail
COMPLAINT:
03 Radio loses power intermittently.

CORRECTION:
3. Tech Comments; Check radio connections, tighten adapter terminals.

Labor: \$40.01	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$40.01
----------------	---------------	--------------	--------------	------------	---------

Segment 4 Retail
COMPLAINT:
04 Fuel gauge does not work.

CORRECTION:
4. Tech Comments; Check and replace fuel gauge sending unit.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R95430	Gasket	1.00	4.99	4.99	\$4.99	N
RE221718	Fuel Sender	1.00	140.37	140.37	\$140.37	N
RE231108	Electrical Repair Kit	1.00	6.63	6.63	\$6.63	N
BAR69445	HYGARD OIL	3.00	14.39	14.39	\$43.17	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8100	8050	RW8100P011159	LF8100	

Segment 4 Retail							
3750	FREIGHT		1.00	21.44	21.44	\$21.44	N
Labor: \$72.77	Parts: \$195.16	OL&M: \$0.00	Misc: \$21.44	Sub-Total:	\$289.37		

Miscellaneous Charges:

Service Accessories

\$54.16

Labor:	\$944.40
Parts:	\$834.36
OL&M:	\$0.00
Misc:	\$80.60
Sales Tax:	\$0.00
Grand Total:	\$1,859.36