

Invoice Number:	136061
Invoice Date:	3/14/2014

Page: 1 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 1 Retail

COMPLAINT:

1. Oil leak at front wheel seal

CORRECTION:

Rebuilt both sides of the MFWD installing new bushings and seals. Replaced the inner bearing and race on the RH side. Greased kingpins and tie rod ends on both sides. Replaced hub oils on both sides and axle oil. Ran to check operation and for leaks.

Torqued front wheel bolts.

****Half price hauling.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7017	Cotter Pin	2.00	0.25	0.25	\$0.50	N
AH146052	Hydraulic Cylinder Kit	1.00	39.19	39.19	\$39.19	N
H152104	Snap Ring	1.00	6.46	6.46	\$6.46	N
H36256	O-Ring	4.00	1.63	1.63	\$6.52	N
JD9050	Bearing Cone	1.00	175.58	175.58	\$175.58	N
JD9115	Bearing Cup	1.00	71.45	71.45	\$71.45	N
N34349	Snap Ring	1.00	5.28	5.28	\$5.28	N
R236289	Bushing	2.00	11.07	11.07	\$22.14	N
R87047	Ring	2.00	6.55	6.55	\$13.10	N
R95118	Bushing	1.00	5.99	5.99	\$5.99	N
R95119	Seal	4.00	14.84	14.84	\$59.36	N
R97605	Set Screw	2.00	6.98	6.98	\$13.96	N
RE265933	Hub Kit	2.00	220.87	220.87	\$441.74	N
RE64225	Grease	1.00	13.92	13.92	\$13.92	N
BAR69445	HYGARD OIL	3.00	14.39	14.39	\$43.17	N
TY26813	GL5 85W140	6.00	6.77	6.77	\$40.62	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
3750	FREIGHT	2.00	11.85	11.85	\$23.70	N

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 1 Retail

3902	MINIMUM DEL VEH CHG	1.00	250.00	250.00	\$250.00	N
Labor: \$1,328.00	Parts: \$958.98	OL&M: \$0.00	Misc: \$273.70	Sub-Total: \$2,560.68		

Segment 2 Retail

COMPLAINT:

2. Pull codes and check all functions of machine

CORRECTION:

Pulled and erased codes. ECU 37 , PCU 62, PCU 17. The ECU code was the only relevant code. Unbolted side shields and hood. Disconnected fuel temp. sensor. Checked voltage to the sensor, and checked sensor resistance. All checked out good. Cleaned sensor terminals and reconnected. The warning light on the dash has not came back on. Checked seat switch for proper operation. Removed seat cushion and installed seat switch that had been removed from seat by previous owner. Checked functions of machine.

Labor: \$327.85	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$327.85		
------------------------	----------------------	-------------------------	---------------------	----------------------------	--	--

Segment 3 Retail

COMPLAINT:

3. Install Case Drain and motor return fittings.

CORRECTION:

Removed plugs and installed a case drain fitting and a motor return fitting.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R218933	Cover	1.00	15.30	15.30	\$15.30	N
RE222718	Breakaway Coupler	1.00	137.91	137.91	\$137.91	N
RE248257	Adapter Fitting	1.00	20.72	20.72	\$20.72	N
RE248312	Adapter Fitting	1.00	44.28	44.28	\$44.28	N
RE322903	Hyd. Quick-Connect Coupler	1.00	141.25	141.25	\$141.25	N
Labor: \$51.19	Parts: \$359.46	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$410.65		

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 4 Retail

COMPLAINT:

4. Hyd. couplers leaking oil. Thinks one is leaking by- pressure test all.

CORRECTION:

Tested breakaway couplers. Rebuilt three of the couplers that were leaking internally. Replaced the outer o-ring for all six of the couplers because they were all leaking when flowing oil from the couplers.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7330	Cap Screw	1.00	1.24	1.24	\$1.24	N
38H5002	Adapter Fitting	-1.00	9.37	9.37	(\$9.37)	N
AH146052	Hydraulic Cylinder Kit	-1.00	39.19	39.19	(\$39.19)	N
H152104	Snap Ring	-1.00	6.46	6.46	(\$6.46)	N
N34349	Snap Ring	-1.00	5.28	5.28	(\$5.28)	N
R124447	Seal	4.00	0.75	0.75	\$3.00	N
R124807	Cap	1.00	6.16	6.16	\$6.16	N
R131677	Guide	3.00	7.68	7.68	\$23.04	N
R83630	O-Ring	6.00	1.67	1.67	\$10.02	N
R95118	Bushing	-2.00	5.99	5.99	(\$11.98)	N
R95119	Seal	-4.00	14.84	14.84	(\$59.36)	N
R95250	Bushing	-2.00	5.75	5.75	(\$11.50)	N
RE186599	Seal	1.00	4.42	4.42	\$4.42	N
RE43889	Seal Kit	3.00	18.46	18.46	\$55.38	N
RE43892	Seal Kit	3.00	2.24	2.24	\$6.72	N
RE66981	Valve Spool	3.00	20.32	20.32	\$60.96	N
TY26101	BRAKE AND PARTS CLEANER-US ONLY	1.00	4.92	4.92	\$4.92	N
<hr/>						
Labor: \$307.08	Parts: \$32.72	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$339.80	

Segment 5 Retail

COMPLAINT:

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 5 Retail

5. Three point will not go down

CORRECTION:

Tested tractor to see if three point system was working properly. Found the system was working, but the cylinders were seized causing the arms not to lower without a lot of weight on them. Removed both cylinders and rebuilt them. Cleaned up the cylinder mounting pins and the pin bores. Installed cylinders and replaced the o-rings for the hose fittings. Greased pins.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH212101	Hydraulic Cylinder Kit	2.00	136.28	136.28	\$272.56	N
T77857	O-Ring	2.00	1.40	1.40	\$2.80	N
T77932	O-Ring	4.00	1.52	1.52	\$6.08	N
BAR69445	HYGARD OIL	12.00	14.39	14.39	\$172.68	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
3750	FREIGHT	1.00	2.50	2.50	\$2.50	N
Labor: \$830.00		Parts: \$454.12	OL&M: \$0.00	Misc: \$2.50	Sub-Total: \$1,286.62	

Segment 6 Retail

COMPLAINT:

6. Monitor on front column- light is out can't tell what gear he is in. Repair other lights.

CORRECTION:

Replaced three bulbs in the cornerpost display. Replaced one cab front work light, and cleaned connections for the front hood lights. Replaced one of the cab roof warning light bulbs, and got all four to operate. If the cab warning lights fail again, the roof harness will have to be replaced due to corroded sockets.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R107890	Bulb	3.00	2.28	2.28	\$6.84	N
R161288	Lamp	1.00	34.51	34.51	\$34.51	N
RE49778	Bulb	1.00	2.82	2.82	\$2.82	N
Labor: \$113.44		Parts: \$44.17	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$157.61	

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 7 Retail

COMPLAINT:

7. Steering cylinders leak.

CORRECTION:

Replaced both steering cylinders due to the fact that they were both leaking, and a cylinder rod is no longer available. The steering hoses going to the cylinders had to be replaced as well because the cylinders updated to a new style. Replaced base end cushions and rod end washers.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7783	Screw	2.00	0.81	0.81	\$1.62	N
24H1439	Washer	2.00	0.54	0.54	\$1.08	N
38H5002	Adapter Fitting	2.00	9.37	9.37	\$18.74	N
51M7041	O-RING	6.00	1.66	1.66	\$9.96	N
AHC11573	Hydraulic Cylinder Kit	1.00	72.97	72.97	\$72.97	N
N191985	Clip	2.00	2.33	2.33	\$4.66	N
P47889	O-Ring	2.00	1.34	1.34	\$2.68	N
R112954	Seal	4.00	13.73	13.73	\$54.92	N
R63937	Washer	8.00	1.70	1.70	\$13.60	N
R95118	Bushing	1.00	5.99	5.99	\$5.99	N
R95250	Bushing	2.00	5.75	5.75	\$11.50	N
RE204690	Hydraulic Hose	2.00	36.52	36.52	\$73.04	N
RE204691	Hydraulic Hose	2.00	41.10	41.10	\$82.20	N
RE287094	Hydraulic Cylinder	1.00	562.16	562.16	\$562.16	N
RE287095	Hydraulic Cylinder	1.00	562.16	562.16	\$562.16	N
T77613	O-Ring	2.00	1.29	1.29	\$2.58	N
T77857	O-Ring	2.00	1.40	1.40	\$2.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	7927	RW8400P007617	LF8400	

Segment 7 Retail							
3750	FREIGHT		1.00	5.00	5.00	\$5.00	N
Labor: \$381.82	Parts: \$1,482.66	OL&M: \$0.00	Misc: \$5.00	Sub-Total:	\$1,869.48		

Miscellaneous Charges:	
Service Accessories	\$200.00

Labor:	\$3,339.38
Parts:	\$3,332.11
OL&M:	\$0.00
Misc:	\$481.20
Sales Tax:	\$0.00
Grand Total:	\$7,152.69

Invoice Number:	229723
Invoice Date:	3/18/2016

Page:	1 of 5
-------	--------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	8056	RW8400P007617	LF8400	

Segment 1 Retail

COMPLAINT:

1. Transmission noise.

CORRECTION:

1. Tech Comments; Remove hood and shields, wash. Drain transmission to check for debris, remove trans and install on stand, remove rear cover, found planetary ring gear broken. Install cover and install reman unit. Change hyd oil and filter, replace one steering hose that had been rubbing on driveline. Replaced hydraulic sight tube. Test drive and calibrate, check for leaks, wash.

No Charge for Hauling

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7382	Cap Screw	2.00	0.90	0.90	\$1.80	N
19M7775	Screw	10.00	0.65	0.65	\$6.50	N
19M7784	Screw	2.00	0.94	0.94	\$1.88	N
38H5146	Elbow Fitting	1.00	28.69	28.69	\$28.69	N
51M7045	O-RING	1.00	2.08	2.08	\$2.08	N
AH87142	Clip	1.00	0.79	0.79	\$0.79	N
B3690R	O-Ring	2.00	3.58	3.58	\$7.16	N
H77698	Tie Band	6.00	0.28	0.28	\$1.68	N
P50631	O-Ring	1.00	3.85	3.85	\$3.85	N
R112857	O-Ring	1.00	3.15	3.15	\$3.15	N
R122886	O-Ring	1.00	3.98	3.98	\$3.98	N
R123993	Tube	1.00	19.61	19.61	\$19.61	N
R126441	Line	1.00	36.29	36.29	\$36.29	N
R151387	Nut	15.00	1.10	1.10	\$16.50	N
R44302	Tie Band	15.00	0.09	0.09	\$1.35	N
RE151986	Transmission Reman	1.00	23,667.82	23,667.82	\$23,667.82	N
RE151986-CR	CORE for:Transmission Reman	-1.00	5,000.00	5,000.00	(\$5,000.00)	N
RE174130	Oil Filter	1.00	80.55	80.55	\$80.55	N
RE174662	Hydraulic Hose	1.00	74.36	74.36	\$74.36	N

CONTINUED ON NEXT PAGE->

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	8056	RW8400P007617	LF8400	

Segment 1 Retail

RE187452	Gauge	1.00	84.96	84.96	\$84.96	N
RE21790	Elbow Fitting	2.00	7.45	7.45	\$14.90	N
T121280	Seal	1.00	12.15	12.15	\$12.15	N
T77932	O-Ring	3.00	1.55	1.55	\$4.65	N
U10289	O-Ring	1.00	3.41	3.41	\$3.41	N
U11017	O-Ring	1.00	5.40	5.40	\$5.40	N
U44496	O-Ring	1.00	2.56	2.56	\$2.56	N
<u>Miscellaneous</u> 3750	<u>Description</u> FREIGHT	<u>Quantity</u> 2.00	<u>List Price</u> 6.02	<u>Net Price</u> 6.02	<u>Extended Price</u> \$12.04	<u>Taxed Ind</u> N
Labor: \$3,617.36		Parts: \$19,086.07	OL&M: \$0.00	Misc: \$12.04	Sub-Total: \$22,715.47	

Segment 2 Retail

COMPLAINT:

2. External coolant leak at head gasket.

CORRECTION:

2. Tech Comments; Check for leaks, found none at head gasket. Tighten engine oil filter.

Labor: \$126.43	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$126.43
-----------------	---------------	--------------	--------------	---------------------

Segment 3 Retail

COMPLAINT:

3. Radiator leak.

CORRECTION:

3. Tech Comments; Drain coolant and replace radiator, refill with new coolant. Replace leaking fuel line and dry rotted fuel cooler hoses.

<u>Part Number</u> 19M7932	<u>Description</u> Cap Screw	<u>Quantity</u> 4.00	<u>List Price</u> 0.60	<u>Net Price</u> 0.60	<u>Extended Price</u> \$2.40	<u>Taxed Ind</u> N
-------------------------------	---------------------------------	-------------------------	---------------------------	--------------------------	---------------------------------	-----------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	8056	RW8400P007617	LF8400	

Segment 3 Retail

24H1136	Washer	4.00	0.33	0.33	\$1.32	N
R122267	Clamp	4.00	5.86	5.86	\$23.44	N
R151387	Nut	-2.00	1.10	1.10	(\$2.20)	N
R167296	Pad	2.00	22.43	22.43	\$44.86	N
R209720	Pin Fastener	3.00	8.97	8.97	\$26.91	N
RE159541	Radiator	1.00	1,049.65	1,049.65	\$1,049.65	N
TY22502	Hose	180.00	0.11	0.11	\$19.80	N
TY26577	Cool-Gard II Pre-mix 55 gal. (208 L)	8.00	12.56	12.56	\$100.48	N
U10289	O-Ring	1.00	3.41	3.41	\$3.41	N
BAR69445	HYGARD OIL	32.00	14.39	14.39	\$460.48	N
BTY26814	GL5 GEAR LUBE 85W140	4.00	4.75	4.75	\$19.00	N
Labor: \$435.65		Parts: \$1,749.55	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,185.20	

Segment 4 Retail

COMPLAINT:

04 Heater does not work.

CORRECTION:

4. Tech Comments; Reconnect heater hoses and replace heater shut off valve.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AT193500	Hand Operated Valve	1.00	95.91	95.91	\$95.91	N
Labor: \$64.61		Parts: \$95.91	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$160.52	

Segment 5 Retail

COMPLAINT:

05 Oil leak at L/H front wheel seal.

CORRECTION:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	8056	RW8400P007617	LF8400	

Segment 5 Retail

5. Tech Comments; Reseal LH MFWD axle and planetary, refill with new oil. Break in seals by driving under 5 mph for 15 minutes. Check for leaks.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7017	Cotter Pin	1.00	0.25	0.25	\$0.25	N
19M7790	Screw	4.00	1.45	1.45	\$5.80	N
34H355	Spring Pin	1.00	0.92	0.92	\$0.92	N
51M7043	O-RING	2.00	1.89	1.89	\$3.78	N
AR94761	Bearing Cone	1.00	20.40	20.40	\$20.40	N
H36256	O-Ring	2.00	1.66	1.66	\$3.32	N
R236289	Bushing	1.00	11.40	11.40	\$11.40	N
R87047	Ring	2.00	6.68	6.68	\$13.36	N
RE265933	Hub Kit	1.00	227.49	227.49	\$227.49	N
T77857	O-Ring	2.00	1.42	1.42	\$2.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JD 8400	8056	RW8400P007617	LF8400	

Segment 5 Retail							
3750	FREIGHT		2.00	5.00	5.00	\$10.00	N

Labor: \$584.63	Parts: \$289.56	OL&M: \$0.00	Misc: \$10.00	Sub-Total: \$884.19			
------------------------	------------------------	-------------------------	----------------------	----------------------------	--	--	--

Miscellaneous Charges:							
Service Accessories							\$200.00

Labor:	\$4,828.68
Parts:	\$21,221.09
OL&M:	\$0.00
Misc:	\$222.04
Sales Tax:	\$0.00
Grand Total:	<u>\$26,271.81</u>