

★ ★

DATE
5-16-2013

LNAME:MURDOCK TOWNSHIP

TAG:54628
YR:1994 MAKE:INTERNATIO
MODEL:TRUCK
MILEAGE:900532
MOTOR:12.7 DDEC11
VIN:RCO81876

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
8879	5" SS FLEX TUBE	4.00	28.95	0	115.80
10557	5" EXHAUST ELBOW	1.00	64.50	0	64.50
45908	5" SS TUBE	2.00	19.75	0	39.50
9624	5" BAND CLAMP	3.00	21.95	0	65.85
T500	5" MUFFLER CLAMP-U BOLT	1.00	8.20	0	8.20
235376686	VITON FUEL PUMP-12.7 DD2	1.00	278.90	0	278.90
FF992	FUEL FILTER-PRIMARY	1.00	14.60	0	14.60
FF993	FUEL FILTER-SECONDARY	1.00	15.90	0	15.90
52234-702	INJ UPPER O-RINGS	6.00	12.70	0	76.20
52346-990	DOUBLE CENTER O-RINGS	12.00	6.80	0	81.60
23511-870	INJECTOR COMPRESSION SEALS	12.00	1.85	0	22.20
L	REPAIR LABOR/EXHAUST-PULL-INJECTOR	14.00	55.00	0	770.00

NOTES

REPLACE EXHAUST PIPE FROM TURBO TO MUFFLER::
STRAIGHT PIPE AND 1ST ELBOW WERE CRACKED CAUSING EXCESSIVE HEAT TO MELT AIR LINES UNDER CAB::
THIS WAS MAKING DUMP AND PTO INOPERABLE UNTIL LINES WERE RECONNECTED TO UNLOAD::
THEN THE DETROIT ENGINE RUNS OUT OF POWER WHEN PULLING LOAD
HAD TO PULL TRUCK HOME FROM FURLEY:
REPLACED FUEL PUMP AND FILTERS- WERE GETTING AIR BUBBLES IN PRIMARY FUEL LINE.
REPLACE INJECTOR O-RINGS: THEN IT WILL NOW RUN TO 1400 RPM BEFORE FALLING ON POWER:
WE WERE GETTING OVER OUR HEAD NOW ON WHAT NEXT TO DO
TOOK TRUCK TO NORMAN SMITH REPAIR- TRUCK IS AT HIS SHOP RIGHT NOW:

REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Signature X _____

Parts	783.25
Labor	770.00
Subtotal	1553.25
retailers exempt	0.00
Shop Fee	2.00
retailers exempt	0.00

Total 1555.25

Check 1555.25

Invoice #
686

DATE
10-18-2012

LNAME:MURDOCK TOWNSHIP

TAG:54628
YR:1994 MAKE:INTERNATIO
MODEL:TRUCK
MILEAGE:900532
MOTOR:12.7 DDEC11
VIN:RCO81876

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
R23537686	FUEL PUMP ASSEMBLY	1.00	384.75	0	384.75
L	REPAIR LABOR/SERVICE CALL	1.00	50.00	0	50.00
L	REPAIR LABOR	3.00	50.00	0	150.00

NOTES

TRUCK WON'T START:
DIAGNOSIS- FUEL PUMP FAILURE- 9/28/12
REPLACE FUEL PUMP ASSEMBLY: 10/1/12

REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Signature X _____

Parts	384.75
Labor	200.00
Subtotal	584.75
retailers exempt	0.00
Shop Fee	2.00
retailers exempt	0.00

Total 586.75

Check 586.75

Invoice #
2109

DATE
9-15-2015

LNAME:MURDOCK TOWNSHIP

TAG:54628
2 YR:1994 MAKE:INTERNATIO
MODEL:TRUCK
MILEAGE:900532
MOTOR:12.7 DDEC11
VIN:RCO81876

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
110-555JHO	ALTERNATOR ASSY	1.00	189.95	0	189.95
FPA-5603	SERPENTINE BELT ALT	1.00	56.45	0	56.45

NOTES

ALTERNATOR ASSY AND SERPENTINE BELT::
ALTERNATOR DEFECTIVE- BELT WORN OUT..
RANDALL REMOVED // GARY INSTALLED ALTERNATOR.

REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Signature X _____

Parts	246.40
Labor	0.00
Subtotal	246.40
retailers exempt	0.00
Shop Fee	2.00
retailers exempt	0.00

Total 248.40

Check 248.40

Invoice #
1289

DATE
1-15-2014

LNAME:MURDOCK TOWNSHIP

TAG:54628
02 YR:1994 MAKE:INTERNATIO
MODEL:TRUCK
MILEAGE:900532
01 MOTOR:12.7 DDEC11
VIN:RCO81876

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
ANTZ	ANTIFREEZE COOLANT	5.00	9.50	0	47.50
BAT	AC-DELCO 31-901CT TOP POST BATTERIES- (18 MO RPLC)	4.00	135.95	0	543.80
L	REPAIR LABOR	1.00	55.00	0	55.00

NOTES
ANTIFREEZE COOLANT FOR WATER PUMP REPLACEMENT
SHOP USE
REPLACEMENT BATTERIES IN TRUCK::

REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Signature X _____

Parts	543.80
Labor	102.50
Subtotal	646.30
retailers exempt	0.00
Shop Fee	2.00
retailers exempt	0.00

Total	648.30
Check	648.30

Invoice #
686

DATE
10-18-2012

LNAME:MURDOCK TOWNSHIP

TAG:54628
0 YR:1994 MAKE:INTERNATIO
MODEL:TRUCK
MILEAGE:900532
MOTOR:12.7 DDEC11
VIN:RCO81876

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
R23537686	FUEL PUMP ASSEMBLY	1.00	384.75	0	384.75
L	REPAIR LABOR/SERVICE CALL	1.00	50.00	0	50.00
L	REPAIR LABOR	3.00	50.00	0	150.00

NOTES

TRUCK WON'T START::
DIAGNOSIS- FUEL PUMP FAILURE- 9/28/12
REPLACE FUEL PUMP ASSEMBLY: 10/1/12

REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****REPRINT*****

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Signature X _____

Parts	384.75
Labor	200.00
Subtotal	584.75
retailers exempt	0.00
Shop Fee	2.00
retailers exempt	0.00

Total 586.75

Check 586.75