

Invoice

DB 9285

Date	Invoice #
8/15/2015	2298

Bill To
Joe Briney

Terms	Project
Net 15th	

Item	Qty	Description	Rate	Amount
Labor		4430 2231 hrs. Install test equipment. Diagnose hydraulic system- lost charge pressure. R&R clutch valve: disassemble and inspect; found bad valve and spring. Repair & install. R&R regulator valve disassemble and inspect: Check flow on charge pump; found bad quad pack. Do extensive research to find replacement parts. R&R hood and split tractor at engine. Remove transmission clutch housing and replace quad pack. Re-assemble tractor and charge a/c. Test run tractor.		2,470.00
Supplies		Service consumables/accessories used in testing; clean-up; and/or assembly.		
Parts	6	global antifreeze		
Parts	6	134A		
Supplies		oil charge		
Supplies	15	hydraulic oil		
Supplies	5	brake cleaner		
Parts		200419 quad clutch pack assembly and freight.		
Parts		50335 gasket		
Parts		26919 packing		
Parts		60038 packing		
Parts		94286 gasket		
Parts	10	26286 O-ring		
Parts		15646 O-ring		
Parts		57247 O-ring		
Parts		57637 seal		
Parts		57636 packing		
Parts	2	33259 O-ring		
Parts		94286 gasket		
			Total	

DB 9285

Invoice

Date	Invoice #
4/17/2012	1260

Bill To
Joe Briney

Terms	Project

Item	Qty	Description	Rate	Amount
Labor		4430 JD Tractor 1953hrs Hydraulic system will not build pressure. Perform hydraulic system tests; replace main hydraulic pump; makes pressure now but still does not perform properly. Remove valve body and inspect; install filter, relief valve in correctly. Perform more hydraulic tests. Return leak to sump. Remove rock shaft housing; replace cover and O-ring; install rock shaft housing and test then. Plugged screen. Clean screen and install new oil. Had to clean screen and filter several times.		1,400.00
Parts		94660 New piston pump		
Parts		55079 cover		
Parts		section hose assembly		
Parts		8914 spring		
Parts		10033 gasket		
Parts		75603 filter		
Parts		7433 packing		
Parts		fittings		
Parts		9411 coupler		
Parts		5167 coupler		
Parts		56065 line		
Parts		packings, O-rings, bolts		
Supplies	5	brake cleaner		
Supplies	22	gallon hydraulic oil		
		Sales Tax Computed in Quicken		
			Total	\$3,706.31

Invoice

Date	Invoice #
2/20/2012	1224

Bill To
Joe Briney 1124 290th Road Beloit, KS 67420

Terms	Project

Item	Qty	Description	Rate	Amount
Labor		4430 ser#007426R @1941hrs. Service call: tow tractor to shop. Split tractor remove engine and disassemble. Clean and transfer all external parts to new engine. Disassemble, clean, and adjust clutch. Install engine on frame and reassemble tractor. Install new turbo; fill with fluids, and prime oil pump. Prime fuel system and test run engine. Set idle to spec. Disassemble dash and replace engine oil pressure gage. Drain and flush hydraulic system and install new oil and filter.	2,650.00	2,650.00
Parts		404T reman long block		
Supplies	20	gal. hydraulic oil		
Supplies		break-in oil		
Supplies	4	134A		
Supplies		134A oil		
Supplies		pipe adaptor		
Supplies	4.5	antifreeze		
Parts		3643 engine oil filter		
Parts		5603 hydraulic oil filter		
Parts		6608 new turbo charger		
Supplies	5	brake cleaner		
Supplies		sealant		
Supplies		wire and connectors		
Supplies		studs and nuts		
Parts		5303 bell housing gasket		
Parts		1071 crank driver		
Parts	3	2435 set screw		
Parts		4733 packing		
Parts		8740 dipstick		
			Total	

Invoice

Date	Invoice #
2/20/2012	1224

Bill To
Joe Briney 1124 290th Road Beloit, KS 67420

Terms	Project

[illegible]