

QUAN.	PART NO.	NAME OF PART	PRICE	CUSTOMER INFORMATION			
1	30442	Fuel Filter		DATE	CUSTOMER'S ORDER NO.	WHEN PROMISED	PHONE
1	57602	Oil Filter		2-24-16			528-7648
1	32472	Fuel Filter		YEAR - MAKE - MODEL	SERIAL NO.		
4	011	RTS 15W40		1997 Freight Linco-FL70	MOTOR NO.		
1	173691	Fan Drive		LICENSE NO.	ODOMETER	WRITTEN BY	
1	3928826	Pump Bracket					
1	4023580	Top Bracket					
1	3030	Chamber					
6	927320	Nozzles		Charged oil and greased unit (Did not grease Pump or Bed)			
6	927330	Nozzle Gaskets					
1	24412001B	Fan Pump					
			9112.89	Found Right Rear Brake Chamber Bad and Replaced it			
				Fan drive was Locked up and 1/2 shd off about went through Radiator Replaced Fan drive			
				Checked Hard starting Problem Inj pump was Bad and nozzles were poor			
				Repaired inj pump and injectors			
				ACCESSORIES			
				LABOR ONLY			
				HOURS:		14.0	
				RATE:		40.00	
				PARTS			
				ACCESSORIES			
				SUBLET REPAIRS			
				TOTAL ACCESSORIES:		Freight 69.00	
				AUTHORIZED BY:		TAX: 26.90	
ESTIMATE AMOUNT - PARTS & LABOR				5053.79			

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND HERBY GRANT YOU A PRICE ESTIMATE FOR THE REPAIR WORK.