Invoice

Date	Invoice #
6/20/2017	

Bill To	
Brandon Murphy 1307 Main St. Anita, IA 50020	

Terms

Due Upon Receipt

Quantity	Description	Rate	Amount
	2004 International 8600 ISM Vin # 1HSHXAHRX5J051926		
	Odometer: 581359		
	Condition: Check Out EGR		
	Correction: Fix EGR Issues As Needed - Cooler & Valve Bad - Fix Exhaust Leak -		
	Dig Out 3 Broken Bolts Out Of The Head & Replace Front Section Of Exhaust		
	Manifold & Gaskets As Needed - Took Valve Cover Off & Fix Bad Oil Leak As		
	Needed		
6	3328948 Gasket, Exh		
9	4965698 Screw, Hex		
3	3103086 Screw, Capt		
4	0.00701.0100		
4	3818824 Nut, Reg		
1	3755843 Gasket, Tur		
1	3899343 Gasket, Tur		
1	3627695 Seal, ORing		
1	3883220 Gasket, Roc		
1	3102466 Manifold		
1	ECM Tune		
2	1/2/20/20/20/20/20/20/20/20/20/20/20/20/2		
1	Air/ Air Clamp		3
4	in. 1 1/8 Straight Hose		
1	Tube Lock Ti		
2			
	3/8" Gr 5 Nut		
3	1.00		
2	1 3/8" Freeze Plug		
I	Ultra Black Silicone		
	11mm Oring Plugs		
16	Diesel / Heavy Duty Labor		

Total

Invoice

Date	Invoice #
6/20/2017	

Bill To	
Brandon Murphy 1307 Main St. Anita, IA 50020	

Terms

Due Upon Receipt

Quantity	Description	Rate	Amount
	Condition: Check Over & Change Oil		
	Correction: Changed Engine Oil & Oil Filter, Check All Boxes & Lube, Added 1		
	Gallon Antifreeze, Changed Air Filter As Needed, Clean Off Engine & Fix		
44	Qt 15W40 Northland Engine Oil		
1	P550757 Fuel Filter		
1	P550949 Lube Filter		1
1	Gallon Antifreeze		
1	Tube Syn Grease		
1	P613336 Air Filter		
1	Red Thunder Clean		0
1	Semi Oil Change/Service Labor		
	Condition: DA Brakes		A .
	Correction: Remove Drive Axle Brakes & Install 4 New 4515 Brake Shoe Sets As		1
	Needed * RETORQUE LUG NUTS AFTER 50-100 MILES *		
4	4515 Brake Shoe Set		
4	Diesel / Heavy Duty Labor		
	Condition: Batteries		
	Correction: Remove Batteries Install 4 New 7236 Batteries Clean & Treat		
4	[] [] [[] [] [] [] [] [] [] [
1	Diesel / Heavy Duty Labor		
	Condition: Clutch Adjustment		İ
	Correction: Adjust Clutch & Linkage To Spec.		
0.5	Diesel / Heavy Duty Labor		
	Sales Tax		
	Section Control of the Control of th		
			4
			1
			1

Total